#### 31st -OCT-2021

PACKAGE-II	STATUS AS ON 31/10/2021
Up to Last Month	Kitchen sink fixing work in 50 flats completed. (Total 56)
Block D01	• False ceiling tile fixing work in toilets completed from 6 <sup>th</sup> to 14 <sup>th</sup> floor.
	Vertical expansion joint sheet fixing work completed.
	Balcony drain grating fixing work completed.
	• 2 <sup>nd</sup> coat External painting work in open to sky shaft area completed.
	• Internal fire alarm work is in progress.
	Common area light fixing work is in progress.
	CCTV camera fixing in progress in stilt floor.
Current Month	Kitchen area false ceiling work completed.
Activity	• Vertical expansion joint sheet painting work completed.
	Columns skirting at stilt floor completed.
	Lift testing work in progress.
	Common area light fixing work is in progress.
	CCTV camera fixing completed in stilt floor.
	Toilets exhaust fans fixing completed.
	Fire shaft glass fixing completed.
	• Internal fire shaft fittings fixing work completed up to 4 <sup>th</sup> floor.
	Terrace fire pump fixing in progress.
Up to Last Month	Kitchen sink fixing work in 56 flats completed.
Block D02	• False ceiling tiles fixing work completed up to 11 <sup>th</sup> floor.
	Vertical expansion joint aluminum sheet fixing work completed.
	Balcony drain grating fixing work completed.
<b>Current Month</b>	• False ceiling tiles fixing work completed from 12 <sup>th</sup> to 14 <sup>th</sup> floor.
Activity	Kitchen area false ceiling work completed.
	• 2 <sup>nd</sup> coat Painting in open to sky area is completed.
	Stilt columns skirting work in progress.
	Stilt floor guard room fix glass fixing work completed.
	Toilets exhaust fans fixing completed.
	Lift testing work is in progress.
	Fire shaft glass fixing completed.
	Terrace fire pump fixing in progress.
	• Internal fire shaft fittings fixing work completed up to 4th floor.
Up to Last Month	Kitchen sink fixing work in 56 flats completed.
Block D03	• False ceiling tiles fixing work completed up to 11 <sup>th</sup> floor.
	Vertical expansion joint aluminum sheet fixing work completed.
	Balcony drain grating fixing work completed.
	• Chinaware fixing work competed from 8 <sup>th</sup> floor to 10 <sup>th</sup> floor.





<b>Current Month</b>	• False ceiling tiles fixing work completed from 12 <sup>th</sup> to 14 <sup>th</sup> floor.
Activity	• Chinaware fixing work competed from 9 <sup>th</sup> floor to 14 <sup>th</sup> floor.
	Stilt floor guard room fix glass fixing work completed.
	• Stilt columns skirting work in progress.
	• Lift testing work is in progress.
	• Terrace fire pump fixing in progress.
	Fire shaft glass fixing completed.
Up to Last Month	Balance Mumty & Machine Room external painting work completed.
Block D04	• Kitchen sink fixing work in 56 flats completed.
	Balcony drain grating fixing work completed.
<b>Current Month</b>	Toilets false ceiling work completed.
Activity	• Chinaware fixing work completed up to 11 <sup>th</sup> floor.
	• Stilt floor guard room fix glass fixing work completed.
	Fire shaft glass fixing completed.
Up to Last Month	• External painting works 90% completed.
Block D05	• Kitchen sink fixing work in 56 flats completed.
	Basement floor tiling in corridor completed.
	Mumty & machine Room external painting work completed.
	Over head water tank tiling work completed.
Current Month	• Terrace Brick coba waterproofing work completed.
Activity	Balcony drain grating work completed.
	• Stilt floor granite flooring work completed.
	• Stilt floor Guard room fix glass fixing work completed.
	• Fire shaft glass fixing completed.
TI. A. T. A. M. A.	
Up to Last Month Block D06	Over head water tank wall casted.
DIOCK DUO	Machine Room shuttering work is in progress.  The shade of the sh
	• Terrace projection slab 35% casted. (Total 60%).
	Basement Brick work completed.  Noticed Classic accordance and the description of the second se
	• Vertical CI piping work completed from 7 <sup>th</sup> to 12 <sup>th</sup> floor.
	• Cpvc piping work completed from 12 <sup>th</sup> to 13 <sup>th</sup> floor.
	• Wings-3 & 4 external plaster work 30% completed.
	• Internal wall putty work completed up to 6 <sup>th</sup> floor.





CGE	WHO – GREATER NOIDA PROJECT
CGE  Current Month Activity	<ul> <li>Machine Room and overhead tank top slab casted.</li> <li>Terrace projection slab 35% casted. (Total 95%).</li> <li>Machine Room stub columns casted.</li> <li>POP cornice work completed.</li> <li>Vertical CI piping work completed from 13th to 14th floor.</li> <li>Cpvc piping work completed at 14th floor.</li> <li>Toilets water proofing completed up to 3rd floor.</li> <li>Kitchen counter fixing work completed up to 8th floor.</li> <li>Kitchen wall tiling work completed up to 2nd floor.</li> <li>External plaster work 50% completed.</li> <li>External putty work 15% completed.</li> </ul>
	• Internal wall putty work completed from 7th floor to 11th floor.
Up to Last Month Non-Tower	<ul> <li>Balance Road VDF completed front of block D-02.</li> <li>Soil filling work in Road area is in progress near boundary wall.</li> <li>Basket ball &amp; Tennis court soil compaction work is in progress.</li> </ul>
	• Front portion of blocks D-02, D-3, D-04 & D-05 development work is in
	progress.  Soil drassing properation work and Plantation work in progress
	<ul> <li>Soil dressing, preparation work and Plantation work in progress.</li> <li>Pergola 3nos errection &amp; painting work completed. (Total 100%</li> </ul>
	completed).
	<ul> <li>Basement firefighting work is in progress.</li> </ul>
	<ul> <li>CCTV camera fixing in progress.</li> </ul>
<b>Current Month</b>	Road VDF completed from Tennis court to block D-05 near
Activity	boundary wall.
	Soil filling work in Road area is in progress near boundary wall.
	• Tennis court base PCC work completed.
	• Front portion of blocks D-02, D-3, D-04 & D-05 development work is
	in progress.
	<ul> <li>Soil dressing, preparation work and Plantation work in progress.</li> <li>Water body piping work completed.</li> </ul>
	<ul> <li>Water body piping work completed.</li> <li>Green are Guiniting work is in progress.</li> </ul>
	<ul> <li>Drain plaster work is in progress.</li> </ul>
	Drain covers laying work front of blocks from D-01 to D-02
	completed.
	Basement sprinklers fixing work is in progress.
	Basement wiring is in progress.
	CCTV camera fixing in progress.
Up to Last Month	Boundary wall Putty work completed.
Retaining Wall &	Boundary wall Railing painting work completed.
Boundary wall Current Month	
Activity	
11011111	l l





#### PHOTOGRAPHS OF PACKAGE-II on 31st OCT -2021


DEVELOPMENT WORK IS IN PROGRESS FRONT OF BLOCK D-04 & D05.







# EXTERNAL PLASTER WORK 50% COMPLETED. OF BOCK D-06. EXTERNAL PUTTY WORK IS IN PROGRESS.







#### **CENTER PARK DEVELOPMENT WORK IN PROGRESS**







## GREEN AREA DEVELOPMENT WORK FRONT OF BLOCKS D-02, D-3 D-04 IS IN PROGRESS.







] <del></del>	CGEWHO – GREATER NOIDA PROJECT
PACKAGE-III	STATUS AS ON 31/10/2021
Up to Last Month Block C01	<ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>100% Internal primer &amp;1<sup>st</sup> coat paint work completed.</li> <li>70% External First coat Paint work completed.</li> <li>Lift ready for testing.</li> </ul>
Current Month Activity	<ul> <li>Chinaware fitting completed.</li> <li>Electrical Rising main completed.</li> <li>Exhaust fan of toilet and kitchen is completed.</li> <li>Main door teak polish is on progress.</li> </ul>
Up to Last Month Block C05	<ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI&amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>100%: Internal flat primer &amp; 1st coat paint work completed.</li> <li>90% External First coat Paint work completed.</li> <li>100% Common area First coat paint work completed.</li> </ul>
Current Month Activity	<ul> <li>Electrical rising main work completed.</li> <li>100% Chinaware fitting work completed.</li> <li>Stilt corridor aluminium frame and glass completed.</li> <li>One lift preliminary testing completed.</li> </ul>
Up to Last Month Block C-06	<ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> </ul>
	<ul> <li>100% Internal 1<sup>st</sup> coat paint including common area work completed.</li> <li>90% External First coat Paint work completed.</li> </ul>





	CGEWIIO - GREATER NOIDAT ROJECT
Current Month Activity  Up to Last Month Block C07	<ul> <li>Electrical rising main work completed.</li> <li>100% Chinaware fitting work completed.</li> <li>Stilt corridor aluminium frame and glass completed.</li> <li>One lift preliminary testing completed.</li> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI&amp;CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>100%: Internal 1st coat paint including common area work completed.</li> <li>95% External First coat Paint work completed.</li> </ul>
Current Month Activity  Up to Last Month Block C08	<ul> <li>Electrical rising main work completed.</li> <li>100% Chinaware fitting work completed.</li> <li>Exhaust fan of toilet and kitchen is completed.</li> <li>Stilt corridor aluminium frame and glass completed.</li> <li>One preliminary lift testing is in progress.</li> <li>100% RCC work completed.</li> <li>100% CI &amp; CPVC work completed.</li> <li>100% Flat POP cornice &amp; 1<sup>st</sup> coat putty work completed.</li> <li>100% Floor tile and wall tile completed.</li> <li>100% External 1<sup>st</sup> coat wall putty work completed.</li> <li>100% M.S staircase railing &amp; marble completed.</li> <li>100% S.S balcony railing work completed.</li> <li>Terrace brick coba 80% completed.</li> </ul>
Current Month Activity	<ul> <li>Level 01 to 08: Lift stone cladding work completed.</li> <li>Level 09: Lift stone cladding work is in progress.</li> <li>Remaining 20% Terrace brick coba work completed.</li> <li>Aluminum door &amp; window making 100% and fixing 70% completed.</li> <li>Aluminum louvers making 100% and fixing 50% completed and remaining is in progress.</li> <li>Level 01 to 12: Internal door fixing completed.</li> <li>Feature wall B/W is in progress.</li> <li>Lift installation is in progress.</li> </ul>





	CGEWHO – GREATER NOIDA PROJECT
	• 100% RCC work completed.
<b>Up to Last Month</b>	<ul> <li>Level 01 to 06: Water proofing work completed.</li> </ul>
	Level 09: External CI work completed.
Block C09	• Level 12: Internal 1 <sup>st</sup> coat putty completed.
	• 100% External plaster completed.
	Level 14: Internal plumbing (cPVC) completed.
	Level 06: External CI work completed.
	• 100% M.S staircase railing work completed.
	Terrace brick coba 80% completed.
	• Level 13: Internal 1 <sup>st</sup> coat putty is in progress.
<b>Current Month</b>	• Level 07 to 11: Water proofing work completed.
Activity	• Level 01 to 08: Toilet Wall tile fixing work completed.
	• Level 10: External CI work is in progress.
	• Level 01 to 12: S.S railing work completed.
	<ul> <li>Remaining 20% Terrace brick coba work is in progress.</li> </ul>
	Lift installation work is in progress.
	• 100% RCC work completed.
Up To Last	• 100% Tile work CI, GI & CPVC work completed.
Month	• 100% M.S staircase & S.S balcony Railing work completed.
	• 100% Aluminum Door window & Louvers fixing completed.
Block C10	• 100% Door shutter (Teak) & staircase marble completed.
	• 100% Internal POP cornice & Wall putty completed.
	Level 01 to 05: Electrical wiring completed
	85% External paint completed.
	Aluminium glass fixing 90% completed.
Comment Manth	T 1014 07 T 4 14ct 4 D 14ct
Current Month	• Level 01 to 07: Internal 1st coat Painting work completed.
Activity	• 10% External paint work completed.
	• Lift installation work is on progress.
	• Level 06&07: Electrical wiring completed.
	Stilt granite flooring & feature wall completed.
	• 100% RCC work completed.
	• 100% Tile work CI, GI & CPVC work completed.
<b>Up to Last Month</b>	• 100% M.S staircase & S.S balcony Railing work completed.
DI1- C11	• 100% Aluminum Door window & Louvers fixing completed.
Block C11	• 100% Door shutter & staircase marble completed.
	• 100% Flat Electrical wiring completed.
	• 100% Internal POP cornice & Wall putty completed.
	<ul> <li>Level 01 to 04: Electrical switch socket completed.</li> </ul>
	• 75% External First coat Paint work completed.





# Current Month Activity • 100%Stilt granite flooring & feature wall completed. • Lift earthing work completed. • Lift ready for testing. • Level 01 to 12: Electrical switch socket completed. • Internal switch socket 100% completed.

Up to Last Month Block C12	<ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% flat internal electrical wiring completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>85% Internal primer &amp; 1<sup>St</sup> coat paint work completed.</li> <li>Lift ready for testing.</li> </ul>
	80% External painting work completed.
Current Month Activity	<ul> <li>Level 01 to 12: 1<sup>St</sup> coat painting completed.</li> <li>Level 01 to 12: Internal Electrical switches completed.</li> <li>Level 01 to 11: Chinaware fixing completed.</li> <li>Stilt granite flooring work completed.</li> <li>10% External painting work completed</li> </ul>
Up to last month UG Tank	U.G. Tank Putty work completed.
Current Month Activity	• U.G. Tank wiring is on progress.
Up to last month  Non-Tower	<ul> <li>Basement putty&amp; 1<sup>st</sup> coat paint 50% completed.</li> <li>Basement plumbing Block C-01,05,06,07,11&amp;12 completed.</li> <li>Basement firefighting fire hydrant, Sprinkler and curtain line 75% completed.</li> <li>Basement VDC flooring 94% completed.</li> <li>External development Sewer &amp; rainwater harvesting work 100% completed.</li> <li>Non tower slab APP membrane water proofing (17720/20700) sqm completed.</li> <li>Green area Guniting work (3200/6000) sqm completed.</li> <li>Road VDF 490/931 RMT completed.</li> </ul>





#### Current Month Activity

- Basement firefighting fire hydrant, Sprinkler and curtain line work is on progress.
- Chequered tile Kerb stone work in progress.
- Drain brick work in progress.
- IGL brick work in progress.
- Planter & Drain brick wall Granite fixing work in progress.
- HDPE pipe work garden hydrant work in progress.
- External firefighting line laying work in progress.
- Basement fire fighting work in progress.
- Road VDF 250 RMT complete
- Non tower slab APP membrane water proofing 700 sqm complete.
- Basement VDC flooring 1000 Sqm complete

#### PHOTOGRAPHS OF PACKAGE-III on 31 -OCT -2021

#### **BIRD EYE VIEW OF PROJECT**







#### BLOCK C05, C6 & C-7 EXTERNAL PAINTING WORK COMPLETED.







#### BLOCK C11, C12&C-01 EXTERNAL PAINTING WORK COMPLETED.







#### BLOCK C08,09&10 EXTERNAL PAINTING WORK IS IN PROGRESS.







#### LANDSCAPING WORK IS ON PROGRESS







DA CIVA CIE IV	CELATIVIC A C ON 24 /4 0 /2024
PACKAGE-IV	STATUS AS ON 31/10/2021
Up to Last Month	Second Lift testing work in progress.
Block A01	Twelfth floor sub main work in progress.
	• Fire door glass fixing work in progress.
	• Expansion joint sheet fixing work in progress.
	Lift machine room light point work completed.
	Numbering of block completed.
Current Month	Second Lift testing work in progress.
Activity	• Twelfth floor sub main work in progress.
	• Fire door glass fixing work in progress.
	• Fire staircase door fixing work in progress.
	Expansion joint sheet fixing work completed.
Up to Last Month	Second Lift testing work in progress.
Block B04	Expansion joint Aluminium sheet covering work completed.
	Fire door glass fixing work in progress.
	Fifth floor ceiling final coat of paint work completed.
	Fire pump installation work in progress.
	Numbering of block completed.
Current Month	Second Lift testing work in progress.
Activity	Fire door glass fixing work in progress.
	Fire staircase door fixing work in progress.
	Fifth floor ceiling final coat of paint work completed.
	Fire pump installation work completed.
<b>Up to Last Month</b>	Second lift Testing work in progress.
Block B05	Expansion joint Aluminium sheet covering work in progress.
	98% External Paint 1 <sup>st</sup> coat work completed.
	Tenth floor sub main work completed.
	Twelfth floor ceiling final coat of paint work completed.
	First floor wall final coat of paint work completed.
	Fire door glass fixing work in progress.
	Fire pump installation work completed.
	Electrical testing work in progress.
	Numbering of block completed.
Current Month	Second lift Testing work in progress.
Activity	• Expansion joint Aluminium sheet covering work completed.
	98%External Paint 1 <sup>st</sup> coat work completed.
	Thirteen floor sub main work completed.
	Thirteen floor ceiling final coat of paint work completed.
	Fire door glass fixing work in progress.
	Fire staircase door fixing work in progress.
<b>Up to Last Month</b>	98% Mumty Machine room external paint work completed.
Block C-16	Meter board fixing work in progress.
	Tenth floor Sub main work completed.
	Twelfth floor ceiling final coat of paint work in progress.
	Numbering of block completed.





	CGEWHO – GREATER NOIDA PROJECT
<b>Current Month</b>	• 98% Mumty Machine room external paint work completed.
Activity	Meter board fixing work in progress.
	Twelfth floor Sub main work completed.
	Twelfth floor ceiling final coat of paint work completed.
	• Twelfth floor fixing of Grating in balcony and bath room work in progress.
<b>Up to Last Month</b>	98% Mumty Machine room external paint work in progress.
Block C-17	Meter board fixing work in progress.
	Expansion joint Aluminum sheet covering work in progress.
	• Fifth floor fixing of Grating in balcony and bath room work in progress.
	Electrical testing work in progress.
	Numbering of block completed.
<b>Current Month</b>	• 98% Mumty Machine room external paint work in progress.
Activity	Meter board fixing work in progress.
	• Expansion joint Aluminum sheet covering work completed.
	• Twelfth floor fixing of Grating in balcony and bath room work in progress.
	Electrical testing work in progress.
	Numbering of block completed.
<b>Up to Last Month</b>	Expansion joint Aluminum sheet covering work in progress.
Block C-02	Aluminium Door and Windows Silicon filling work in progress.
	Numbering of block completed.
CAMAh	
Current Month	• Expansion joint Aluminum sheet covering work completed.
Activity	Aluminium Door and Windows Silicon filling work in progress.  Sub-main models and leading to the sub-main models and the sub-main models.
	Sub main work completed.  Bising main work completed.
II. 4. I and Mandle	Rising main work completed.
Up to Last Month Block C-03	First coat External Painting work completed.
DIOCK C-03	• Expansion joint Aluminium sheet covering work in progress.
	Expansion joint Aluminum sheet covering work in progress.  Electrical testing and deing appearance.
	Electrical testing work in progress.  Number in a of block completed.
Commont Month	Numbering of block completed.
Current Month Activity	• Expansion joint Aluminium sheet covering work completed.
	Stilt floor skirting work in progress.
Up to Last Month Block C-04	First coat External Painting work completed.
DIUCK C-U4	• Expansion joint Aluminium sheet covering work in progress.
	Aluminium Door and Windows Silicon filling work in progress.
0 (37 (3	Numbering of block completed.
Current Month	• Expansion joint Aluminium sheet covering work completed.
Activity	Aluminium Door and Windows Silicon filling work in progress.
	• Stilt floor skirting work in progress.





	00= ,, == 0
<b>Up to Last Month</b>	<ul> <li>Ramp No-3- 100% slab casting work completed.</li> </ul>
NTA	<ul> <li>Ramp No-3- brick work and plaster work in progress.</li> </ul>
	<ul> <li>Darin covering work in progress.</li> </ul>
	<ul> <li>Water Body stone fixing work in progress.</li> </ul>
	Green area development work in progress.
	Green Area Kerb stone fixing work completed.
	<ul> <li>Parking area Kerb stone fixing work completed.</li> </ul>
	<ul> <li>Basket ball &amp; Tennis court work in progress.</li> </ul>
	<ul> <li>IGL Drain water proofing plaster work in progress.</li> </ul>
	<ul> <li>Basement Fire Fighting main line connection work in progress.</li> </ul>
	Basement painting work in progress.
	Basement light fixing work in progress.
<b>Current Month</b>	<ul> <li>Ramp No-3- brick work and plaster work completed.</li> </ul>
Activity	Darin covering work in progress.
	Water Body stone fixing work in progress.
	• Green area development work in progress.
	Basket ball & Tennis court work in progress.
	<ul> <li>IGL Drain water proofing plaster work in progress.</li> </ul>
	<ul> <li>Basement Fire Fighting main line connection work in progress.</li> </ul>
	• Sprinkler fixing work in progress.
	Basement painting work in progress.
	Basement light fixing work in progress.





#### PHOTOGRAPHS OF PACKAGE-IV on 31st OCT 2021

#### **BIRD EYE VIEW OF PROJECT**








# MONTHLY PROGRESS REPORT CGEWHO – GREATER NOIDA PROJECT CENTRAL PARK DEVELOPMENT IS IN PROGRESS.








#### MONTHLY PROGRESS REPORT CGEWHO – GREATER NOIDA PROJECT EXTERNAL ROAD WORK COMPLETED.







#### MONTHLY PROGRESS REPORT CGEWHO – GREATER NOIDA PROJECT ROAD GREEN AREA WORK IN PROGRESS.







PACKAGE-V	STATUS AS ON 31/10/2021
<b>Up to Last Month</b>	
Block B01	<ul> <li>Balance 5% Toilet false ceiling tile fixing work completed. (Total 100%).</li> <li>Balance 10% Floor drain gratings in Toilets fixing work completed. (Total 100%).</li> </ul>
	<ul> <li>Expansion joint covering with Aluminum sheet is completed.</li> <li>Tower bolt fixing work 80% completed.</li> <li>Main door polish work is in progress.</li> <li>Internal 2<sup>nd</sup> coat ceiling painting work is in progress.</li> <li>2<sup>nd</sup> lift testing work completed.</li> <li>WC &amp; washbasin fixing work completed.</li> <li>Internal fire alarm fixing work 90% completed.</li> <li>Terrace Fire pump fixing work completed.</li> <li>CCTV camera fixing in progress.</li> </ul>
Current Activity	<ul> <li>Expansion joint covering with Aluminum sheet painting work completed.</li> <li>Stilt floor columns skirting work is in progress.</li> <li>Balance 20% Tower bolt fixing work completed. (Total 100%).</li> <li>Main door polish 1<sup>st</sup> coat work completed.</li> <li>Internal 2<sup>nd</sup> coat ceiling painting work is completed.</li> <li>Fire door shutters fixing work completed.</li> <li>Internal fire shaft fittings fixing work completed up to 4<sup>th</sup> floor.</li> <li>CCTV camera fixing work completed at stilt floor.</li> </ul>
Up to Last Month	<ul> <li>Balance 5% Toilet false ceiling tile fixing work completed. (Total 100%).</li> <li>Balance 15% Floor drain gratings in Toilets fixing work completed. (Total</li> </ul>
Block B02	100%).
	Tower bolt fixing work 80% completed.
	Main door polish work is completed.
	<ul> <li>Internal ceiling 2<sup>nd</sup> coat painting work is in progress.</li> <li>WC &amp; washbasin fixing work completed.</li> </ul>
	<ul> <li>2<sup>nd</sup> lift testing work completed.</li> </ul>
	<ul> <li>Internal fire alarm fixing work in progress.</li> </ul>
	Terrace Fire pump fixing work completed.
Current Activity	<ul> <li>Balance 20% Tower bolt fixing work completed. (Total 100%).</li> <li>Internal ceiling 2<sup>nd</sup> coat painting work is completed.</li> <li>Internal fire alarm fixing work 80% completed.</li> <li>Internal fire shaft fittings fixing work completed up to 4<sup>th</sup> floor.</li> </ul>





1	CGEWHO – GREATER NOIDAT ROJECT
Up to Last Month	<ul> <li>Tower bolt fixing work completed up to 10<sup>th</sup> floor.</li> <li>Both Lifts testing work is completed.</li> </ul>
Block B03	<ul> <li>Internal 2<sup>nd</sup> coat ceiling painting work is in progress.</li> </ul>
Block Bos	
	• Expansion joint covering with Aluminum sheet is completed.
	WC & wash basin fixing work 80% completed.  The state of the stat
	Terrace fire pump fixing work completed.
<b>Current Activity</b>	
	• Internal 2 <sup>nd</sup> coat ceiling painting work is completed.
	Expansion joint covering sheet painting work completed.
	• Internal fire shaft fittings fixing work completed up to 4th floor.
	• Internal fire alarm fixing work 80% completed.
	WC & washbasin fixing work completed.
Up to Last Month	<ul> <li>Balcony &amp; Toilet floor drain grating fixing work is in progress.</li> </ul>
ep to East Worth	<ul> <li>Fire shaft glass fixing work completed.</li> </ul>
Block C15	
Diversión de	• Expansion joint covering with Aluminum sheet is completed.
	• Internal fire alarm fixing work 80% completed.
	Terrace fire pump fixing work completed.
G	CCTV camera fixing in progress.
Current Activity	Balcony & Toilet floor drain grating fixing work is in progress.
	• Stilt columns painting work is in progress.
	Fire door shutters fixing work completed.
	• Expansion joint covering sheet painting work completed.
	Internal fire alarm fixing work completed.
	• Internal fire shaft fittings fixing work completed up to 4 <sup>th</sup> floor.
	CCTV camera fixing work completed at stilt floor.
<b>Up to Last Month</b>	Tower bolt fixing work is in progress.
	WC & washbasin fixing work completed.
	Balcony & Toilet floor drain grating fixing work is in progress.
Block C14	Expansion joint covering with GI sheet is completed.
	• Internal fire alarm fixing work 80% completed.
	Terrace fire pump fixing work completed.
	CCTV camera fixing in progress.
<b>Current Activity</b>	Tower bolt fixing work 50% completed.
	Balcony & Toilet floor drain grating fixing work is in progress.
	Internal fire door shutters fixing work completed.
	Expansion joint covering sheet painting work completed.
	Internal fire alarm fixing work completed.
	• Internal fire shaft fittings fixing work completed up to 4th floor.
	CCTV camera fixing work completed at stilt floor.





	CGE (VIIC GREATER TOTAL TROUBET		
<b>Up to Last Month</b>	Ramp-1 & 2 fire fighting work is completed.		
	• External Road Drain plaster work 5% completed. (Total 95%).		
	Horticulture work is in progress.		
Non-Tower	• Drain SFRC covers fixing work 40% completed.		
	Water body granite cladding work is in progress.		
	• IGL trench waterproofing plaster work is in progress near block C-14.		
	Basement fire fighting ITV valves fixing work is in progress.		
<b>Current Activity</b>	• Horticulture work is in progress.		
	• Drain SFRC covers fixing work 30% completed. (Total 70%).		
	• IGL trench waterproofing plaster work is completed near block C-14.		
	Water body granite cladding & Tiling work is in progress.		
	Basement fire fighting ITV valves fixing work is in progress.		
	Basement sprinklers fixing work is in progress.		

#### PHOTOGRAPHS OF PACKAGE-V on 31st OCT -2021

#### **BIRD EYE VIEW OF PROJECT**







#### **CENTER PARK VIEW.**

#### WATER BODY TILING & GRANITE CLADDING WORK IS IN PROGRESS.







# ROAD DRAIN COVERS LAYING WORK COMPLETED FRONT OF BLOCKS C-14 & C-15.

#### IGL TRENCH PLASTER WORK COMPLETED SIDE OF BLOCK C-14.







#### ROAD DRAIN COVERS LAYING WORK IS IN PROGRESS.







PACKAGE-VI	STATUS AS ON 31/10/2021
Up to Last Month	Gate no-3 Wall & floor tiling work in Guard Room completed.
Boundary Wall &	Main gate no-2 ACP & HPL cladding work completed.
Gates	Main Gate no-3 ACP & HPL cladding work is in progress.
	Gate no-1 SS gate fixing work completed.
	• Gate no-2 Ss gate fixing work is in progress.
<b>Current Month</b>	Gate no-2 Ss gate fixing work completed.
Activity	Horticulture work front of gates- 1 & 2 completed.
Up to Last Month	Mummty external plaster work completed.
Shopping.	• External painting work 1 <sup>st</sup> coat 80% completed.
	• Toilets Tiling & Granite work completed in 1 <sup>st</sup> ,2 <sup>nd</sup> & 3 <sup>rd</sup> floors.
	Entrance Planter granite cladding 90% work completed.
Current Month	Entrance Planter granite cladding work completed.
Activity	Planters Granite top fixing work is in progress.
	• Entry planters' pressure Guniting work completed.
	Terrace brick coba waterproofing work completed.
	Staircase railing work is in progress.
Up to Last Month	Over head water tank wall casted.
Nursing	Entrance Ramps chequered tile flooring work completed.
	• Internal drainage work at Gfloor & 1 <sup>st</sup> floor is completed.
	• Toilet's cistern fixing work completed at Gfloor & 1 <sup>st</sup> floor.
G 135 13	Internal fire fighting work is in progress.
Current Month	Over head water tank top slab shuttering is in progress.
Activity	• Entry kerb stone fixing work completed.
	• Internal fire fighting work is in progress.
	• Internal toilets sunken water proofing work completed at Gfloor.
TI. A. T. A. M. A.	Toilet wall tiling work is in progress.
Up to Last Month School	• Mumty slab casted.
School	• Terrace parapet wall brick work 90% completed.
Commont Month	• Internal plaster 90% completed at 1st floor.
Current Month	• Terrace parapet wall brick work 8% completed. (Total 98%).
Activity	• Internal plaster 10% completed at 1 <sup>st</sup> floor. (Total 100%).
Im to I and Manual	• External plaster work 30% completed.
Up to Last Month Community Center	• 25 % Terrace stub columns casted. (Total 50%).
Community Center	• Terrace projection shuttering work is in progress.
	<ul> <li>Balance 35% 3<sup>rd</sup> floor slab casted. (Total 100%).</li> <li>AAC block work 90% completed in 2<sup>rd</sup> floor.</li> </ul>
	T 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	The state of the s
	<ul> <li>Internal plaster 50% completed at 2<sup>nd</sup> floor.</li> <li>Toilets Cpvc piping work at Gfloor is in progress.</li> </ul>
	<ul> <li>Internal putty work 80% completed at Gfloor &amp; 1<sup>st</sup> floor.</li> </ul>
	<ul> <li>Internal putty work 80% completed at Gfloor.</li> <li>Internal HVAC ducting work 60% completed at Gfloor.</li> </ul>
	<ul> <li>Internal five Ac ducting work 60% completed at Officer.</li> <li>Internal fire fighting work is in progress.</li> </ul>
	<ul> <li>Swimming pool piping work is in progress.</li> </ul>
	- 5 willining poor piping work is in progress.





<b>Current Month</b>	•	Balance 50 % Terrace stub columns casted. (Total 100%).	
Activity	•	Terrace projection slab 50% casted.	
	•	AAC block work 10% completed in 2 <sup>nd</sup> floor. (Total 100%)	
	•	AAC block work at 3 <sup>rd</sup> floor is in progress.	
	•	Internal plaster 30% completed at 2 <sup>nd</sup> floor. (Total 80%).	
	•	Toilets Cpvc piping work at Gfloor is completed.	
	•	Internal putty work 90% completed in Gfloor,1st floor.	
	•	Gfloor floor tiling work in Restaurant area completed.	
	•	Internal HVAC ducting work 98% completed at Ground Floor & 1st	
		floor.	
	•	Internal fire fighting work is in progress.	
	•	Swimming pool waterproofing work completed.	
<b>Up to Last Month</b>	•	Road soil filling work front of shopping to nursing home is in progress.	
Non-Tower Area	•	APP water proofing work front of community center is in progress.	
	•	Green area PCC front of shopping completed.	
	•	VDF flooring front of shopping is completed.	
	•	Kerb stone fixing work front of shopping completed.	
<b>Current Month</b>			
Activity	•	APP water proofing work front of community center is completed.	
	•		
	•		
	•	Road hord core laying & compaction work is in progress from	
		Nursing home to Gate no-2.	
	•	Horticulture work in Road from Gate no-2 divider area completed.	





#### PHOTOGRAPHS OF PACKAGE-VI on 31st OCT - 2021

#### **OVERALL VIEW OF PACKAGE VI FROM GATE NO -02**







# SHOPPING AREA FRONT PLANTERS' GRANITE CLADDING WORK COMPLETED.







## TERRACE PROJECTION SHUTTERING WORK IS IN PROGRESS. ROAD WBM WORK IS IN PROGRESS FRONT OF COMMUNITY CENTER.







#### **GATE NO -2 ENTRY HORTICULTURE WORK COMPLETED.**







#### **QUALITY CONTROL**

### <u>DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS</u> <u>CONDUCTED AT SITE:</u>

S. No.	Materials	Source From	<b>Test Date</b>	Tests done	Result
1	Coarse Sand	Bajpur		Each truck	Sieve Analysis & Silt content
2	Coarse Aggregate	Nangal		Each truck	Sieve Analysis & Impact Value
3	Fine Sand	Yamuna Nagar		Each truck	Sieve Analysis & Silt content
4	Bricks	Greater Noida	Greater Noida Each truck		Dimension, Water Absorption & Compressive strength
5	Cement	Third party testing is being done			
6	Steel		Third party te	sting is being done	
7	Piles Integrity		Third party te	sting is being done	
8	Soil Compaction	Third party testing is being done			
9	STP water	Third party testing is being done			
10	Wood	Third party testing is being done			
11	Wires	Third party testing is being done			
12	Tiles	Third party testing is being done			
13	VDF	Third party testing is being done (Flexural Strength done.).			
14					
15	Slump test conducted at site to insure workability if concrete.				





#### **CUBE COMPRESSIVE STRENGTH TESTING**







#### BRICK COMPRESSIVE STRENGTH TESTING







#### **COARSE SAND SIEVE ANALASYS TESTING.**







#### **20MM COARSE AGGREGATE TESTING**







PACKAGE-E (a)		STATUS AS ON 31/10/2021	
<b>Up to Last Month</b>	•	LT panel installation work is in progress.	
	•	Substation fencing work in progress.	
	•	3mtrs pole light fixing work in progress.	
	•	3mtrs Pole foundation work is in progress.	
	•	NPCL substation work is in progress.	
	•	LT cable laying work is in progress.	
<b>Current Month</b>	•	LT panel installation work is in progress.	
Activity	•	Substation fencing work in progress.	
	•	3mtrs pole light fixing work in progress.	
	•	3mtrs Pole foundation work is in progress.	
	•	NPCL substation work is in progress.	
	•	LT cable laying work is in progress.	
	•	33 KV substation trench work is in progress.	

#### **SUB-STATION FENCING WORK IS IN PROGRESS.**







#### NPCL SUBSTATION TRENCH WORK IS IN PROGRESS.







PACKAGE-E (b)	STATUS AS ON 31/10/2021
Up to Last Month	Hoarding boarding 1 no. installation work completed.
	Bollard light foundation work is in progress.
	3mtr Pole & light installation work in progress.
	6mtr Pole & light installation work in progress.
	LT cable installation work is in progress.
Current Month	Bollard light foundation work is in progress.
Activity	• 3mtr Pole foundation & pole light installation work in progress.
	LT cable installation work is in progress.

#### 3 MTR HIGH POLE & LIGHT INSTALLATION WORK IN PROGRESS.





