30th -SEPT-2021

| PACKAGE-II           |   | STATUS AS ON 30/09/2021  |
|----------------------|---|--|
| Up to Last Month     | • | Mumty & Machine Room External Painting work completed.   |
| Block D01            | • | Kitchen sink fixing work in 6 flats completed.   |
|                      | • | False ceiling tile fixing work in toilets completed from 2 <sup>nd</sup> to 5 <sup>th</sup> floor. |
|                      | • | Rising main fixing work completed.   |
| <b>Current Month</b> | • | Kitchen sink fixing work in 50 flats completed. (Total 56)   |
| Activity             | • | False ceiling tile fixing work in toilets completed from 6 <sup>th</sup> to 14 <sup>th</sup>       |
|                      |   | floor.   |
|                      | • | Vertical expansion joint sheet fixing work completed.  |
|                      | • | Balcony drain grating fixing work completed.   |
|                      | • | 2 <sup>nd</sup> coat External painting work in open to sky shaft area completed.                   |
|                      | • | Internal fire alarm work is in progress.   |
|                      | • | Common area light fixing work is in progress.  |
|                      | • | CCTV camera fixing in progress in stilt floor.   |
| Up to Last Month     | • | <ul> <li>Mumty &amp; Machine Room External Painting work completed.</li> </ul>                     |
| Block D02            | • | Rising main fixing work completed.   |
| <b>Current Month</b> | • | Kitchen sink fixing work in 56 flats completed.  |
| Activity             | • | False ceiling tiles fixing work completed up to 11 <sup>th</sup> floor.                            |
|                      | • | Vertical expansion joint aluminum sheet fixing work completed.                                     |
|                      | • | Balcony drain grating fixing work completed.   |
| Up to Last Month     | • | Chinaware fixing work completed from 3 <sup>rd</sup> floor to 7 <sup>th</sup> floor.               |
| Block D03            | • | <ul> <li>Mumty &amp; Machine Room External Painting work completed.</li> </ul>                     |
|                      | • | Rising main fixing work completed.   |
| Current Month        | • | Kitchen sink fixing work in 56 flats completed.  |
| Activity             | • | False ceiling tiles fixing work completed up to 11 <sup>th</sup> floor.                            |
|                      | • | Vertical expansion joint aluminum sheet fixing work completed.                                     |
|                      | • | Balcony drain grating fixing work completed.   |
|                      | • | Chinaware fixing work competed from 8 <sup>th</sup> floor to 10 <sup>th</sup> floor.               |
| Up to Last Month     | • | Balance 8% External painting work completed. (Total 98%).  |
| Block D04            | • | Basement tiles flooring work in corridor completed.  |
|                      | • | <ul> <li>Mumty &amp; Machine Room External Painting work 75% completed.</li> </ul>                 |
|                      | • | Rising main fixing work completed.   |
| Current Month        | • | Balance • Mumty & Machine Room external painting work  |
| Activity             |   | completed.   |
|                      | • | Kitchen sink fixing work in 56 flats completed.  |
| TT 4 T 4 T 7         | • | Balcony drain grating fixing work completed.   |
| Up to Last Month     | • | Balance 8% Aluminum door window glazing fixing work completed.                                     |
| Block D05            |   | (Total 98%).   |
|                      | • | Internal Painting work completed up to 14 <sup>th</sup> floor.                                     |
|                      | • | Internal door shutters painting work completed from 11 <sup>th</sup> to 14 <sup>th</sup> floor.    |
|                      | • | Internal fire shaft door frame fixing work completed up to 14 <sup>th</sup> floor.                 |





| CGEWHO – GREATER NOIDA PROJECT |  |  |
|--------------------------------|--|--|
| Current Month                  | • External painting works 90% completed.   |  |
| Activity                       | • Kitchen sink fixing work in 56 flats completed.  |  |
|                                | Basement floor tiling in corridor completed.   |  |
|                                | • • Mumty & machine Room external painting work completed.   |  |
|                                | Over head water tank tiling work completed.  |  |
| Up to Last Month               | <ul> <li>Over head water tank base slab casted.</li> </ul>   |  |
| Block D06                      | • Terrace projection slab 25% casted.  |  |
|                                | Parapet wall brick work completed at terrace.  |  |
|                                | • Balcony RCC wall casted from 9 <sup>th</sup> floor to 14 <sup>th</sup> floor.  |  |
|                                | • Balance 15% 14 <sup>th</sup> floor Brick completed. (Total 100%).  |  |
|                                | • Internal wall conduiting work completed at 14 <sup>th</sup> floor.   |  |
|                                | • Internal Plaster work completed at 1 <sup>st</sup> & 14 <sup>th</sup> floor. (Total 100%).   |  |
|                                | • Door frames fixing completed at 13 <sup>th</sup> & 14 <sup>th</sup> floor.   |  |
|                                | • Vertical CI piping work completed up to 6 <sup>th</sup> floor.   |  |
|                                | • Cpvc piping work completed up to 11 <sup>th</sup> floor.   |  |
| Current Month                  | Over head water tank wall casted.  |  |
| Activity                       | <ul> <li>Machine Room shuttering work is in progress.</li> </ul>   |  |
|                                | • Terrace projection slab 35% casted. (Total 60%).   |  |
|                                | Basement Brick work completed.   |  |
|                                | • Vertical CI piping work completed from 7 <sup>th</sup> to 12 <sup>th</sup> floor.  |  |
|                                | • Cpvc piping work completed from 12 <sup>th</sup> to 13 <sup>th</sup> floor.  |  |
|                                | • Wings-3 & 4 external plaster work 30% completed.   |  |
|                                | • Internal wall putty work completed up to 6 <sup>th</sup> floor.  |  |
| Up to Last Month               | Road area PCC 240 Sqm completed front of block D-02.   |  |
| Non-Tower                      | • Road reinforcement work for vdf is in progress front of block D-02.  |  |
|                                | Basket ball & Tennis court foundation brick work completed.  |  |
|                                | • Drain SFRC cover casting & laying completed front of block D-03.   |  |
|                                | • Front portion of blocks D-02, D-3, D-04 & D-05 development work is in  |  |
|                                | progress.  |  |
|                                | • Soil dressing, preparation work and Plantation work in progress.   |  |
|                                | Amphitheatre granite stone work completed.   |  |
|                                | • Central Park pathway chequered tiles flooring work 65% completed.  |  |
|                                | • Central Park pathway chequered files flooring work 65% completed.  |  |
|                                | <ul> <li>Pergola 1 no erection work completed.</li> </ul>  |  |
| Current Month                  |  |  |
| Current Month<br>Activity      | Pergola 1 no erection work completed.  |  |
|                                | <ul> <li>Pergola 1 no erection work completed.</li> <li>Balance Road VDF completed front of block D-02.</li> </ul>   |  |
|                                | <ul> <li>Pergola 1 no erection work completed.</li> <li>Balance Road VDF completed front of block D-02.</li> <li>Soil filling work in Road area is in progress near boundary wall.</li> </ul>  |  |
|                                | <ul> <li>Pergola 1 no erection work completed.</li> <li>Balance Road VDF completed front of block D-02.</li> <li>Soil filling work in Road area is in progress near boundary wall.</li> <li>Basket ball &amp; Tennis court soil compaction work is in progress.</li> </ul>   |  |
|                                | <ul> <li>Pergola 1 no erection work completed.</li> <li>Balance Road VDF completed front of block D-02.</li> <li>Soil filling work in Road area is in progress near boundary wall.</li> <li>Basket ball &amp; Tennis court soil compaction work is in progress.</li> <li>Front portion of blocks D-02, D-3, D-04 &amp; D-05 development work is in progress.</li> <li>Soil dressing, preparation work and Plantation work in progress.</li> </ul>  |  |
|                                | <ul> <li>Pergola 1 no erection work completed.</li> <li>Balance Road VDF completed front of block D-02.</li> <li>Soil filling work in Road area is in progress near boundary wall.</li> <li>Basket ball &amp; Tennis court soil compaction work is in progress.</li> <li>Front portion of blocks D-02, D-3, D-04 &amp; D-05 development work is in progress.</li> <li>Soil dressing, preparation work and Plantation work in progress.</li> <li>Pergola 3nos errection &amp; painting work completed. (Total 100%</li> </ul>             |  |
|                                | <ul> <li>Pergola 1 no erection work completed.</li> <li>Balance Road VDF completed front of block D-02.</li> <li>Soil filling work in Road area is in progress near boundary wall.</li> <li>Basket ball &amp; Tennis court soil compaction work is in progress.</li> <li>Front portion of blocks D-02, D-3, D-04 &amp; D-05 development work is in progress.</li> <li>Soil dressing, preparation work and Plantation work in progress.</li> <li>Pergola 3nos errection &amp; painting work completed. (Total 100% completed).</li> </ul> |  |
|                                | <ul> <li>Pergola 1 no erection work completed.</li> <li>Balance Road VDF completed front of block D-02.</li> <li>Soil filling work in Road area is in progress near boundary wall.</li> <li>Basket ball &amp; Tennis court soil compaction work is in progress.</li> <li>Front portion of blocks D-02, D-3, D-04 &amp; D-05 development work is in progress.</li> <li>Soil dressing, preparation work and Plantation work in progress.</li> <li>Pergola 3nos errection &amp; painting work completed. (Total 100%</li> </ul>             |  |





## PHOTOGRAPHS OF PACKAGE-II on 30th SEPT -2021


DEVELOPMENT WORK IS IN PROGRESS FRONT OF BLOCK D-04 & D05.







#### EXTERNAL PLASTER WORK OF BLOCK D-06 IS IN PROGRESS.








#### **CENTER PARK DEVELOPMENT WORK IN PROGRESS**







# GREEN AREA DEVELOPMENT WORK FRONT OF BLOCKS D-02, D-3 D-04 IS IN PROGRESS.







|                               | CGEWHO – GREATER NOIDA PROJECT  |
|-------------------------------|---|
| PACKAGE-III                   | STATUS AS ON 30/09/2021   |
|                               |   |
| Up to Last Month<br>Block C01 | <ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>100% Internal primer &amp;1st coat paint work completed.</li> <li>70% External First coat Paint work completed.</li> <li>Lift ready for testing.</li> </ul>  |
| Current Month<br>Activity     | <ul> <li>Level 01 to 08: Chinaware fitting completed.</li> <li>Level 01 to 14: Electrical Rising main completed.</li> <li>Exhaust fan of toilet and kitchen is completed.</li> <li>Main door teak polish is on progress.</li> </ul>   |
| Up to Last Month<br>Block C05 | <ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI&amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>100%: Internal flat primer &amp; 1st coat paint work completed.</li> <li>90% External First coat Paint work completed.</li> <li>100% Common area First coat paint work completed.</li> <li>Lift ready for testing.</li> </ul> |
| Current Month<br>Activity     | <ul> <li>Electrical rising main work completed.</li> <li>100% Chinaware fitting work completed.</li> <li>Exhaust fan of toilet and kitchen is completed.</li> </ul>   |
| Up to Last Month Block C-06   | <ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>100% Internal 1st coat paint including common area work completed.</li> <li>90% External First coat Paint work completed.</li> <li>Lift ready for testing.</li> </ul>  |





|                                  | CGEWHO - GREATER NOIDA FROJECT   |
|----------------------------------|--|
| Current Month<br>Activity        | <ul> <li>Electrical rising main work completed.</li> <li>100% Chinaware fitting work completed.</li> <li>Exhaust fan of toilet and kitchen is completed.</li> </ul>  |
| Up to Last<br>Month<br>Block C07 | <ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI&amp;CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>100%: Internal 1<sup>st</sup> coat paint including common area work completed.</li> <li>95% External First coat Paint work completed.</li> <li>Lift ready for testing.</li> </ul> |
| Current Month<br>Activity        | <ul> <li>Electrical rising main work completed.</li> <li>100% Chinaware fitting work completed.</li> <li>Exhaust fan of toilet and kitchen is completed.</li> </ul>  |
| Up to Last Month<br>Block C08    | <ul> <li>100% RCC work completed.</li> <li>100% CI &amp; CPVC work completed.</li> <li>100% Flat POP cornice &amp; 1<sup>st</sup> coat putty work completed.</li> <li>100% Floor tile and wall tile completed.</li> <li>100% External 1<sup>st</sup> coat wall putty work completed.</li> <li>100% M.S staircase railing &amp; marble completed.</li> <li>100% S.S balcony railing work completed.</li> <li>Terrace brick coba 80% completed.</li> </ul>   |
| Current Month<br>Activity        | <ul> <li>Lift stone cladding work starts.</li> <li>Remaining 20% Terrace brick coba work is in progress.</li> <li>Aluminum door &amp; window making 100% and fixing 40% completed.</li> <li>Aluminum louvers making 100% and fixing 30% completed.</li> <li>Level 01 to 05: Main door fixing is in progress.</li> </ul>  |
| Up to Last Month Block C09       | <ul> <li>Level 15(Terrace): 100% slab casting completed.</li> <li>Level 12: Internal 1<sup>st</sup> coat putty completed.</li> <li>60% External plaster completed.</li> <li>Level 14: Internal plumbing (cPVC) completed.</li> <li>Level 06: External CI work completed.</li> <li>80% M.S staircase railing work completed.</li> <li>Terrace brick coba 80% completed.</li> </ul>  |





| Current Month<br>Activity        | <ul> <li>Level 13: Internal 1<sup>st</sup> coat putty is in progress.</li> <li>Level 01 to 06: Water proofing work completed.</li> <li>Level 07: Water proofing work is in progress.</li> <li>Toilet Wall tile fixing work starts.</li> <li>Level 07,08&amp;09: External CI work completed.</li> <li>Level 10: External CI work is in progress.</li> <li>Remaining 40% External plaster work completed.</li> <li>Level 01&amp;02: S.S railing work completed.</li> <li>Remaining 20% Terrace brick coba work is on progress.</li> <li>Lift installation work is on progress.</li> </ul> |
|----------------------------------|---|
| Up To Last<br>Month<br>Block C10 | <ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter (Teak) &amp; staircase marble completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>75% External paint completed.</li> <li>Aluminium glass fixing 90% completed.</li> </ul>  |
| Current Month<br>Activity        | <ul> <li>Level 01: Internal Painting work is on progress.</li> <li>10% External paint work completed. <ul> <li>100%Lift cladding work completed.</li> </ul> </li> <li>Lift installation work is on progress.</li> <li>100%Internal door fixing completed.</li> <li>Level 01 to 05: Electrical wiring completed.</li> <li>Level 06: Electrical wiring is in progress.</li> <li>Stilt granite flooring &amp; feature wall starts.</li> </ul>  |
| Up to Last Month<br>Block C11    | <ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat Electrical wiring completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>75% External First coat Paint work completed.</li> </ul>  |
| Current Month<br>Activity        | <ul> <li>100%Stilt granite flooring &amp; feature wall is on progress.</li> <li>Lift earthing work is on progress.</li> <li>Lift installation work is on progress.</li> <li>Level 01 to 04: Electrical switch socket completed.</li> <li>Level 05: Electrical switch socket is in progress.</li> </ul>  |





|                               | CGEWHO – GREATER NOIDA PROJECT   |
|-------------------------------|--|
| Up to Last Month<br>Block C12 | <ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% flat internal electrical wiring completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>85% Internal primer &amp; 1<sup>St</sup> coat paint work completed.</li> <li>Lift ready for testing.</li> <li>70% External painting work completed.</li> </ul>  |
| Current Month<br>Activity     | <ul> <li>Internal primer &amp; 1<sup>St</sup> coat painting is on progress.</li> <li>Internal Electrical switches is on progress.</li> <li>Stilt granite flooring work is on progress.</li> <li>20% External painting work completed.</li> </ul>   |
| Up to last month<br>UG Tank   | U.G. Tank Putty work completed.  |
| Current Month<br>Activity     | U.G. Tank wiring is on progress.   |
| Up to last month  Non-Tower   | <ul> <li>Retaining wall casting completed (277/303) m</li> <li>Boundary wall casted (277/277) RMT</li> <li>Basement putty&amp; 1<sup>st</sup> coat paint 50% completed.</li> <li>Basement plumbing Block C-01,05,06,07,11&amp;12 completed.</li> <li>Basement firefighting fire hydrant, Sprinkler and curtain line 75% completed.</li> <li>Basement VDC flooring 94% completed.</li> <li>External development Sewer &amp; rainwater harvesting work 100% completed.</li> <li>Non tower slab APP membrane water proofing (17720/20700) sqm completed.</li> <li>Green area Guniting work (3200/6000) sqm completed.</li> <li>Road VDF 350/931 RMT completed.</li> </ul> |
| Current Month<br>Activity     | <ul> <li>Basement firefighting fire hydrant, Sprinkler and curtain line work is on progress.</li> <li>Chequered tile Kerb stone work in progress.</li> <li>Drain brick work in progress.</li> <li>IGL brick work in progress.</li> <li>Planter &amp; Drain brick wall Granite fixing work in progress.</li> <li>HDPE pipe work garden hydrant work in progress.</li> <li>External firefighting line laying work in progress.</li> <li>Basement fire fighting work in progress.</li> <li>Road VDF 140 RMT.</li> </ul>   |





## PHOTOGRAPHS OF PACKAGE-III on 30 -SEP -2021

#### **BIRD EYE VIEW OF PROJECT**







## BLOCK C05, C6 & C-7 EXTERNAL PAINTING IN PROGRESS.







#### BLOCK C11, C12&C-01 EXTERNAL PAINTING IN PROGRESS.







#### **BLOCK C08,09&10 EXTERNAL PAINTING WORK IN PROGRESS.**







#### LANDSCAPING WORK IS ON PROGRESS







| PACKAGE-IV                     | STATUS AS ON 30/09/2021   |
|--------------------------------|---|
| Up to Last Month               | Second Lift testing work in progress.   |
| Block A01                      | <ul> <li>Common area shaft paint work completed.</li> </ul>   |
|                                | Eleventh floor sub main work completed.   |
|                                | Rising main work completed.   |
| <b>Current Month</b>           | Second Lift testing work in progress.   |
| Activity                       | • Twelfth floor sub main work in progress.  |
|                                | Fire door glass fixing work in progress.  |
|                                | • Expansion joint sheet fixing work in progress.  |
|                                | • Lift machine room light point work completed.   |
|                                | • Numbering of block completed.   |
| <b>Up to Last Month</b>        | Second Lift testing work in progress.   |
| Block B04                      | • Expansion joint Aluminum sheet covering work in progress.   |
|                                | Common area shaft paint work completed.   |
|                                | Rising main work completed.   |
| Current Month                  | • Second Lift testing work in progress.   |
| Activity                       | • Expansion joint Aluminium sheet covering work completed.  |
|                                | • Fire door glass fixing work in progress.  |
|                                | • Fifth floor ceiling final coat of paint work completed.   |
|                                | • Fire pump installation work in progress.  |
|                                | Numbering of block completed.   |
| Up to Last Month               | <ul> <li>Second lift Lift Testing work in progress.</li> </ul>  |
| Block B05                      | • Expansion joint Aluminum sheet covering work in progress.   |
|                                | • 98% External Paint 1 <sup>st</sup> coat work completed.   |
|                                | • 100% Aluminum door windows silicon filling work completed.  |
|                                | Ninth floor sub main work completed.  |
|                                | Rising main work completed.   |
| Current Month                  | • Second lift Testing work in progress.   |
| Activity                       | • Expansion joint Aluminium sheet covering work in progress.  |
|                                | • 98%External Paint 1st coat work completed.  |
|                                | • Tenth floor sub main work completed.  |
|                                | Twelfth floor ceiling final coat of paint work completed.  First floor well final coat of paint work completed. |
|                                | First floor wall final coat of paint work completed.  First door closs firing work in progress.                 |
|                                | Fire door glass fixing work in progress.  Fire nump installation work completed.                                |
|                                | • Fire pump installation work completed.  |
|                                | Electrical testing work in progress.  Numbering of block completed.   |
| Un to Last Manth               | Numbering of block completed.  OSO Mumber Machine group external point work completed.                          |
| Up to Last Month<br>Block C-16 | 95% Mumty Machine room external paint work completed.      Motor board fixing work in progress.                 |
| DIUCK C-10                     | Meter board fixing work in progress.     Ninth floor Sub main work completed.                                   |
|                                | Ninth floor Sub main work completed.      Dising main fixing work completed.                                    |
|                                | <ul> <li>Rising main fixing work completed.</li> </ul>  |





|                         | CGEWHO - GREATER NOIDA PROJECT  |
|-------------------------|---|
| <b>Current Month</b>    | • 98% Mumty Machine room external paint work completed.                           |
| Activity                | Meter board fixing work in progress.  |
|                         | Tenth floor Sub main work completed.  |
|                         | Twelfth floor ceiling final coat of paint work in progress.                       |
|                         | Numbering of block completed.   |
| <b>Up to Last Month</b> | 95% Mumty Machine room external paint work in progress.                           |
| Block C-17              | Meter board fixing work in progress.  |
|                         | Rising main fixing work completed.  |
|                         |   |
| <b>Current Month</b>    | • 98% Mumty Machine room external paint work in progress.                         |
| Activity                | Meter board fixing work in progress.  |
|                         | • Expansion joint Aluminum sheet covering work in progress.                       |
|                         | • Fifth floor fixing of Grating in balcony and bath room work in progress.        |
|                         | • Electrical testing work in progress.  |
|                         | Numbering of block completed.   |
| <b>Up to Last Month</b> | One Lift testing work completed.  |
| Block C-02              | Expansion joint Aluminum sheet covering work in progress.                         |
|                         | Rising main work completed.   |
|                         | Aluminum Door and Windows Silicon filling work in progress.                       |
| <b>Current Month</b>    | • Expansion joint Aluminum sheet covering work in progress.                       |
| Activity                | Aluminium Door and Windows Silicon filling work in progress.                      |
|                         | Numbering of block completed.   |
| <b>Up to Last Month</b> | 98% First coat External Painting work completed.                                  |
| Block C-03              | Expansion joint Aluminum sheet covering work in progress.                         |
|                         | Rising main work completed.   |
| Current Month           | First coat External Painting work completed.                                      |
| Activity                | <ul> <li>Expansion joint Aluminium sheet covering work in progress.</li> </ul>    |
| 12021120                | <ul> <li>Expansion joint Aluminum sheet covering work in progress.</li> </ul>     |
|                         | <ul> <li>Electrical testing work in progress.</li> </ul>                          |
|                         | <ul> <li>Numbering of block completed.</li> </ul>                                 |
| Up to Last Month        | 99% First coat External Painting work completed.                                  |
| Block C-04              | <ul> <li>Expansion joint Aluminum sheet covering work in progress.</li> </ul>     |
|                         | <ul> <li>Rising main work completed.</li> </ul>                                   |
|                         | <ul> <li>Aluminum Door and Windows Silicon filling work in progress.</li> </ul>   |
| <b>Current Month</b>    | First coat External Painting work completed.                                      |
| Activity                | • Expansion joint Aluminium sheet covering work in progress.                      |
| •                       | <ul> <li>Aluminium Door and Windows Silicon filling work in progress.</li> </ul>  |
|                         | Numbering of block completed.   |
| Up to Last Month        | Ramp No-3- 30% slab casting work completed.                                       |
| NTA                     | <ul> <li>Green area development work in progress.</li> </ul>                      |
|                         | <ul> <li>99% Green Area Kerb stone fixing work completed.</li> </ul>              |
|                         | <ul> <li>97% Parking area Kerb stone fixing work completed.</li> </ul>            |
|                         | <ul> <li>Basket ball &amp; Tennis court work in progress.</li> </ul>              |
|                         | <ul> <li>IGL Drain water proofing plaster work in progress.</li> </ul>            |
|                         | <ul> <li>Basement Fire Fighting main line connection work in progress.</li> </ul> |
|                         | basement ine righting main fine conficction work in progress.                     |





#### Current Month Activity

- Ramp No-3- 100% slab casting work completed.
- Ramp No-3- brick work and plaster work in progress.
- Darin covering work in progress.
- Water Body stone fixing work in progress.
- Green area development work in progress.
- Green Area Kerb stone fixing work completed.
- Parking area Kerb stone fixing work completed.
- Basket ball & Tennis court work in progress.
- IGL Drain water proofing plaster work in progress.
- Basement Fire Fighting main line connection work in progress.
- Basement painting work in progress.
- Basement light fixing work in progress.

## PHOTOGRAPHS OF PACKAGE-IV on 30th SEP 2021


**BIRD EYE VIEW OF PROJECT** 







## **CENTRAL PARK DEVELOPMENT IS IN PROGRESS.**







## GREEN AREA DEVELOPMENT WORK IN PROGRESS.







## **BLOCK NUMBERING WORK COMPLETED.**







## **ROAD GREEN AREA WORK IN PROGRESS.**







| PACKAGE-V                     | STATUS AS ON 30/09/2021  |
|-------------------------------|--|
| Up to Last Month              | 5111 05 135 O11 5010712021   |
| Block B01                     | <ul> <li>Toilet false ceiling tile fixing work 95% completed.</li> <li>Floor drain gratings in Toilets fixing work 90% completed.</li> <li>2<sup>nd</sup> lift testing work is in progress.</li> <li>Entrance door locks fixing work 100% completed.</li> <li>Fire shaft glass fixing work 100% completed.</li> <li>Terrace Fire pump fixing work is in progress.</li> </ul>   |
| Current Activity              | <ul> <li>Balance 5% Toilet false ceiling tile fixing work completed. (Total 100%).</li> <li>Balance 10% Floor drain gratings in Toilets fixing work completed. (Total 100%).</li> <li>Expansion joint covering with Aluminum sheet is completed.</li> <li>Tower bolt fixing work 80% completed.</li> <li>Main door polish work is in progress.</li> <li>Internal 2<sup>nd</sup> coat ceiling painting work is in progress.</li> <li>2<sup>nd</sup> lift testing work completed.</li> <li>WC &amp; washbasin fixing work completed.</li> <li>Internal fire alarm fixing work 90% completed.</li> <li>Terrace Fire pump fixing work completed.</li> <li>CCTV camera fixing in progress.</li> </ul> |
| Up to Last Month<br>Block B02 | <ul> <li>Toilet false ceiling tile fixing work 95% completed.</li> <li>Floor drain gratings in Toilets fixing work 85% completed.</li> <li>2<sup>nd</sup> lift testing work is in progress.</li> <li>Entrance door locks fixing work 100% completed.</li> <li>Fire shaft glass fixing work 100% completed.</li> <li>Terrace fire pump fixing work is in progress.</li> </ul>   |
| Current Activity              | <ul> <li>Balance 5% Toilet false ceiling tile fixing work completed. (Total 100%).</li> <li>Balance 15% Floor drain gratings in Toilets fixing work completed. (Total 100%).</li> <li>Tower bolt fixing work 80% completed.</li> <li>Main door polish work is completed.</li> <li>Internal ceiling 2<sup>nd</sup> coat painting work is in progress.</li> <li>WC &amp; washbasin fixing work completed.</li> <li>2<sup>nd</sup> lift testing work completed.</li> <li>Internal fire alarm fixing work in progress.</li> <li>Terrace Fire pump fixing work completed.</li> </ul>  |





|                               | CGEWIIO – GREATER NOIDA FROJECT   |
|-------------------------------|---|
| Up to Last Month<br>Block B03 | <ul> <li>Entry door shutter polish work completed from 2<sup>nd</sup> floor to 13<sup>th</sup> floor.</li> <li>Entry door lock fixing work 100% completed.</li> <li>Both Lifts testing work is in progress.</li> <li>Terrace fire pump fixing work is in progress.</li> </ul>   |
| Current Activity              | <ul> <li>Tower bolt fixing work completed up to 10<sup>th</sup> floor.</li> <li>Both Lifts testing work is completed.</li> <li>Internal 2<sup>nd</sup> coat ceiling painting work is in progress.</li> <li>Expansion joint covering with Aluminum sheet is completed.</li> <li>WC &amp; wash basin fixing work 80% completed.</li> <li>Terrace fire pump fixing work completed.</li> </ul>  |
| Up to Last Month Block C15    | <ul> <li>Toilets false ceiling tile fixing work 100% completed.</li> <li>Entry door lock fixing work 100% completed.</li> <li>Fire shaft glass fixing work is in progress.</li> </ul>   |
| Current Activity              | <ul> <li>WC &amp; washbasin fixing work completed.</li> <li>Balcony &amp; Toilet floor drain grating fixing work is in progress.</li> <li>Fire shaft glass fixing work completed.</li> <li>Expansion joint covering with Aluminum sheet is completed.</li> <li>Internal fire alarm fixing work 80% completed.</li> <li>Terrace fire pump fixing work completed.</li> <li>CCTV camera fixing in progress.</li> </ul>   |
| Up to Last Month Block C14    | <ul> <li>Toilets false ceiling tile fixing work 100% completed.</li> <li>Entry door lock fixing work 100% completed.</li> </ul>   |
| Current Activity              | <ul> <li>Tower bolt fixing work is in progress.</li> <li>WC &amp; washbasin fixing work completed.</li> <li>Balcony &amp; Toilet floor drain grating fixing work is in progress.</li> <li>Expansion joint covering with GI sheet is completed.</li> <li>Internal fire alarm fixing work 80% completed.</li> <li>Terrace fire pump fixing work completed.</li> <li>CCTV camera fixing in progress.</li> </ul>  |
| Up to Last Month Non-Tower    | <ul> <li>Ramp-02 fire fighting work is in progress.</li> <li>External Road Drain plaster work 20% completed. (Total 90%).</li> <li>Horticulture work is in progress.</li> <li>Vertical expansion joint Aluminum sheet fixing work between blocks C-14 &amp; C-15 and B-02 &amp; B-03 completed.</li> <li>Vertical expansion joint Aluminum sheet fixing work between blocks B-01 &amp; B-02 is in progress.</li> <li>IGL trench waterproofing plaster work is in progress.</li> </ul> |





#### **Current Activity**

- Ramp-1 & 2 fire fighting work is completed.
- External Road Drain plaster work 5% completed. (Total 95%).
- Horticulture work is in progress.
- Drain SFRC covers fixing work 40% completed.
- Water body granite cladding work is in progress.
- IGL trench waterproofing plaster work is in progress near block C-14.
- Basement firefighting ITV valves fixing work is in progress.

## PHOTOGRAPHS OF PACKAGE-V on 30th SEPT -2021

#### **BIRD EYE VIEW OF PROJECT**







#### **CENTER PARK VIEW.**







## CENTRAL PARK TOP VIEW WATER BODY GRANITE CLADDING WORK IS IN PROGRESS.







#### HORTICULTURE WORK IS IN PROGRESS FRONT OF BLOCK B-02 & B-03.







| PACKAGE-VI              | STATUS AS ON 30/09/2021   |
|-------------------------|---|
| Up to Last Month        | 12 12 12 12 13 13 13 13 13 13 13 13 13 13 13 13 13  |
| Boundary Wall &         | Gate no-1 Wall & floor tiling work in Guard Room completed.   |
| Gates                   | Main gate no-1 ACP & HPL cladding work completed.   |
|                         | Main Gate no-1 ACP & HPL cladding work is in progress.  |
| Current Month           |   |
| Activity                | Gate no-3 Wall & floor tiling work in Guard Room completed.   |
|                         | Main gate no-2 ACP & HPL cladding work completed.   |
|                         | Main Gate no-3 ACP & HPL cladding work is in progress.  |
|                         | Gate no-1 SS gate fixing work completed.  |
|                         | • Gate no-2 Ss gate fixing work is in progress.   |
| Up to Last Month        | Mumty external plaster work is in progress.   |
| Shopping.               | Toilets Tiling & Granite work is in progress at Gfloor.   |
|                         | Entrance Planter brick work completed.  |
|                         | Road Drain brick work completed front of shopping area.   |
| <b>Current Month</b>    | Mumty external plaster work completed.  |
| Activity                | • External painting work 1 <sup>st</sup> coat 80% completed.  |
|                         | • Toilets Tiling & Granite work completed in 1 <sup>st</sup> ,2 <sup>nd</sup> & 3 <sup>rd</sup> floors. |
|                         | • Entrance Planter granite cladding 90% work completed.   |
|                         |   |
| Up to Last Month        | Entrance Ramps Brick work completed.  |
| Nursing                 | • Internal drainage work at Gfloor & 1st floor is in progress.  |
| <b>Current Month</b>    | Over head water tank wall casted.   |
| Activity                | Entrance Ramps chequered tile flooring work completed.  |
|                         | • Internal drainage work at Gfloor & 1st floor is completed.  |
|                         | • Toilet's cistern fixing work completed at Gfloor & 1st floor.   |
|                         | Internal fire fighting work is in progress.   |
| Up to Last Month        | Mumty shuttering & Reinforcement work is in progress.   |
| School                  | • Terrace projection 25% casted. (Total 90%).   |
|                         | • Internal plaster completed at 1st floor.  |
|                         |   |
| <b>Current Month</b>    | Mumty slab casted.  |
| Activity                | • Terrace parapet wall brick work 90% completed.  |
|                         | • Internal plaster 90% completed at 1st floor.  |
| Up to Last Month        | Terrace stub columns 25% casted.  |
| <b>Community Center</b> | Terrace projection shuttering work is in progress.  |
|                         | • 3 <sup>rd</sup> floor slab 65% casted.  |
|                         | • Balance 3 <sup>rd</sup> floor slab Reinforcement work is in progress.                                 |
|                         | • AAC block work 90% completed in 2 <sup>nd</sup> floor.  |
|                         | • Internal plaster work 85% completed at 1 <sup>st</sup> floor.   |





| Current Month<br>Activity | <ul> <li>25 % Terrace stub columns casted. (Total 50%).</li> <li>Terrace projection shuttering work is in progress.</li> <li>Balance 35% 3<sup>rd</sup> floor slab casted. (Total 100%).</li> </ul> |
|---------------------------|---|
|                           | • AAC block work 90% completed in 2 <sup>nd</sup> floor.  |
|                           | • Internal plaster work 15% completed at 1st floor. (Total 100%).   |
|                           | • Internal plaster 50% completed at 2 <sup>nd</sup> floor.  |
|                           | • Toilets Cpvc piping work at Gfloor is in progress.  |
|                           | • Internal putty work 80% completed at Gfloor & 1st floor.  |
|                           | • Internal HVAC ducting work 60% completed at Gfloor.   |
|                           | • Internal fire fighting work is in progress.   |
|                           | • Swimming pool piping work is in progress.   |
| <b>Up to Last Month</b>   | • 5% APP membrane water proofing work completed. (Total 85%).   |
| Non-Tower Area            | • Basement fire fighting work in progress.  |
|                           | • External sewerage piping work 5% completed. (Total 100%)  |
|                           | • External drainage works 10% completed. (Total 100%).  |
|                           |   |
| <b>Current Month</b>      | • Road soil filling work front of shopping to nursing home is in  |
| Activity                  | progress.   |
|                           | • APP water proofing work front of community center is in progress.   |
|                           | • Green area PCC front of shopping completed.   |
|                           | • VDF flooring front of shopping is completed.  |
|                           | • Kerb stone fixing work front of shopping completed.   |

## PHOTOGRAPHS OF PACKAGE-VI on 30<sup>th</sup> SEPT – 2021

## **OVERALL VIEW OF PACKAGE VI FROM GATE NO -02**







#### SHOPPING AREA FRONT PLANTERS' GRANITE CLADDING IN PROGRESS.

#### EXTERNAL PAINTING 80% COMPLETED.







# BALANCE COUMNITY 3<sup>RD</sup> FLOOR ROOF SLAB CASTED. TERRACE PROJECTION SHUTTERING WORK IS IN PROGRESS. APP WATER PROOFING WORK FRONT OF COMMUNITY IS IN PROGRESS.







## GATE NO -2SS GATE CLADDING & FIXING WORK COMPLETED.







## **QUALITY CONTROL**

# <u>DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS</u> <u>CONDUCTED AT SITE:</u>

| S.<br>No. | Materials   | Source From  | Test Date      | Tests done          | Result  |
|-----------|---|--|----------------|---------------------|---|
| 1         | Coarse Sand   | Bajpur   |                | Each truck          | Sieve Analysis & Silt content                               |
| 2         | Coarse Aggregate  | Nangal   |                | Each truck          | Sieve Analysis &<br>Impact Value                            |
| 3         | Fine Sand   | Yamuna Nagar   |                | Each truck          | Sieve Analysis &<br>Silt content                            |
| 4         | Bricks  | Greater Noida  |                | Each truck          | Dimension, Water<br>Absorption &<br>Compressive<br>strength |
| 5         | Cement  | Third party testing is being done                            |                |                     |   |
| 6         | Steel   |  | Third party te | sting is being done |   |
| 7         | Piles Integrity   |  | Third party te | sting is being done |   |
| 8         | Soil Compaction   |  | Third party te | sting is being done |   |
| 9         | STP water   | Third party testing is being done                            |                |                     |   |
| 10        | Wood  | Third party testing is being done                            |                |                     |   |
| 11        | Wires   | Third party testing is being done                            |                |                     |   |
| 12        | Tiles   | Third party testing is being done                            |                |                     |   |
| 13        | VDF   | Third party testing is being done (Flexural Strength done.). |                |                     |   |
| 14        | RCC Cubes are being tested and Register is being maintained.    |  |                |                     |   |
| 15        | Slump test conducted at site to insure workability if concrete. |  |                |                     |   |





#### **CUBE COMPRESSIVE STRENGTH TESTING**







#### **BRICK COMPRESSIVE STRENGTH TESTING**







#### **COARSE SAND SIEVE ANALASYS TESTING.**







#### **20MM COARSE AGGREGATE TESTING**







## PACKAGE-E (a)

| PACKAGE-E (a)           | STATUS AS ON 30/09/2021                                     |  |  |
|-------------------------|---|--|--|
| <b>Up to Last Month</b> | Landscape lighting cable laying work is in progress.        |  |  |
|                         | Solar inverter installation work is in progress.            |  |  |
|                         | Chamber making work in green area is in progress.           |  |  |
|                         | 6mtrs pole foundation work is in progress.                  |  |  |
|                         | • 6mtrs street pole light fixing work is in progress.       |  |  |
|                         | • ESS-3 & ESS-5A LT panel installation work is in progress. |  |  |
|                         | • ESS-3 & ESS-5A LT cable laying work is in progress.       |  |  |
|                         | • ESS-3 & ESS-5A RMU installation work is in progress.      |  |  |
| Current Month           | • LT panel installation work is in progress.                |  |  |
| Activity                | Substation fencing work in progress.                        |  |  |
|                         | • 3mtrs pole light fixing work in progress.                 |  |  |
|                         | • 3mtrs Pole foundation work is in progress.                |  |  |
|                         | NPCL substation work is in progress.                        |  |  |
|                         | LT cable laying work is in progress.                        |  |  |


#### PANEL ASSEMBLING WORK IS IN PROGRESS.







#### NPCL SUBSTATION WORK IS IN PROGRESS.








| PACKAGE-E (b)        | STATUS AS ON 30/09/2021  |  |
|----------------------|--|--|
| Up to Last Month     | Landscape lighting cable laying work is in progress.             |  |
|                      | Solar inverter installation work is in progress.                 |  |
|                      | • Chamber work in green area is in progress.                     |  |
|                      | • RCC Hume pipe laying & chamber work done at ESS-02, 05B & ESS- |  |
|                      | 01.  |  |
|                      | Fencing work is in progress.                                     |  |
|                      | RMU panel installation work completed.                           |  |
|                      | National flag mast installation work completed.                  |  |
|                      | Feeder pillar installation work is in progress.                  |  |
|                      | LT cabling work is in progress.                                  |  |
|                      | Earthing work is in progress.                                    |  |
| <b>Current Month</b> | Hoarding boarding installation work completed.                   |  |
| Activity             | Bollard light foundation work is in progress.                    |  |
|                      | • 6mtr Pole & light installation work in progress.               |  |
|                      | LT cable installation work is in progress.                       |  |





#### **HOARDING BOARD INSTALLATION WORK IN PROGRESS.**







#### 3 MTR HIGH POLE & LIGHT INSTALLATION WORK IN PROGRESS.





