



30.11.2023

BLOCK	STATUS AS ON 30	30.11.2023 <sup>th</sup> NOVEMBER-2023
BLOCK	<ul> <li>STATUS AS ON 30</li> <li>100% Completed Works <ul> <li>Terrace floor level slab R.C.C</li> <li>Terrace floor Parapet Columns Conc.</li> <li>Lift Head room (4 out of 4) - Slab Co</li> <li>Over Head Water Tank <ul> <li>(a) Base Slab Concrete 2 out of 2</li> <li>(b) Tank Wall Concrete 2 out of 2</li> <li>(c) Top Cover slab Concrete 2 out</li> </ul> </li> <li>Block work upto Tenth floor &amp; Parapet Ceiling Plastering upto Tenth floor.</li> <li>Wall plastering upto Tenth floor.</li> <li>1<sup>st</sup> Coat Wall Putty upto Tenth floor</li> </ul> </li> </ul>	rete. oncrete. 2 at of 2
	Electrical Conducting works in Tenth     STATUS UPTO PREVIOUS MONTH	n floor. STATUS AS ON 30 <sup>th</sup> NOVEMBER-2023
A1 BLOCK	<ul> <li>90% Completed Works <ul> <li>Electrical Conducting works in Tenth floor.</li> <li>Fixing of Balcony Handrail.</li> <li>External Plastering 95% completed in all sides.</li> <li>Fixing of Water supply pipe Lines (CPVC) – 92% completed (185 / 200).</li> </ul> </li> <li>Works On Progress <ul> <li>1<sup>st</sup> Coat Wall Putty started in Tenth floor floor.</li> <li>Fixing of Sanitary Lines (PVC) – 45% completed (90/ 200).</li> </ul> </li> <li>Fixing of Vertical Plumbing Lines in Shaft 40% completed. (80/200).</li> <li>Fixing of Staircase Handrail 70% completed.</li> <li>Lift Materials 4 out of 4 received.</li> </ul> <li>Model Flat Finishing works 90% completed.</li>	<ul> <li>90% Completed Works <ul> <li>Fixing of Balcony Handrail.</li> <li>External Plastering 95% completed in all sides.</li> <li>Fixing of Water supply pipe Lines (CPVC) –97% completed (195 / 200).</li> </ul> </li> <li>Works On Progress <ul> <li>Fixing of Sanitary Lines (PVC) – 80% completed (160/ 200).</li> <li>Fixing of Vertical Plumbing Lines in Shaft 60% completed. (120/200).</li> <li>Fixing of Staircase Handrail 75% completed.</li> <li>Fixing of Bathroom Wall Tiles 20% completed (40/200).</li> <li>Laying Of Floor Tiles <ul> <li>a) Ceramic Tiles in Bathroom 20% completed (40/200).</li> </ul> </li> <li>Vitrified Tiles in Halls &amp; Bedrooms 18% completed (36/200).</li> </ul></li></ul>



Page 2

A2 BLOCK A2 BLOCK A2 BLOCK	STATUS AS ON 30 <sup>4</sup> Completed Works errace floor level slab R.C.C errace floor Parapet Columns Conc ft Head room (4 out of 4) - Slab C ver Head Water Tank (a) Base Slab Concrete 2 out of 2 (b) Tank Wall Concrete 2 out of (c) Top Cover slab Concrete 2 o lock work upto Tenth floor & Para	oncrete. 2 2
A2 BLOCK	Completed Works errace floor level slab R.C.C errace floor Parapet Columns Conc ft Head room (4 out of 4) - Slab C ver Head Water Tank (a) Base Slab Concrete 2 out of 2 (b) Tank Wall Concrete 2 out of (c) Top Cover slab Concrete 2 o	crete. Poncrete. 2 2 2
A2 BLOCK A2 BLOCK A2 BLOCK	errace floor level slab R.C.C errace floor Parapet Columns Conc ft Head room (4 out of 4) - Slab C ver Head Water Tank (a) Base Slab Concrete 2 out of 2 (b) Tank Wall Concrete 2 out of (c) Top Cover slab Concrete 2 o	oncrete. 2 2
A2 BLOCK • 90% ( • Ceili • Wall	eiling Plastering upto Tenth floor. Tall plastering upto Tenth floor. <sup>t</sup> Coat Wall Putty upto Ninth floor	-
<ul> <li>◆ 90% (</li> <li>■ Ceili</li> <li>■ Wall</li> </ul>	UPTO PREVIOUS MONTH	STATUS AS ON 30 <sup>th</sup> NOVEMBER-2023
floor Fixin Exte comp Fixin	ng of Balcony Handrail. In all sides 90% bleted. Ing of Water supply pipe Lines V(C) – 92% completed (184 / 200).	<ul> <li>90% Completed Works         <ul> <li>Electrical Conducting works in Tenth floor.</li> <li>Fixing of Balcony Handrail.</li> <li>External plastering in all sides 90% completed.</li> <li>Fixing of Water supply pipe Lines (CPVC) –95% completed (190 / 200).</li> </ul> </li> <li>Works On Progress         <ul> <li>1<sup>st</sup> Coat Wall Putty in Tenth floor.</li> <li>Fixing of Sanitary Lines (PVC) – 60% completed (120/ 200).</li> </ul> </li> </ul>



	■ Fixing of Sanitary Lines (PVC) – 22%		
	completed (45/ 200). • Fixing of Vertical Plumbing Lines in		
	Shaft started.		
	Lift Materials 4 out of 4 received		
BLOCK	STATUS AS ON 30 <sup>th</sup> NOVEMBER-2023		
	<ul> <li>100% Completed Works</li> <li>Terrace floor level slab R.C.C</li> </ul>		
	<ul> <li>Terrace floor Parapet Columns Concrete.</li> </ul>		
	Lift Head room (3 out of 3) - Slab Concrete.		
	<ul> <li>Over Head Water Tank</li> <li>(a) Base Slab Concrete (3 out of 3)</li> <li>(b) Wall Concrete (3 out of 3)</li> </ul>		
	(c) Top Cover slab (3 out of 3)		
	<ul> <li>Block work upto Tenth floor &amp; Parapet wall.</li> </ul>		
	<ul> <li>Ceiling Plastering upto Tenth floor.</li> </ul>		
	<ul> <li>Wall plastering upto Tenth floor.</li> </ul>		
	<ul> <li>1<sup>st</sup> Coat Wall Putty upto Tenth floor.</li> </ul>		
	■ 2 <sup>nd</sup> Coat Wall Putty upto Tenth floor.		
	• Fixing of Balcony Handrail.		
B1 BLOCK	Fixing of Staircase Hand Rails		
	<ul> <li>Fixing of Internal Plumbing Line</li> </ul>		
	a) Water supply pipe Lines (CPVC).		
	b) Sanitary Lines (PVC)		
	<ul> <li>Fixing of Vertical Plumbing Line in Shafts</li> <li>a) Water supply pipe Lines (G.I).</li> <li>b) Sanitary Lines (PVC).</li> </ul>		
	<ul><li>Fixing of Bathroom Wall Tiles.</li><li>Laying Of Floor Tiles</li></ul>		
	b) Ceramic Tiles in Bathroom		
	<ul><li>c) Vitrified Tiles in Halls &amp; Bedrooms.</li><li>d) Vitrified Tiles in Corridor</li></ul>		
	<ul><li>d) Vitrified Tiles in Corridor.</li><li>Fixing of UPVC Windows.</li></ul>		
	<ul> <li>Fixing of UPVC French Door (without Mosquito mesh shutter)</li> </ul>		
	<ul> <li>Kitchen Finishing Works</li> </ul>		
	c) Fixing of Wall Dados.		
	d) Laying of Granite Countertop.		



	e) Fixing of S.S Sink.	
	<ul> <li>External Plastering in all sides.</li> <li>Water Proofing Works.</li> <li>Termore floor Water proofing.</li> </ul>	
	<ul><li>a) Terrace floor Water proofing.</li><li>b) Over Head Water Tank</li></ul>	
	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30 <sup>th</sup> NOVEMBER-2023
	♦ 90% Completed Works	♦ 90% Completed Works
	• Lift Installation works 3 out 3.	<ul> <li>Lift Installation works 3 out 3.</li> </ul>
	<ul> <li>Lift Cladding works 2 out of 3.</li> </ul>	<ul> <li>Lift Cladding works 3 out of 3.</li> </ul>
	<ul> <li>Fixing of Door Shutters 90% completed (760/840).</li> </ul>	<ul> <li>Fixing of Door Shutters 95% completed (800/840).</li> </ul>
	• Laying of Green marble for Staircase.	<ul> <li>Laying of Green marble for Staircase.</li> </ul>
BI BLOCK	<ul> <li>Application of Exterior Wall Primer</li> </ul>	<ul> <li>Application of Exterior Wall Primer</li> </ul>
DIBLOCK	♦ Works On Progress	♦ Works On Progress
	• Fixing of M.S Window Safety Grills.	• Fixing of M.S Window Safety Grills
	• Electrical wire pulling work on	40% completed.
	progress.	<ul> <li>Electrical wire pulling work 25%</li> </ul>
	• Lift Cladding works for 3 <sup>rd</sup> Lift on	completed (30/120).
	progress.	• Model Flat Finishing works 95%
	• Model Flat Finishing works 95% completed.	completed.
BLOCK	STATUS AS ON 30th NOVEMBER-2023	
	◆ 100% Completed Works	
	<ul> <li>Seventh floor level slab R.C.C</li> </ul>	
	<ul> <li>Seventh floor Columns Concrete.</li> </ul>	
	Eighth floor level slab 1 <sup>st</sup> Half R.C.C	
	<ul> <li>Block work upto Fifth floor.</li> </ul>	
	<ul> <li>Ceiling plastering upto Fourth floor.</li> </ul>	
B2 BLOCK	<ul> <li>Wall plastering upto Fourth floor.</li> </ul>	
D2 BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30 <sup>th</sup> NOVEMBER-2023
	Works On Progress	♦ Works On Progress
	<ul> <li>Eighth floor level slab – 1<sup>st</sup> Half Shuttering &amp; Barbending works 90% completed.</li> </ul>	<ul> <li>Eighth floor level slab – 2<sup>nd</sup> Half Shuttering &amp; Barbending works 60% completed.</li> </ul>
		<ul> <li>Ninth floor level slab – 1<sup>st</sup> Half Shuttering works 20% completed.</li> </ul>



Page 5

	Block work	<ul> <li>Block work</li> </ul>	
	<ul><li>a) In Fifth floor 80% completed.</li><li>b) In Sixth floor 40% completed.</li></ul>	<ul><li>a) In Sixth floor 60% completed.</li><li>b) In Seventh floor 20% completed.</li></ul>	
	<ul> <li>Ceiling Plastering</li> </ul>	Ceiling Plastering	
	a) In Fourth floor 80% completed.	a) In Fifth floor 50% completed.	
	<ul> <li>Wall Plastering</li> </ul>	<ul> <li>Wall Plastering</li> </ul>	
	a) In Fourth floor 80% completed.	a) In Fifth floor 50% completed	
BLOCK	STATUS AS ON 30th NOVEMBER-2023		
	<ul> <li>100% Completed Works</li> <li>Terrace floor level slab R.C.C</li> </ul>		
	<ul> <li>Terrace floor Parapet Columns Concret</li> </ul>	e.	
	Lift Head room (4 out of 4) - Slab Cond	crete.	
	<ul> <li>Over Head Water Tank <ul> <li>(a) Base Slab Concrete (3 out of 3)</li> <li>(b) Wall Concrete (3 out of 3)</li> <li>(c) Top Cover slab (3 out of 3)</li> </ul> </li> <li>Block work upto Tenth floor &amp; Parapet wall.</li> </ul>		
	• Ceiling Plastering upto Tenth floor.		
	• Wall plastering upto Tenth floor.		
	<ul> <li>1<sup>st</sup> Coat Wall Putty upto Tenth floor.</li> </ul>		
	■ 2 <sup>nd</sup> Coat Wall Putty upto Tenth floor.		
C1 BLOCK	<ul> <li>Fixing of Balcony Handrail.</li> </ul>		
	<ul> <li>Fixing of Internal Plumbing Line.</li> </ul>		
	a) Water supply pipe Lines (CPVC).		
	b) Sanitary Lines (PVC)		
	<ul> <li>Fixing of Vertical Plumbing Line in Shafts</li> </ul>		
	a) Water supply pipe Lines (G.I).		
	b) Sanitary Lines (PVC).		
	<ul> <li>Fixing of Bathroom Wall Tiles.</li> <li>Laying Of Floor Tiles <ul> <li>a) Ceramic Tiles in Bathroom</li> <li>b) Vitrified Tiles in Halls &amp; Bedrooms</li> <li>c) Vitrified Tiles in Corridor 100% completed.</li> </ul> </li> <li>Fixing of UPVC Windows.</li> <li>Fixing of UPVC French Door (without Mosquito mesh shutter) 100% completed.</li> <li>External Plastering in all sides.</li> <li>Water Proofing Works.</li> <li>a) Over Head Water Tank</li> </ul>		



	<ul> <li>Laying of Green marble for Staircase.</li> <li>Kitchen Finishing Works <ul> <li>a) Fixing of Wall Dados.</li> </ul> </li> </ul>	
	<ul><li>b) Laying of Granite Countertop.</li><li>Fixing of S.S Sink.</li></ul>	
	<ul> <li>Lift Cladding works 4 out of 4.</li> </ul>	
	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th NOVEMBER-2023
	<ul> <li>90% Completed Works</li> <li>Fixing of Staircase Hand Rails 3 out of 3</li> <li>Fixing of UPVC French Door (without</li> </ul>	<ul> <li>90% Completed Works</li> <li>Fixing of Staircase Hand Rails 3 out of 3</li> <li>Water Proofing Works.</li> </ul>
	<ul> <li>Mosquito mesh shutter) 235 / 240</li> <li>Laying Of Floor Tiles <ul> <li>a) Vitrified Tiles in Corridor.</li> </ul> </li> </ul>	<ul> <li>a) Terrace floor Water proofing.</li> <li>Lift Installation works 4 out 4.</li> <li>Application of Exterior Wall Primer</li> </ul>
	<ul> <li>Water Proofing Works.</li> <li>a) Terrace floor Water proofing.</li> <li>Lift Installation works 4 out 4.</li> </ul>	<ul> <li>Fixing of Door Shutters 95% completed (1035 / 1080).</li> </ul>
	<ul><li>Lift Cladding works 3 out of 4.</li><li>Application of Exterior Wall Primer</li></ul>	<ul> <li>Works On Progress</li> <li>Fixing of M.S Window Safety Grills 30% completed.</li> </ul>
	<ul> <li>Fixing of Door Shutters 90% completed (975 / 1080).</li> </ul>	<ul> <li>Electrical wire pulling work 30% completed (36/120).</li> </ul>
	<ul> <li>Works On Progress</li> <li>Fixing of M.S Window Safety Grills.</li> <li>Electrical wire pulling work.</li> </ul>	• <b>Model Flat</b> Finishing works 95% completed.
	<ul> <li>Lift Cladding work for 4<sup>th</sup> Lift 50% completed.</li> </ul>	
	• <b>Model Flat</b> Finishing works 95% completed.	
BLOCK	STATUS AS ON 30th NOVEMBER-2023	
	<ul> <li>100% Completed Works</li> <li>Terrace floor level slab R.C.C</li> <li>Terrace floor Parapet Columns Concrete.</li> </ul>	
C2 BLOCK	<ul> <li>Lift Head room (3 out of 4) - Slab Concrete.</li> <li>Over Head Water Tank <ul> <li>(a) Base Slab Concrete (2 out of 3)</li> <li>(b) Wall Concrete (2 out of 3)</li> </ul> </li> </ul>	
	<ul><li>(c) Top Cover slab (2 out of 3)</li><li>Block work upto Tenth floor &amp; Parapet</li></ul>	wall.



Progress Report No.60 (07.03.2017 - 30.11.2023)

Page 7

• Ceiling Plastering upto Tenth floor.	
<ul> <li>Wall plastering upto Tenth floor.</li> </ul>	
• 1 <sup>st</sup> Coat Wall Putty upto Tenth floor.	
■ 2 <sup>nd</sup> Coat Wall Putty upto Tenth floor.	
<ul> <li>Fixing of Internal Plumbing Line</li> </ul>	
a) Water supply pipe Lines (CPVC).	
b) Sanitary Lines (PVC)	
<ul> <li>Fixing of Vertical Plumbing Line in Sha</li> </ul>	afts
a) Water supply pipe Lines (G.I).	
b) Sanitary Lines (PVC).	
<ul> <li>External Plastering in all sides.</li> <li>Water Proofing Works.</li> <li>a) Over Head Water Tank 1 out of 3</li> </ul>	
<ul> <li>Fixing of Bathroom Wall Tiles complete</li> <li>Laying Of Floor Tiles</li> </ul>	
a) Ceramic Tiles in Bathroom completed.	
<ul><li>b) Vitrified Tiles in Halls &amp; Bedrooms completed.</li><li>c) Vitrified Tiles in Corridor completed.</li></ul>	
<ul> <li>Kitchen Finishing Works</li> </ul>	
<ul> <li>a) Fixing of Wall Dados 100% completed. (120 / 120)</li> <li>b) Laying of Granite Countertop 100% completed. (120 / 120).</li> <li>c) Fixing of S.S Sink 100% completed. (120 / 120).</li> </ul>	
STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th NOVEMBER-2023
<ul> <li>90% Completed Works</li> <li>2<sup>nd</sup> Coat Wall Putty 95% completed. (117/120)</li> <li>Fixing of Balcony Handrail.</li> <li>Fixing of Staircase Hand Rails</li> <li>Application of Exterior Wall Primer</li> <li>Laying Of Floor Tiles <ul> <li>a) Vitrified Tiles in Corridor.</li> </ul> </li> <li>Fixing of Main Door &amp; Internal Shutters 90% completed (965 / 1080)</li> <li>Lift Installation works 2 out 4 - 90% completed.</li> </ul>	<ul> <li>90% Completed Works</li> <li>Fixing of Balcony Handrail.</li> <li>Fixing of Staircase Hand Rails</li> <li>Application of Exterior Wall Primer</li> <li>Fixing of Main Door &amp; Internal Shutters 92% completed (998 / 1080)</li> <li>Lift Installation works 2 out 4 - 90% completed.</li> <li>Fixing of UPVC Window 96% completed. (578 / 600)</li> <li>Works On Progress</li> <li>Fixing of UPVC French Door (without</li> </ul>
<ul> <li>Works On Progress</li> <li>Fixing of UPVC Window 75% completed. (450 / 600)</li> </ul>	<ul> <li>Fixing of OPVC French Door (without Mosquito mesh shutter) 88% completed. (213 /240)</li> <li>Lift Installation works - 3<sup>rd</sup> Lift 75%</li> </ul>



	<ul> <li>Fixing of UPVC French Door (without Mosquito mesh shutter) 52% completed. (126 /240)</li> <li>Lift Installation works – 3<sup>rd</sup> Lift 70% completed.</li> <li>Water Proofing Works. <ul> <li>a) Terrace floor Water proofing 45% completed.</li> <li>b) Over Head Water Tank 2 out 3 work in progress.</li> </ul> </li> <li>Laying of Green marble for Staircase 60% completed.</li> <li>Lift Cladding work 40% completed.</li> </ul>	<ul> <li>completed.</li> <li>Water Proofing Works. <ul> <li>a) Terrace floor Water proofing 50% completed.</li> <li>b) Over Head Water Tank 2 out 3 work in progress.</li> </ul> </li> <li>Laying of Green marble for Staircase 70% completed.</li> <li>Lift Cladding work 70% completed.</li> </ul>
BLOCK	STATUS AS ON 30 <sup>th</sup>	NOVEMBER-2023
C3 BLOCK	<ul> <li>100% Completed Works</li> <li>Terrace floor level slab R.C.C</li> <li>Terrace floor Parapet Columns Concrete</li> <li>Lift Head room (4 out of 4) - Slab Conc</li> <li>Over Head Water Tank <ul> <li>(a) Base Slab Concrete (2 out of 3)</li> <li>Block work upto Tenth floor &amp; Parapet</li> <li>Ceiling Plastering upto Tenth floor.</li> <li>Wall plastering upto Tenth floor.</li> <li>Ist Coat Wall Putty upto Tenth floor.</li> <li>Fixing of Internal Plumbing Line <ul> <li>a) Water supply pipe Lines (CPVC).</li> <li>b) Sanitary Lines (PVC)</li> </ul> </li> <li>Fixing of Vertical Plumbing Line in Sha a) Water supply pipe Lines (G.I).</li> <li>b) Sanitary Lines (PVC).</li> <li>External Plastering in all sides.</li> </ul> </li> </ul>	rete. wall.
	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30 <sup>th</sup> NOVEMBER-2023
	<ul> <li>90% Completed Works</li> <li>Fixing of Balcony Handrail.</li> </ul>	<ul> <li>90% Completed Works</li> <li>Fixing of Balcony Handrail.</li> </ul>
	Fixing of Staircase Hand Rails.	<ul> <li>Fixing of Staircase Hand Rails.</li> </ul>
	<ul> <li>Application of Exterior Wall Primer</li> </ul>	<ul> <li>Application of Exterior Wall Primer</li> </ul>
	<ul> <li>♦ Works On Progress</li> <li>● 2<sup>nd</sup> Coat Wall Putty 34% completed.</li> </ul>	<ul> <li>Kitchen Finishing Works</li> <li>a) Fixing of Wall Dados 90%</li> </ul>



Progress Report No.60 (07.03.2017 - 30.11.2023)

Page 9

	<ul> <li>( 34 /100 ).</li> <li>Fixing of Bathroom Wall Tiles 43% completed. ( 131 /300 )</li> <li>Laying Of Floor Tiles <ul> <li>a) Ceramic Tiles in Bathroom 43% completed. ( 131 /300 )</li> <li>b) Vitrified Tiles in Halls &amp; Bedrooms 42% completed. ( 42 / 100 )</li> </ul> </li> <li>Fixing of UPVC Window 13% Completed.( 65 / 500 )</li> <li>Fixing of UPVC French Door (without Mosquito mesh shutter) 33% completed ( 66 / 200 )</li> <li>Fixing of Main Door &amp; Internal Shutters started ( 33 / 900 )</li> <li>Lift Installation works – Materials received 4 out 4.</li> <li>Kitchen Finishing Works <ul> <li>a) Laying of S.S Sink 25% completed. ( 25 / 100).</li> </ul> </li> </ul>	<ul> <li>completed (90/100)</li> <li>b) Laying of Granite Countertop 93% completed. (93/100).</li> <li>c) Fixing of S.S Sink 90% completed. (93/100).</li> <li><b>Works On Progress</b> <ul> <li>2<sup>nd</sup> Coat Wall Putty 63% completed. (63 /100).</li> </ul> </li> <li>Fixing of Bathroom Wall Tiles 72% completed. (216 /300)</li> <li>Laying Of Floor Tiles <ul> <li>a) Ceramic Tiles in Bathroom 72% completed. (216 /300)</li> <li>b) Vitrified Tiles in Halls &amp; Bedrooms 85% completed. (85 / 100)</li> </ul> </li> <li>Fixing of UPVC Window 13% Completed.(65 / 500)</li> <li>Fixing of UPVC French Door (without Mosquito mesh shutter) 34% completed (68 / 200)</li> <li>Fixing of Main Door &amp; Internal Shutters on progress (67 / 900)</li> <li>Lift Installation works – Materials received 4 out 4. Scaffolding works started.</li> <li>Lift Cladding work 20% completed.</li> <li>Water Proofing Works. a) Terrace floor Water proofing 20% completed.</li> </ul>
BLOCK	STATUS AS ON 30 <sup>th</sup>	*
D1 BLOCK	<ul> <li>100% Completed Works</li> <li>Terrace floor level slab R.C.C</li> <li>Terrace floor Parapet Columns Concrete.</li> <li>Lift Head room (4 out of 4) - Slab Concrete.</li> <li>Over Head Water Tank <ul> <li>(a) Base Slab Concrete (3 out of 3)</li> <li>(b) Wall Concrete (3 out of 3)</li> <li>(c) Top Cover slab (3 out of 3 )</li> </ul> </li> <li>Block work upto Tenth floor &amp; Parapet wall.</li> </ul>	
	• Ceiling Plastering upto Tenth floor.	



<b></b>	1	
	<ul> <li>Wall plastering upto Tenth floor.</li> </ul>	
	<ul> <li>1<sup>st</sup> Coat Wall Putty upto Tenth floor</li> </ul>	
	<ul> <li>Water Proofing Works.</li> </ul>	
	a) Over Head Water Tank 3 out	of 3
	<ul> <li>Fixing of Internal Plumbing Line</li> </ul>	
	a) Water supply pipe Lines (CP'	VC).
	b) Sanitary Lines (PVC)	
	<ul> <li>Fixing of Vertical Plumbing Line in Shafts</li> <li>a) Water supply pipe Lines (G.I).</li> <li>b) Sanitary Lines (PVC).</li> </ul>	
D1 BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th NOVEMBER-2023
	♦ 90% Completed Works	♦ 90% Completed Works
	Fixing of Balcony Handrail.	<ul> <li>Fixing of Balcony Handrail.</li> </ul>
	<ul> <li>External plastering in all sides 95% completed.</li> </ul>	<ul> <li>External plastering in all sides 95% completed.</li> </ul>
	<ul> <li>Application of External Wall Primer- 1<sup>st</sup> Coat</li> </ul>	<ul> <li>Application of External Wall Primer- 1<sup>st</sup> Coat</li> </ul>
	<ul> <li>♦ Works On Progress</li> </ul>	<ul><li>Fixing of Bathroom Wall Tiles 96%</li></ul>
	• 2 <sup>nd</sup> Coat Wall Putty 20% completed.	completed. ( 310 / 320 ).
	( 16 /80 ).	<ul> <li>Laying Of Floor Tiles</li> </ul>
	<ul> <li>Fixing of Bathroom Wall Tiles 70% completed. (225 / 320).</li> </ul>	a) Ceramic Tiles in Bathroom 96% completed. ( 310 / 320 )
	<ul> <li>Laying Of Floor Tiles</li> </ul>	• Vitrified Tiles in Halls & Bedrooms
	a) Ceramic Tiles in Bathroom 68%	93% completed. (75 / 80).
	completed. (220/320) b) Vitrified Tiles in Halls &	<ul> <li>Kitchen Finishing Works</li> <li>a) Fixing of Wall Dados 95%</li> </ul>
	b) Vitrified Tiles in Halls & Bedrooms 75% completed. ( 60 /	completed. ( 76 / 80 )
	80)	b) Laying of Granite Countertop 95%
	• Fixing of UPVC Windows 35% completed. (141 / 400).	completed. (76 / 80). c) Fixing of S.S Sink 92% completed.
	• Fixing of Main Door & Internal	( 74 / 80). ♦ Works On Progress
	Shutters 4% completed ( 40 / 880 )	• 2 <sup>nd</sup> Coat Wall Putty 30% completed.
	<ul> <li>Kitchen Finishing Works</li> </ul>	( 24 /80 ).
	a) Fixing of Wall Dados 56% completed. (45/80)	• Fixing of UPVC Windows 35%
	b) Laying of Granite Countertop 65%	completed. $(141 / 400)$ .
	completed. ( 52 / 80).	<ul> <li>Fixing of Main Door &amp; Internal Shutters 75% completed (662 / 880)</li> </ul>
	c) Fixing of S.S Sink 65% completed.	• Application of Exterior Wall Primer
	(52/80).	• Lift Installation works 2 out 4 - 70%
	<ul> <li>Application of Exterior Wall Primer</li> </ul>	



	Lift Installation works 2 out 4 - 65%	completed.	
	completed.	<ul> <li>Water Proofing Works.</li> </ul>	
	<ul> <li>Water Proofing Works.</li> </ul>	a) Terrace floor Water proofing	
	a) Terrace floor Water proofing 75% completed.	80% completed.	
BLOCK	STATUS AS ON 30th NOVEMBER-2023		
	<ul> <li>100% Completed Works</li> <li>Terrace floor level slab R.C.C</li> </ul>		
	<ul> <li>Terrace floor Parapet Columns Concrete.</li> </ul>		
	Lift Head room (3 out of 3) - Slab Concrete.		
	<ul> <li>Over Head Water Tank</li> <li>(a) Base Slab Concrete (3 out of 3)</li> </ul>		
	(b) Wall Concrete (3 out of 3)		
	(c) Top Cover slab (3 out of 3)		
	Block work upto Tenth floor & Parapet v	vall.	
	<ul> <li>Ceiling Plastering upto Tenth floor.</li> </ul>		
	• Wall plastering upto Tenth floor.		
	I <sup>st</sup> Coat Wall Putty upto Tenth floor.		
	■ 2 <sup>nd</sup> Coat Wall Putty upto Tenth floor.		
D2 BLOCK	<ul> <li>Fixing of Balcony Handrail.</li> </ul>		
	<ul> <li>Fixing of Staircase Hand Rails</li> </ul>		
	<ul> <li>Fixing of Internal Plumbing Line</li> </ul>		
	a) Water supply pipe Lines (CPVC).		
	b) Sanitary Lines (PVC)		
	<ul> <li>Fixing of Vertical Plumbing Line in Shafts</li> </ul>		
	a) Water supply pipe Lines (G.I).		
	b) Sanitary Lines (PVC).		
	<ul> <li>Fixing of Bathroom Wall Tiles.</li> </ul>		
	<ul> <li>Laying Of Floor Tiles</li> </ul>		
	a) Ceramic Tiles in Bathroom		
	b) Vitrified Tiles in Halls & Bedrooms.		
	c) Vitrified Tiles in Corridor.		
	<ul><li>Fixing of UPVC Windows.</li><li>Fixing of Main Door &amp; Internal Shutters.</li></ul>		
	<ul> <li>Fixing of Main Door &amp; Internal Shutters.</li> <li>Kitchen Finishing Works</li> </ul>		
	a) Fixing of Wall Dados.		
	<ul><li>a) Fixing of Wan Dados.</li><li>b) Laying of Granite Countertop.</li><li>c) Fixing of S.S Sink.</li></ul>		



	<ul> <li>External Plastering in all sides.</li> <li>Water Proofing Works. <ul> <li>a) Terrace floor Water proofing.</li> <li>b) Over Head Water Tank</li> </ul> </li> <li>Laying of Green marble for Staircase.</li> <li>Fixing of UPVC French Door (without Mosquito mesh shutter).</li> </ul>	
	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30 <sup>th</sup> NOVEMBER-2023
	<ul> <li>90% Completed Works</li> <li>Fixing of UPVC French Door (without Mosquito mesh shutter). (152 / 160)</li> <li>Lift Installation works 4 out 4.</li> <li>Lift Cladding works 4 out of 4.</li> <li>Application of Exterior Wall Primer.</li> <li>Works On Progress</li> <li>Fixing of M.S Window Safety Grills.</li> <li>Fire Fighting Works on progress.</li> <li>Wire pulling works on progress.</li> <li>Model Flat Finishing works 95% completed.</li> </ul>	<ul> <li>90% Completed Works</li> <li>Lift Installation works 4 out 4.</li> <li>Lift Cladding works 4 out of 4.</li> <li>Application of Exterior Wall Primer</li> <li>Works On Progress</li> <li>Fixing of M.S Window Safety Grills 47% completed. (152 / 320).</li> <li>Fire Fighting Works 50% completed.</li> <li>Wire pulling works on progress.</li> <li>Model Flat Finishing works 95% completed.</li> </ul>
BLOCK	STATUS AS ON 30 <sup>th</sup> NOVEMBER-2023	
	◆ 100% Completed Works	
D3 BLOCK	<ul> <li>100% Completed Works</li> <li>Terrace floor level slab R.C.C</li> <li>Terrace floor Parapet Columns Concrete.</li> <li>Lift Head room (4 out of 4) - Slab Concrete.</li> <li>Over Head Water Tank <ul> <li>(a) Base Slab Concrete (3 out of 3)</li> <li>(b) Wall Concrete (3 out of 3)</li> <li>(c) Top Cover slab (3 out of 3)</li> </ul> </li> <li>Block work upto Tenth floor &amp; Parapet wall.</li> <li>Ceiling Plastering upto Tenth floor.</li> <li>Wall plastering upto Tenth floor.</li> <li>1<sup>st</sup> Coat Wall Putty upto Tenth floor.</li> <li>Fixing of Balcony Handrail.</li> <li>Fixing of Staircase Hand Rails</li> <li>Fixing of Internal Plumbing Line <ul> <li>a) Water supply pipe Lines (CPVC).</li> <li>b) Sanitary Lines (PVC)</li> </ul> </li> </ul>	



		<u> </u>			
	<ul> <li>Fixing of Vertical Plumbing Line in Shafts</li> </ul>				
	a) Water supply pipe Lines (G.I).				
	b) Sanitary Lines (PVC).				
	<ul> <li>External Plastering in all sides.</li> </ul>				
	<ul> <li>Water Proofing Works.</li> </ul>				
	a) Over Head Water Tank 1 out of 3				
	<ul> <li>Fixing of Bathroom Wall Tiles 100% completed. ( 320 / 320 )</li> </ul>				
	<ul> <li>Kitchen Finishing Works</li> <li>Eising of Well Dedag 100% completed (20 (20))</li> </ul>				
	a) Fixing of Wall Dados 100% completed. (80/80)				
	b) Laying of Granite Countertop 100% completed. (80/80).				
	<ul> <li>Fixing of S.S Sink 100% completed. ( 80 / 80).</li> </ul>				
	<ul> <li>Laying Of Floor Tiles</li> <li>a) Ceramic Tiles in Bathroom 100% completed. (320 / 320)</li> </ul>				
		-			
D3 BLOCK	<ul> <li>Fixing of Main Door &amp; Internal Shutter</li> </ul>	_			
DS BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30 <sup>th</sup> NOVEMBER-2023			
	◆ 90% Completed Works	◆ 90% Completed Works			
	■ 2 <sup>nd</sup> Coat Wall Putty upto Tenth floor.	• 2 <sup>nd</sup> Coat Wall Putty upto Tenth floor.			
	• Laying Of Floor Tiles	<ul> <li>Laying Of Floor Tiles</li> <li>a) Vitrified Tiles in Halls &amp;</li> </ul>			
	a) Ceramic Tiles in Bathroom 95% completed. (310 / 320)	a) Vitrified Tiles in Halls & Bedrooms. (72 / 80)			
	b) Vitrified Tiles in Halls &	b) Vitrified Tiles in Corridor.			
	Bedrooms. (70/80)	• Fixing of UPVC Windows 96%			
	c) Vitrified Tiles in Corridor. completed. (387/400)				
	• Fixing of UPVC Windows 96%	• Fixing of UPVC French Door (without			
	<ul><li>completed. (387 / 400)</li><li>Fixing of UPVC French Door (without</li></ul>	Mosquito mesh shutter) 99% completed (159/160).			
	Mosquito mesh shutter) 93% completed (	<ul><li>Laying of Green marble for Staircase.</li></ul>			
	150 / 160).	<ul><li>Lift Cladding works 90% completed.</li></ul>			
	<ul> <li>Laying of Green marble for Staircase.</li> </ul>	<ul> <li>Application of Exterior Wall Primer</li> </ul>			
	<ul> <li>Lift Cladding works 90% completed.</li> </ul>	<ul> <li>Water Proofing Works.</li> </ul>			
	<ul> <li>Application of Exterior Wall Primer</li> </ul>	a) Terrace floor Water proofing 90%			
	♦ Works On Progress	completed.			
	• Fixing of Main Door & Internal	b) Over Head Water Tank 3 out of 3			
	Shutters 80% completed ( 720 / 880 )	completed. ♦ Works On Progress			
	Lift Installation works - 3 out of 4 -	• Lift Installation works - 3 out of 4 -			
	80% completed & 4 <sup>th</sup> Lift 60%	80% completed & 4 <sup>th</sup> Lift 65%			
	completed.	completed.			
	• Water Proofing Works.	• Fixing of M.S Window Safety Grills			
	a) Terrace floor Water proofing 85% completed.	18% completed (60/320).			
	compicieu.				



	b) Over Head Water Tank 2 out 3 work in progress	<ul> <li>Fire Fighting works on progress.</li> </ul>			
	<ul> <li>Fixing of M.S Window Safety Grills.</li> </ul>				
	<ul> <li>Fire Fighting works on progress.</li> </ul>				
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30 <sup>th</sup> NOVEMBER-2023			
<b>BLOCK</b>	<ul> <li>100% Completed Works</li> <li>Terrace floor level slab R.C.C</li> <li>Terrace floor Parapet Columns Concrete</li> <li>Lift Head room (2 out of 2) - Slab Conc</li> <li>Over Head Water Tank <ul> <li>(a) Base Slab Concrete</li> <li>(b) Tank Wall Concrete</li> <li>(c) Top Cover slab Concrete.</li> </ul> </li> <li>Block work upto Fourth floor &amp; Parapet</li> <li>Ceiling Plastering upto Fourth floor.</li> <li>Uall plastering upto Fourth floor.</li> <li>1<sup>st</sup> Coat Wall Putty upto Fourth floor.</li> <li>2<sup>nd</sup> Coat Wall Putty upto Fourth floor.</li> <li>Fixing of Balcony Handrail.</li> <li>Fixing of Staircase Hand Rails</li> <li>Fixing of Internal Plumbing Line <ul> <li>Water supply pipe Lines (CPVC).</li> <li>Sanitary Lines (PVC)</li> </ul> </li> <li>Fixing of Bathroom Wall Tiles.</li> <li>Laying Of Floor Tiles <ul> <li>Vitrified Floor Tiles in Hall &amp; rooms</li> </ul> </li> </ul>	e. rete. t wall.			
	<ul> <li>a) Vitrified Floor Tiles in Hall &amp; rooms</li> <li>b) Ceramic Floor Tiles in Bathrooms.</li> <li>c) Kota Stone in Staircase &amp; Lobby</li> <li>Fixing of UPVC Windows.</li> </ul>				
	<ul> <li>Fixing of Wooden flush Door for rooms.</li> </ul>				
	<ul> <li>Fixing of Fire Safety Door for Hall Main Entrance</li> </ul>				
	<ul> <li>External Plastering in all sides.</li> </ul>				
	• Water Proofing Works.				
	a) Terrace floor Water proofing.				



<b>b</b> ) Over Head Water Tank.			
STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th NOVEMBER-2023		
<ul> <li>90% Completed Works</li> <li>Lift Installation works 4 out 4.</li> <li>Lift Cladding works 4 out of 4.</li> <li>Application of Exterior Wall Primer.</li> </ul>	<ul> <li>90% Completed Works</li> <li>Lift Installation works 4 out 4.</li> <li>Lift Cladding works 4 out of 4.</li> <li>Application of Exterior Wall Primer.</li> </ul>		
<ul> <li>Works On Progress</li> <li>Fire Fighting works – Installation of Pipelines 75% completed.</li> <li>Electrical Wire &amp; cables pulling work</li> </ul>	Pipelines 80% completed.		
<ul> <li>Electrical Wire &amp; cables pulling work 70% completed.</li> <li>Fixing of Sanitary fixtures.</li> </ul>	<ul> <li>Electrical Wire &amp; cables pulling work 75% completed.</li> <li>Fixing of Sanitary fixtures.</li> </ul>		

	STATUS AS ON 30th NOVEMBER-2023		
	Underground Sump-1 (Near D-Block)		
	Structure Work.		
	◆ Completed		
	Base Slab - R.C.C 100% completed.		
	■ Sump Wall - R.C.C 100% completed.		
	■ Top slab R.C.C 100% completed.		
	<ul> <li>Outer Wall Waterproof plastering – 100% completed.</li> </ul>		
	On Progress		
	<ul> <li>Inner Wall Waterproof plastering started.</li> </ul>		
	<ul> <li>Pump room Inner plastering works.</li> </ul>		
EXTERNAL	Underground Sump-2 (Near B-Block)		
DEVELOPMENT	Structure Work.		
WORKS	◆ Completed		
	• P.C.C for Base Slab 100% completed.		
	Base Slab R.C.C 95% completed.		
	■ Sump Wall - R.C.C 85% completed.		
	♦ On Progress		
	Sump Wall Reinforcement and Shuttering for balance on progress		
	<ul> <li>Shuttering work for Top slab of Sump on progress</li> </ul>		
	Sewage Treatment Plant-1 (Near D-Block)		
	Structure Work		
	■ Base slab – R.C.C 100% completed.		
	■ STP Wall – R.C.C 100% completed.		
	■ STP Top Slab – R.C.C 100% completed.		



#### PHOTOGRAPHS OF WORK PROGRESS AS ON 30th NOVEMBER 2023

<u>**Community Hall</u></u> : Fire Fighting Works – Installation of Pipeline 80% completed. Electrical Wire pulling work 75% completed.</u>** 







**<u>Block A1:</u>** Vertical Plumbing works 60% completed. Laying of floor Tiles on progress.



**<u>Block A2</u>**: Over Head Water Tank R.C.C works completed. Fixing of Internal sanitary lines 60% completed. Vertical plumbing works in shafts started.





**Block B1:** Electrical Wire pulling works 30% completed. Fixing of Window Safety Grills 40% completed.






**Block B2 :** Eighth Floor Level slab  $1^{st}$  half concrete casting 100% completed. Shuttering & Barbending works for  $2^{nd}$  half of Eighth floor level slab 60% completed. Shuttering works for  $1^{st}$  half of Ninth floor level slab 20% completed.





**Block C1:** Fixing of Door Shutters 95% completed. Fixing of Window Safety Grills & Electrical Wire pulling works 30% completed.







Block C2: Fixing of UPVC Windows 96% completed. Staircase Green marble laying 70% completed.



**Block C3:** Fixing of Bathroom wall tiles & laying of bathroom floor tiles 72% compled. Laying of Vitrified Tiles 85% completed.






**Block D1:** Fixing of UPVC Windows 35% completed. Fixing of Bathroom wall tiles & laying of bathroom floor tiles 96% compled. Laying of Vitrified Tiles 93% completed.






Block D2: Fire Fighting works 50% completed. Fixing of M.S Safety Grill for windows 47% completed.





**Block D3:** Fixing of UPVC Windows 96% completed. Laying of Bathroom Floor Tiles 100% completed & Vitrified Tiles 90% completed.





**Sewage Treatment Plant 1 (Near D Block)** – Base Slab RCC completed. Wall Concrete & Top Slab 100% completed.



U.G Sump 1 (Near D Block) – Base Slab RCC 95% completed. Sump wall & Top Slab Concrete 100% completed.





**U.G Sump 2** – Base Slab RCC 95% completed. Sump wall Concrete 85% completed. Shutering works for Top Slab on progress.





#### **QUALITY CONTROL**

#### **DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS CONDUCTED AT** <u>SITE:</u>

Sl.No.	Materials	Source from	Test Done	Result
1	M-Sand	Arcot (T.K), Ranipet (Dist) Walajabad(T.K), Kanchipuran (Dt)	Each Truck	Sieve Analysis & Silt content
2.	P- Sand	Uthiramerur, Kanchipuram (DT) Walajabad(T.K), Kanchipuran (Dt)	Each Truck	Sieve Analysis & Silt content
2	Coarse Aggregate (20mm)	Sriperambathur, Kanchipuran (Dt), Vellore Dt & Chitoor Dt.	Each Truck	Sieve Analysis
3	Coarse Aggregate (12mm)	Sriperambathur, Kanchipuran (Dt) Vellore Dt & Chitoor Dt.	Each Truck	Sieve Analysis
4	Cement	Third party testing is being done.		
5	Steel	Third party testing is being done.		
6	Pile Integrity	Third party testing is being done.		
7	Soil Compaction	Third party testing is being done.		
8	RCC cubes are being tested and Register is being maintained.			
9	Slump test conducted at site to insure workability of concrete.			



#### PHOTOGRAPH OF QUALITY CONTROL AT SITE

## **Concrete Cube Compressive Strength Testing**





# 20mm & 12mm Aggregate Sieve Analysis Testing





## **Fine Aggregate Sieve Analysis Testing**



