CGEWHO – CHENNAI PHASE-III PROJECT



PROGRESS REPORT

STATUS AS ON: 31.10.2022



31.10.2022

BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 31st OCTOBER - 2022		
A1 BLOCK	 Structure Work. Completed Sixth floor level slab – 1st Half R.C.C 100% completed. Sixth floor Columns Concrete 20% completed. On Progress Shuttering works for 1st half of Seventh floor level slab 10% completed and balance works on progress. Internal Finishing Work. Block Work Upto Second floor 95% completed. Fourth floor 75% completed. Fourth floor 50% completed. Ceiling Plastering Stilt floor 50% completed. Second floor 80% completed. Wall Plastering First floor 90% completed. Second floor 10% completed. Model Flat Finishing works 90% completed. Model Flat Finishing works 90% completed. 	 Structure Work. Completed Sixth floor level slab – 1st Half R.C.C 100% completed. Sixth floor Columns Concrete 60% completed. On Progress Shuttering works 6th floor level slab – 2nd half – 90% completed. 7th floor level slab – 1st half – 15% completed. Internal Finishing Work. Block Work Upto Second floor 95% completed. Third floor 80% completed. Fourth floor 60% completed. First floor 95% completed. Second floor 85% completed. Third floor 80% completed. Third floor 80% completed. Wall Plastering First floor 95% completed. Second floor 40% completed. Model Flat Finishing works 90% completed.		



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 31st OCTOBER - 2022	
	 Structure Work. Completed Fifth floor level slab – 1st Half R.C.C 100% completed. Fifth floor Columns Concrete 50% completed. 	 Structure Work. Completed Upto Fifth floor level slab − R.C.C 100% completed. Fifth floor Columns Concrete 50% completed. Sixth floor level slab − 1st Half R.C.C 100% completed. 	
	 On Progress Shuttering & Barbending works for 2nd half of Fifth floor level slab 50% completed and balance works on progress. Shuttering & Barbending works for 1st half of Sixth floor on progress. 	◆ On Progress • Shuttering & Barbending work for 5 th floor columns or progress	
A2 BLOCK	 Internal Finishing Work. Block Work First floor 95% completed. Second floor 95% completed. Third floor 75% completed. 	 Internal Finishing Work. Block Work First floor 95% completed. Second floor 95% completed. Third floor 90% completed. Fourth floor 15% completed. 	
	 Ceiling Plastering Stilt floor 65% completed. First floor 95% completed. Second floor 90% completed. Wall Plastering First floor 95% completed. Second floor 25% completed. 	 Ceiling Plastering Stilt floor 65% completed. First floor 95% completed. Second floor 95% completed. Wall Plastering First floor 95% completed. Second floor 50% completed. 	



BLOCK STATUS UPTO PREVIO MONTH		STATUS AS ON 31st OCTOBER - 2022	
	 Structure Work. Completed Upto Terrace floor level slab- R.C.C 100% completed. 	 Structure Work. Completed Upto Terrace floor level slab- R.C.C 100% completed. 	
	■ Terrace floor Parapet Columns Concrete 100% completed.	Terrace floor Parapet Columns Concrete 100% completed.	
	 Lift Head room (3 out of 3) - Base Slab Concrete 100% completed 	 Lift Head room (3 out of 3) - Base Slab Concrete 100% completed 	
B1 BLOCK	 Over Head Water Tank (a) Base Slab Concrete (2 out of 3) - 100% completed. (b) Wall Concrete (1 out of 3) - 100% completed. ◆ On Progress Shuttering & Barbending works for Base slab of Over Head Water Tank (3rd) on progress. 	 Over Head Water Tank (a) Base Slab Concrete (2 out of 3) 100% completed. (b) Wall Concrete (2 out of 3) - 100% completed. ◆ On Progress Shuttering & Barbending works for Base slab of Over Head Water Tank (3rd) 50% completed. 	
	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Terrace floor Parapet wall 100% completed. 	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Terrace floor Parapet wall 100% completed. 	
	 ◆ Ceiling Plastering ■ Stilt floor 80% completed. ■ First floor to Seventh floor 90% completed. ■ Eighth floor 85% completed. ■ Ninth floor 85% completed. ■ Tenth floor 85% completed. 	 Ceiling Plastering Stilt floor 80% completed. First floor to Seventh floor 95% completed. Eighth floor 90% completed. Ninth floor 90% completed. Tenth floor 90% completed. 	
[◆ Wall Plastering ■ First floor to Sixth floor 90%	◆ Wall Plastering ■ First floor to Sixth floor 95%	



	completed. Seventh floor 85% completed. Eighth floor 85% completed. Ninth floor 85% completed. Tenth floor 85% completed. Fixing of Balcony Rails	completed. Seventh floor 90% completed. Eighth floor 90% completed. Ninth floor 90% completed. Tenth floor 90% completed. Fixing of Balcony Rails	
	Balcony railing work 25% Balcony railing wo completed.		
	 External Finishing Works External Plastering In South Side Elevation 100% completed. In East Side Elevation 20% completed. In West Side Elevation 10% 	 External Finishing Works External Plastering In South Side Elevation 100% completed. In East Side Elevation 40% completed. 	
	completed.	 In West Side Elevation 25% completed. In South Side Elevation 10% completed. 	
	• Model Flat Finishing works 90% completed.	Model Flat Finishing works 90% completed.	
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 31st OCTOBER - 2022	
	Structure Work.	Structure Work.	
	♦ Completed	♦ Completed	
	■ Upto Third floor level slab – R.C.C 100% completed.	■Upto Third floor level slab – R.C.C 100% completed.	
	■ Third floor Columns Concrete 80% completed.	■ Third floor Columns Concrete 80% completed.	
B2 BLOCK	◆ On Progress • Shuttering works for 1 st half of Fourth floor level slab 15% completed and balance works on progress.	◆ On Progress • Shuttering works for 1 st half of Fourth floor level slab 15% completed and balance works on progress.	
	• Internal Finishing Work.	• Internal Finishing Work.	
	◆ Block Work • First floor 50% completed.	◆ Block Work • First floor 50% completed.	



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 31st OCTOBER - 2022	
	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (4 out of 4) - Base Slab Concrete 100% completed On Progress Shuttering works for Over Head Tank Base slab on progress. 	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (4 out of 4) - Base Slab Concrete 100% completed On Progress Shuttering & Reinforcement works for Over Head Tank Base 	
C1 BLOCK	 Internal Finishing Work. Block Work Upto Ninth floor 95% completed. Tenth floor 80% completed. Terrace Parapet Wall 80% completed. 	 Internal Finishing Work. Block Work Upto Ninth floor 95% completed. Tenth floor 95% completed. Terrace Parapet Wall 90% completed. 	
	 ◆ Ceiling Plastering ■ Stilt floor 90% completed. ■ First floor to Sixth floor 95% completed. ■ Seventh floor 90% completed. ■ Eighth floor 80% completed. 	 Ceiling Plastering Stilt floor 90% completed. First floor to Ninth floor 95% completed. Tenth floor 30% completed. 	
	 ◆ Wall Plastering ■ First floor to Fifth floor 95% completed. ■ Sixth floor 90% completed. ■ Seventh floor 70% completed. ■ Eighth floor 10% completed. 	 Wall Plastering First floor to Fifth floor 95% completed. Sixth floor 95% completed. Seventh floor 90% completed. Eighth floor 70% completed. Ninth floor 20% completed. Tenth floor 20% completed. 	



	 External Finishing Works External Plastering In North Side Elevation 50% completed. Model Flat Finishing works 90% completed. 	 External Finishing Works External Plastering In North Side Elevation 75% completed. In West Side Elevation 10% completed. Model Flat Finishing works 90% completed. 		
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 31st OCTOBER - 2022		
C2 BLOCK	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. Terrace floor Parapet Columns Concrete 90% completed. On Progress Shuttering works for Lift Base slab on progress. Internal Finishing Work. Block Work Upto Seventh floor 95% completed. Eighth floor 65% completed. Ninth floor 30% completed. 	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. Terrace floor Parapet Columns Concrete 90% completed. On Progress Shuttering & Reinforcement works for Lift Base slab on progress. Internal Finishing Work. Block Work Upto Seventh floor 95% completed. Eighth floor 85% completed. Ninth floor 40% completed. Tenth floor 10% completed. 		
	 ◆ Ceiling Plastering ■ Stilt floor 90% completed. ■ First floor to Sixth floor 95% completed. ■ Seventh floor 90% completed. 	 Ceiling Plastering Stilt floor 90% completed. First floor to Seventh floor 95% completed. 		
	◆ Wall Plastering ■ Upto Fourth floor 95% completed.	◆ Wall Plastering • Upto Fifth floor 95% completed.		



	Fifth floor 90% completed.	Sixth floor 90% completed.		
	Sixth floor 90% completed.	Seventh floor 70% completed.		
	Seventh floor 20% completed.			
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 31st OCTOBER - 2022		
	 Structure Work. Completed Upto Seventh Floor level slab – R.C.C 100% completed. Seventh floor Columns Concrete 100% completed. 	 Structure Work. Completed Upto Seventh Floor level slab – R.C.C 100% completed. Seventh floor Columns Concrete 100% completed. Eighth floor level slab – 1st Half R.C.C 100% completed. 		
	◆ On Progress Shuttering works & Barbending works for Full slab of Eighth floor level slab 60% completed and balance works on progress.	 ◆ On Progress ■ 8th Floor – 2nd half: (a) Shuttering works – 95% completed. (b) Reinforcement works – 20% completed. 		
	• Internal Finishing Work.	Internal Finishing Work.		
C3 BLOCK	 Block Work First floor 95% completed. Second floor 90% completed. Third floor 90% completed. Fourth floor 80% completed. Fifth floor 50% completed. 	 ◆ Block Work ■ First floor 95% completed. ■ Second floor 90% completed. ■ Third floor 90% completed. ■ Fourth floor 80% completed. ■ Fifth floor 75% completed. ■ Sixth floor 10% completed. 		
	 Ceiling Plastering Stilt floor 90% completed. First floor 95% completed. Second floor 95% completed. Third floor 95% completed. Fourth floor 25% completed. 	 ◆ Ceiling Plastering ■ Stilt floor 90% completed. ■ First floor 95% completed. ■ Second floor 95% completed. ■ Third floor 95% completed. ■ Fourth floor 70% completed. 		
	 ◆ Wall Plastering ■ First floor 95% completed. ■ Second floor 15% completed. 	 ◆ Wall Plastering ■ First floor 95% completed. ■ Second floor 15% completed 		



		■ Third floor 20% completed.		
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 31st OCTOBER - 2022		
	 Structure Work. Completed Upto Eighth floor level slab – R.C.C 100% completed. Eighth floor Columns Concrete 100% completed. Ninth floor level slab – 1st Half R.C.C 100% completed. 	 Structure Work. Completed Upto Ninth floor level slab – R.C.C 100% completed. Ninth floor Columns Concrete 50% completed. 		
	◆ On Progress Shuttering works for 2 nd half of Ninth floor level slab 15% completed and barbending works on progress.	◆ On Progress Shuttering works for 1 st half of Tenth floor level slab 10% completed and barbending works on progress.		
D1 BLOCK	 Internal Finishing Work. Block Work First floor to Fifth floor 95% completed. Sixth floor 90% completed. Seventh floor 20% completed. Ceiling Plastering First floor 95% completed. Second floor 95% completed. 	 Internal Finishing Work. Block Work First floor to Fifth floor 95% completed. Sixth floor 90% completed. Seventh floor 50% completed. Ceiling Plastering First floor 95% completed. Second floor 95% completed. Third floor 25% completed. Fourth floor 90% completed. 		
	 ◆ Wall Plastering ■ First floor 95% completed. ■ Second floor 45% completed. 	 Wall Plastering First floor 95% completed. Second floor 90% completed. Third floor 25% completed. 		



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 31st OCTOBER - 2022
	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (4 out of 4)-Base Slab Concrete 100% completed. Over Head Water Tank (a) Base Slab Concrete (2 out of 3) - 100% completed. 	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (4 out of 4)-Base Slab Concrete 100% completed. Over Head Water Tank (a) Base Slab Concrete (2 out of 3) - 100% completed. (b) Wall concrete (1 out of 3) – 100% completed.
D2 BLOCK	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Terrace floor Parapet wall 95% completed. 	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Terrace floor Parapet wall 95% completed.
	 Ceiling Plastering Stilt floor 80% completed. First floor to Eighth floor 95% completed. Ninth floor 90% completed. Tenth floor 90% completed. 	 Ceiling Plastering Stilt floor 80% completed. First floor to Eighth floor 95% completed. Ninth floor 90% completed. Tenth floor 90% completed.
	 ◆ Wall Plastering ■ First floor to Fifth floor 90% completed. ■ Sixth floor 70% completed. ■ Seventh floor 90% completed. ■ Eighth floor 90% completed. 	 Wall Plastering First floor to Eighth floor 95% completed. Ninth floor 90% completed. Tenth floor 90% completed.



	 Ninth floor 70% completed. Tenth floor 60% completed. External Finishing Works External Plastering In West Side Elevation 75% completed. 	 External Finishing Works External Plastering In West Side Elevation 100% completed. In North Side Elevation 10% completed. In South Side Elevation 10% completed. 		
	• Model Flat Finishing works 90% completed.	Model Flat Finishing works 90% completed.		
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 31st OCTOBER - 2022		
	 Structure Work. Completed Upto Tenth floor level slab – R.C.C 100% completed Tenth floor Columns Concrete 100% completed. Terrace slab level slab – 1st Half R.C.C 100% completed. 	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed Terrace floor Parapet Columns Concrete 50% completed. Lift Head room (1 out of 4)-Base Slab Concrete 100% 		
D3 BLOCK	◆ On Progress Shuttering & Barbending works for 2 nd half of Terrace floor level slab on progress.	 completed. On Progress Shuttering & Barbending works for balance Parapet columns on progress. 		
	 Internal Finishing Work. Block Work Upto Eighth floor 95% completed. Ninth floor 85% completed. 	 Internal Finishing Work. Block Work Upto Eighth floor 95% completed. Ninth floor 90% completed. Tenth floor 20% completed. 		
	◆ Ceiling Plastering ■ Stilt floor 85% completed.	◆ Ceiling Plastering • Stilt floor 85% completed.		



	 ■ First floor to Fourth floor 95% completed. ■ Fifth floor 85% completed. ■ Sixth floor 85% completed. ◆ Wall Plastering ■ First floor to Third floor 95% completed. ■ Fourth floor 75% completed. ■ Fifth floor 25% completed 	 First floor to Sixth floor 95% completed. Seventh floor 90% completed. Eighth floor 90% completed. Wall Plastering First floor to Third floor 95% completed. Fourth floor 90% completed. Fifth floor 60% completed. Sixth floor 60% completed. Eighth floor 50% completed. 		
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 31 st OCTOBER - 2022		
COMMUNITY HALL	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (2 out of 2) – Base slab Concrete 100% completed. Over Head Water Tank (a) Base slab concrete completed. (b) Tank Wall concrete completed. 	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (2 out of 2) – Base slab Concrete 100% completed. Over Head Water Tank (c) Base slab concrete completed. (d) Tank Wall concrete completed. 		
	 Internal Finishing Work. Block Work First floor 95% completed. Second floor 95% completed. Third floor 95% completed. Fourth floor 95% completed. Ceiling Plastering Stilt floor 90% completed. First floor 95% completed. Second floor 95% completed. 	 Internal Finishing Work. Block Work First floor 95% completed. Second floor 95% completed. Third floor 95% completed. Fourth floor 95% completed. Ceiling Plastering Stilt floor 90% completed. First floor 95% completed. Second floor 95% completed. 		



- Third floor 90% completed.
- Fourth floor 75% completed.

♦ Wall Plastering

- First floor 95% completed.
- Second floor 95% completed.
- Third floor 90% completed.
- Fourth floor 70% completed.

♦ Ceiling Putty work

- First floor 95% completed.
- Second floor 90% completed.

♦ Wall Putty work

- First floor 95% completed.
- Second floor 90% completed.

♦ Wall Painting work

• First floor - 1st Coat painting 95% completed.

♦ Floor Tiling Work

- First floor Vitrified Tile laying 95% completed.
- Second floor Vitrified Tile laying 10% completed.

♦ UPVC Window Fixing Work

• First floor UPVC Window fixing 95% completed.

• External Finishing Work.

- ♦ External Plastering
 - West Side elevation 95% completed.
 - South Side elevation 90% completed.
 - North Side elevation 70% completed.
 East Side elevation 60% completed.

- Third floor 95% completed.
- Fourth floor 85% completed.

♦ Wall Plastering

- First floor 95% completed.
- Second floor 95% completed.
- Third floor 90% completed.
- Fourth floor 80% completed.

♦ Ceiling Putty work

- First floor 95% completed.
- Second floor 90% completed.

♦ Wall Putty work

- First floor 95% completed.
- Second floor 90% completed.

♦ Wall Painting work

• First floor - 1st Coat painting 95% completed.

♦ Floor Tiling Work

- First floor Vitrified Tile laying 95% completed.
- Second floor Vitrified Tile laying 85% completed.

♦ Fixing of UPVC Windows

- First floor UPVC Window fixing 95% completed.
- Second floor UPVC Window fixing 85% completed.
- Third floor UPVC Window fixing 50% completed

• External Finishing Work.

- ♦ External Plastering
 - West Side elevation 95% completed.
 - South Side elevation 90% completed.
 - North Side elevation 90% completed.
 East Side elevation 90% completed.



PHOTOGRAPHS OF WORK PROGRESS AS ON 31st OCTOBER 2022


Block A1: Sixth Floor Level slab 1st Half Concrete casting 100% completed. Sixth floor columns 60% completed.



Block A2: Sixth Floor Level slab 1st half concrete casting 100% completed.



Block B1: External plastering work –South Side elevation 100% completed, East side elevation 40% completed, West side elevation 25% completed, South side elevation 10% completed.



Block B2: Third Floor Level slab concrete casting 100% completed. Shuttering works for 1st half of Fourth floor level slab 15% completed.



Block C1: Terrace Floor level slab concrete 100% completed. External Plastering in North Side elevation 75% completed, West Side elevation 10% completed.



Block C2: Terrace floor level slab 100% completed. Shuttering & Reinforcement for Lift Base slab on progress



Block C3: Eighth Floor level slab 1st half Concrete casting 100% completed. Shuttering works for 2nd half of Eighth floor level slab 95% completed and balance works on progress.



Block D1: Ninth Floor level slab Concrete casting 100% completed. Shuttering works for 1st half of Tenth floor level slab 10% completed.



Block D2: Terrace Parapet Columns concrete 100% completed. External Plastering work in West side elevation 100% completed, North side & South side elevation 10% completed.



Block D3: Terrace Floor level slab Concrete casting 100% completed. Parapet columns concrete 50% completed.



Community Hall: External Plastering in West side elevation 95% completed, South side elevation 90% completed & North side elevation 90%, East side elevation 90% completed. Over Head Water Tank Concrete completed.



QUALITY CONTROL

<u>DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS CONDUCTED</u> <u>AT SITE:</u>

Sl.No.	Materials	Source from	Test Done	Result
1	M-Sand	Arcot (T.K), Ranipet (Dist) Walajabad(T.K), Kanchipuran (Dt)	Each Truck	Sieve Analysis & Silt content
2.	P- Sand	Uthiramerur, Kanchipuram (DT) Walajabad(T.K), Kanchipuran (Dt)	Each Truck	Sieve Analysis & Silt content
2	Coarse Aggregate (20mm)	Sriperambathur, Kanchipuran (Dt), Vellore Dt & Chitoor Dt.	Each Truck	Sieve Analysis
3	Coarse Aggregate (12mm)	Sriperambathur, Kanchipuran (Dt) Vellore Dt & Chitoor Dt.	Each Truck	Sieve Analysis
4	Cement	Third party testing i	s being done.	
5	Steel	Third party testing i	s being done.	
6	Pile Integrity	Third party testing is being done.		
7	Soil Compaction	Third party testing is being done.		
8	RCC cubes are being tested and Register is being maintained.			
9	Slump test conducted at site to insure workability of concrete.			



PHOTOGRAPH OF QUALITY CONTROL AT SITE

Concrete Cube Compressive Strength Testing



20mm & 12mm Aggregate Sieve Analysis Testing



Fine Aggregate Sieve Analysis Testing

