



28.02.2023

		20.02.2025
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 28th FEBRUARY -2023
A1 BLOCK	 Structure Work. Completed Upto Seventh floor level slab R.C.C 100% completed. Seventh floor Columns Concrete 100% completed. Eighth floor level slab – 1st Half R.C.C 100% completed. Eighth floor Columns Concrete 45% completed. 6 On Progress 8th floor level slab – 2nd half Shuttering & barbending works 60% completed. Internal Finishing Work. Block Work Upto Third floor 95% completed. Fourth floor 20% completed. Sixth floor 50% completed. Sixth floor 50% completed. Upto Tolw floor 95% completed. Fifth floor 50% completed. Sixth floor 20% completed. Upto Fourth floor 95% completed. Fifth floor 20% completed. Wall Plastering First floor 95% completed. Second floor to Fourth floor 80% completed. Firth floor 20% completed. First floor 95% completed. Second floor to Fourth floor 80% completed. Firth floor 20% completed. Second floor to Fourth floor 80% completed. Second floor to Fourth floor 80% completed. Firth floor 20% completed. Model Flat Finishing works 90% completed. 	 Structure Work. Completed Upto Eighth floor level slab R.C.C 100% completed. Eighth floor Columns Concrete 50% completed. On Progress 9th floor level slab – 1st half Shuttering & barbending works 45% completed. Internal Finishing Work. Block Work Upto Third floor 95% completed. Fourth floor 85% completed. Fifth floor 75% completed. Sixth floor 50% completed. Sixth floor 50% completed. Stilt floor 50% completed. Upto Fourth floor 95% completed. Fifth floor 50% completed. Blocy completed. Second floor to Fourth floor 80% completed. Fifth floor 50% completed. Fisting of Balcony Rails Balcony railing work 25% completed. Model Flat Finishing works 90% completed.



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 28 th FEBRUARY -2023
	 Structure Work. Completed Upto Seventh floor level slab R.C.C 100% completed. Seventh floor Columns Concrete 50% completed. Eighth floor level slab – 1st Half R.C.C 100% completed. Eighth floor Columns Concrete 10% completed. Eighth floor Columns Concrete 10% completed. Market Barbending Works on progress. 	 Structure Work. Completed Upto Seventh floor level slab R.C.C 100% completed. Seventh floor Columns Concrete 100% completed. Eighth floor level slab – 1st Half R.C.C 100% completed. Eighth floor Columns Concrete 50% completed. On Progress 9th floor level slab- 1st half shuttering & barbending works on progress.
A2 BLOCK	 Internal Finishing Work. Block Work Upto Third floor 95% completed. Fourth floor 60% completed. Fifth floor 60% completed. Ceiling Plastering Stilt floor 65% completed. Upto Third floor 95% completed. Fourth floor 15% completed. 	 Internal Finishing Work. Block Work Upto Third floor 95% completed. Fourth floor 70% completed. Fifth floor 65% completed. Ceiling Plastering Stilt floor 65% completed. Upto Third floor 95% completed. Fourth floor 30% completed.
	 Wall Plastering First floor 95% completed. Second floor 95% completed. Third floor 70% completed. Fourth floor 15% completed. Fixing of Balcony Rails Balcony railing work 10% completed. 	 Wall Plastering First floor 95% completed. Second floor 95% completed. Third floor 85% completed. Fourth floor 15% completed. Fixing of Balcony Rails Balcony railing work 20% completed.



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 28th FEBRUARY -2023
	 Structure Work. Completed Upto Terrace floor level slab- R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (3 out of 3) - Slab Concrete 100% completed Over Head Water Tank (a) Base Slab Concrete (3 out of 3) - 100% completed. (b) Wall Concrete (3 out of 3) - 100% completed. (c) Top Cover slab (3 out of 3) - 100% completed. 	 Structure Work. Completed Upto Terrace floor level slab- R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (3 out of 3) - Slab Concrete 100% completed Over Head Water Tank (a) Base Slab Concrete (3 out of 3) - 100% completed. (b) Wall Concrete (3 out of 3) - 100% completed. (c) Top Cover slab (3 out of 3) - 100% completed.
B1 BLOCK	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Terrace floor Parapet wall 100% completed. Ceiling Plastering Stilt floor 80% completed. First floor to Tenth floor 95% completed. Wall Plastering First floor to Tenth floor 95% completed. Wall Plastering First floor to Tenth floor 95% completed. Wall Plastering First floor to Tenth floor 95% completed. Wall Plastering First floor to Tenth floor 95% completed. Wall Plastering First floor to Tenth floor 95% completed. Wall Putty work – 1st Coat	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Terrace floor Parapet wall 100% completed. Ceiling Plastering Stilt floor 80% completed. First floor to Tenth floor 95% completed. Wall Plastering First floor to Tenth floor 95% completed. Wall Plastering First floor to Tenth floor 95% completed. Wall Plastering First floor to Tenth floor 95% completed. Wall Plastering First floor to Tenth floor 95% completed. Wall Putty work – 1st Coat Upto Tenth floor 90% completed Fixing of Balcony Rails Balcony railing work 90%
	 completed. Fixing of Staircase Hand Rails Upto Fifth floor completed. 	 completed. Fixing of Staircase Hand Rails Upto Sixth floor completed.
	 Internal Plumbing Lines First floor to Tenth floor 85% 	 Internal Plumbing Lines Water supply pipe Lines (CPVC) -



	completed.	60% completed.
	 Fixing of Bathroom Wall Tiles Fifth floor to Tenth floor 50% 	Sanitary Lines (PVC) – 60% completed
	completed.	Vertical Plumbing Lines
	 Fixing of UPVC Windows Upto Fifth floor 15 % completed. 	• Water supply pipe Lines (G.I) - 15% completed.
	External Finishing Works	Sanitary Lines (PVC) – 15% completed.
	 External Plastering In South Side Elevation 100% completed. In East Side Elevation 70% 	 Fixing of Bathroom Wall Tiles Fifth floor to Tenth floor 50% completed.
	completed. In West Side Elevation 50%	 Fixing of UPVC Windows Upto Fifth floor 15 % completed.
	completed. In North Side Elevation 90% completed.	 External Finishing Works External Plastering
	• Model Flat Finishing works 90% completed.	 In South Side Elevation 100% completed. In East Side Elevation 80% completed.
		 In West Side Elevation 80% completed. In North Side Elevation 90% completed.
		• Model Flat Finishing works 90% completed.
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 28th FEBRUARY -2023
	Structure Work.	Structure Work.
B2 BLOCK	Completed	Completed
	• Upto Third floor level slab – R.C.C 100% completed.	• Upto Third floor level slab – R.C.C 100% completed.
	• Third floor Columns Concrete 80% completed.	 Third floor Columns Concrete 80% completed.
	On Progress	On Progress
	 Shuttering works for 1st half of Fourth floor level slab 15% completed and balance works on progress. 	 Shuttering works for 1st half of Fourth floor level slab 15% completed and balance works on progress.



	 Internal Finishing Work. Block Work First floor 50% completed. 	 Internal Finishing Work. Block Work First floor 50% completed.
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 28th FEBRUARY -2023
	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (4 out of 4) - Slab Concrete 100% completed. Over Head Water Tank (a) Base Slab Concrete (3 out of 3) - 100% completed. (b) Wall Concrete (2 out of 3) - 100% completed. (c) Top Cover slab Concrete (2 out of 3 100% completed. 	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (4 out of 4) - Slab Concrete 100% completed. Over Head Water Tank (a) Base Slab Concrete (3 out of 3) - 100% completed. (b) Wall Concrete (3 out of 3) - 100% completed. (c) Top Cover slab Concrete (3 out of 3 100% completed.
C1 BLOCK	 On Progress Shuttering & Reinforcement works for Over Head Tank Wall & cover slab on progress. 	
	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Terrace Parapet Wall 95% completed. 	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Terrace Parapet Wall 95% completed.
	 Ceiling Plastering Stilt floor 90% completed. First floor to Tenth floor 95% completed. 	 Ceiling Plastering Stilt floor 90% completed. First floor to Tenth floor 95% completed.
	 Wall Plastering First floor to Tenth floor 95% completed. 	 Wall Plastering First floor to Tenth floor 95% completed.
	 ♦ Wall Putty work – 1st Coat ■ Upto Seventh floor 90% 	 Wall Putty work – 1st Coat Upto Eighth floor 90% completed



completed	■ Ninth floor 10% completed.
 Fixing of Balcony Rails Balcony railing work 85% completed. 	 Fixing of Balcony Rails Balcony railing work 90% completed.
 Fixing of Staircase Hand Rails Upto Second floor completed. Internal Plumbing Lines 	 Fixing of Staircase Hand Rails Staircae 1 - Upto Tenth floor completed.
 First floor to Tenth floor 85% completed. Fixing of Bathroom Wall Tiles Seventh floor to Tenth floor 50% 	 Internal Plumbing Lines Water supply pipe Lines (CPVC) - 90% completed. Sanitary Lines (PVC) - 90%
 • External Finishing Works • External Plastering 	 completed Vertical Plumbing Lines Water supply pipe Lines (G.I) -
 In North Side Elevation 100% completed. In West Side Elevation 70% completed. 	 50% completed. Sanitary Lines (PVC) - 50% completed.
■ In East Side Elevation 70% completed.	 Fixing of Bathroom Wall Tiles Seventh floor to Tenth floor 50% completed.
• Model Flat Finishing works 90% completed.	 External Finishing Works External Plastering In North Side Elevation 100% completed. In West Side Elevation 90% completed. In East Side Elevation 90% completed. In South Side Elevation 95% completed. Model Flat Finishing works 90% completed.



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 28 th FEBRUARY -2023
C2 BLOCK	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (3 out of 4) - Slab Concrete 100% completed. Over Head Water Tank	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (3 out of 4) - Slab Concrete 100% completed. Over Head Water Tank
C2 BLOCK	 Parapet Wall 90% competed. Ceiling Plastering Stilt floor 90% completed. First floor to Ninth floor 95% completed. Tenth floor 80% completed. Wall Plastering Upto Ninth floor 95% completed 	 Parapet Wall 90% competed. Ceiling Plastering Stilt floor 90% completed. First floor to Tenth floor 95% completed. Wall Plastering Upto Ninth floor 95% completed
	 Tenth floor 75% completed. Wall Putty work-1st Coat Upto 8th floor completed. Fixing of Balcony Rails Balcony railing work 75% completed. External Finishing Works External Plastering In North Side Elevation 100% completed. In East Side Elevation 30% 	 Tenth floor 90% completed. Wall Putty work-1st Coat Upto 8th floor 100% completed. Fixing of Balcony Rails Balcony railing work 80% completed. External Finishing Works External Plastering In North Side Elevation 100% completed. In East Side Elevation 50%



Progress Report No.51 (07.03.2017 - 28.02.2023)

Page 8

	1	1,1
	completed	completed
		In West Side Elevation 50%
		completed
		• In South Side Elevation 30%
		completed.
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 28th FEBRUARY -2023
	Structure Work.	Structure Work.
	◆ Completed	Completed
	• Upto Tenth Floor level slab –	■ Upto Terrace Floor level slab –
	R.C.C 100% completed.	R.C.C 100% completed.
	• Tenth floor Columns Concrete	• Terrace floor columns concrete
	10% completed.	15% completed.
	On Progress	♦ On Progress
	■10 th Floor Columns Concrete	•Terrace floor – Columns Shuttering
	work on progress.	& Barbending works on progress.
	■ Terrace floor – 1 st half Shuttering	Internal Finishing Work.
	& Barbending works on progress	Block Work
	Internal Finishing Work.	• Upto Fifth floor 95% completed.
	Block Work	• Sixth floor to Eighth floor 90%
	• Upto Fifth floor 95% completed.	completed. • Ninth floor 75% completed.
	• Sixth floor to Eighth floor 80%	-
C3 BLOCK	completed.	Ceiling Plastering
	• Ninth floor 20% completed.	• Stilt floor 90% completed.
	♦ Ceiling Plastering	• First floor to Fifth floor 95%
	• Stilt floor 90% completed.	completed.
	• First floor to Fifth floor 95%	• Sixth floor 70% completed.
	completed.	Wall Plastering
	■ Sixth floor 30% completed.	• First floor 95% completed.
	♦ Wall Plastering	• Second floor to Fifth floor 90%
	• First floor 95% completed.	completed.
	 Second floor 90% completed 	• Sixth floor 45% completed.
	• Third floor 90% completed.	 Fixing of Balcony Rails
	• Fourth floor 90% completed.	 Balcony railing work 65% completed.
	• Fifth floor 90% completed.	External Finishing Works
	Sixth floor 30% completed.	External Plastering
		In West Side Elevation -
		Scaffolding work on progress
1		B ProBross



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 28th FEBRUARY -2023
	 Structure Work. Completed Upto Terrace floor level slab R.C.C 100% completed. Terrace Parapet Columns 	 Structure Work. Completed Upto Terrace floor level slab R.C.C 100% completed. Terrace Parapet Columns Concrete 100 % completed.
	 Concrete 60 % completed. Lift Head room (1 out of 4) - Slab Concrete 100% completed. 	100 % completed.Lift Head room (3 out of 4) - Slab Concrete 100% completed.
	 On Progress Shuttering & Reinforcement works for Terrace floor parapet columns and Lift slab on progress 	 Over Head Water Tank (a) Base slab Concrete (1 out of 3)) – 100% completed. On Progress Shuttering & Reinforcement works for Lift slab & Tank wall on progress
D1 BLOCK	 Internal Finishing Work. Block Work First floor to Seventh floor 95% completed. Eighth floor 80% completed. Ninth floor 50% completed. Tenth floor 20% completed. 	 Internal Finishing Work. Block Work First floor to Seventh floor 95% completed. Eighth floor 90% completed. Ninth floor 75% completed. Tenth floor 30% completed.
	 Ceiling Plastering First floor to Seventh floor 95% completed. Eighth floor 20% completed. 	 Ceiling Plastering First floor to Seventh floor 95% completed. Eighth floor 40% completed.
	 Wall Plastering Upto Sixth floor 95% completed Seventh floor 75% completed. 	 Wall Plastering Upto Seventh floor 95% completed Eighth floor 35% completed.
	 Wall Putty work – 1st Coat Upto Fifth floor 90% completed. 	 Wall Putty work – 1st Coat Upto Sixth floor 90% completed.
	 Fixing of Balcony Rails Balcony railing work 65% completed. 	 Fixing of Balcony Rails Balcony railing work 75% completed.



		 External Finishing Works External Plastering In West Side Elevation - 10% completed.
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 28 th FEBRUARY -2023
	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. 	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed.
	 Lift Head room (4 out of 4)- Slab Concrete 100% completed. 	 Lift Head room (4 out of 4)- Slab Concrete 100% completed.
D2 BLOCK	 Over Head Water Tank (a) Base Slab Concrete (3 out of 3) - 100% completed. (b) Tank wall Concrete (3 out of 3) - 100% completed. (c) Top Cover slab (3 out of 3) - 100% completed. 	 Over Head Water Tank (a) Base Slab Concrete (3 out of 3) 100% completed. (b) Tank wall Concrete (3 out of 3) 100% completed. (c) Top Cover slab (3 out of 3) - 100% completed.
	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Terrace floor Parapet wall 95% completed. 	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Terrace floor Parapet wall 95% completed.
	 Ceiling Plastering Stilt floor 80% completed. First floor to Tenth floor 95% completed. 	 Ceiling Plastering Stilt floor 80% completed. First floor to Tenth floor 95% completed.
	 Wall Plastering First floor to Tenth floor 95% completed. 	 Wall Plastering First floor to Tenth floor 95% completed.
	 Wall Putty work – 1st Coat Upto Tenth floor 90% completed 	 Wall Putty work – 1st Coat Upto Tenth floor 90% completed
	 Fixing of Balcony Rails Balcony railing work 85% completed. 	 Fixing of Balcony Rails Balcony railing work 90% completed.



 Fixing of Bathroom Wall Tiles Sixth floor Tenth floor 50% completed. 	 Fixing of Staircase Hand Rails Staircae 1 - Upto Tenth floor completed.
 External Finishing Works External Plastering 	 Staircase 2 – Upto First floor completed.
In West Side Elevation 100% completed.In North Side Elevation 90%	 Fixing of Bathroom Wall Tiles Sixth floor Tenth floor 50% completed.
completed. In South Side Elevation 90% completed. In East Side Elevation 90%	 Laying Of Floor Tiles Ceramic Tiles in Bathroom – 25% completed. Vitrified Tiles in Halls &
• Model Flat Finishing works 90%	Bedrooms – 5% completed.External Finishing Works
completed.	 External Plastering In West Side Elevation 100% completed.
	 In North Side Elevation 95% completed. In South Side Elevation 95%
	 In South Side Elevation 95% completed. In East Side Elevation 95% completed.
	• Model Flat Finishing works 90% completed.





	External Finishing Works	External Finishing Works		
	External Plastering	External Plastering		
	■ In East Side Elevation 65% completed.	■ In East Side Elevation 95% completed.		
	In North Side Elevation 40% completed.	 In North Side Elevation 95% completed. 		
	 In South Side Elevation 85% completed. 	 In South Side Elevation 95% completed. 		
		 In West Side Elevation 55% completed. 		
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 28 th FEBRUARY -2023		
	 Structure Work. Completed Upto Terrace floor level slab – 	 Structure Work. Completed Upto Terrace floor level slab – 		
	R.C.C 100% completed.	R.C.C 100% completed.		
	 Terrace floor Parapet Columns Concrete 100% completed. 	 Terrace floor Parapet Columns Concrete 100% completed. 		
	 Lift Head room (2 out of 2) – slab Concrete 100% completed. 	 Lift Head room (2 out of 2) – slab Concrete 100% completed. 		
	 Over Head Water Tank (a) Base slab concrete completed. (b) Tank Wall concrete completed. 	 Over Head Water Tank (a) Base slab concrete completed. (b) Tank Wall concrete completed. 		
COMMUNITY HALL	 Internal Finishing Work. Block Work Upto Fourth 100% completed. 	 Internal Finishing Work. Block Work Upto Fourth 100% completed. 		
	 Ceiling Plastering Stilt floor 90% completed. 	 Ceiling Plastering Stilt floor 90% completed. 		
	Upto Third floor 100% completedFourth floor 95% completed.	• Upto Fourth floor 100% completed		
		 Wall Plastering Upto Fourth floor 100% completed 		
	 Wall Plastering Upto Third floor 100% completed 	 Ceiling Putty work Upto Fourth floor 100% completed 		
	• Fourth floor 95% completed.	 ♦ Wall Putty work 		
	 Ceiling Putty work Upto Third floor 100% completed 	• Upto Fourth floor 100% completed		
	• Fourth floor 95% completed.	 Wall Painting work Upto Fourth floor - 1st Coat 		



	painting 95% completed		
 Wall Putty work Upto Third floor 100% completed 	painting 95% completed.		
• Fourth floor 95% completed.	 Staircase Hand Railing work First floor 90% completed. 		
♦ Wall Painting work	 Second floor 90% completed. 		
• Upto Second floor - 1st Coat	 Third floor 75% completed. 		
painting 95% completed.	• Fourth floor 75% completed.		
	-		
 Third & Fourth floor - 1st Coat painting 80% completed. 	 Flooring Work Stilt floor Granolithic flooring 95% 		
 Staircase Hand Railing work 	completed. • Vitrified Floor Tiles in Hall &		
• First floor 90% completed.	rooms - Upto Fourth floor 95%		
Second floor 90% completed.	completed.		
• Third floor 75% completed.	Ceramic Floor Tiles in Bathrooms		
• Fourth floor 75% completed.	– Upto Fourth floor 95%		
◆ Flooring Work	completed. ♦ Wall Tiles & Cladding Work		
• Stilt floor Granolithic flooring	 Wan Thes & Clauding Work Ceramic Wall Tiles in Bathrooms – 		
95% completed. • Vitrified Floor Tiles in Hall &	Upto Fourth floor 95% completed.		
rooms - Upto Fourth floor 95%	♦ Fixing of UPVC Windows		
completed.	• Upto Third floor UPVC Window fixing 95% completed.		
 Ceramic Floor Tiles in Bathrooms 			
– Upto Fourth floor 95%	• Fourth floor UPVC Window fixing		
completed.	90% completed. • All floors Staircase fixed windows		
♦ Wall Tiles & Cladding Work			
• Ceramic Wall Tiles in Bathrooms	90% completed		
– Upto Fourth floor 95%	External Finishing Work.		
completed.	 External Plastering 		
 Fixing of UPVC Windows 	•West Side elevation 100%		
Upto Third floor UPVC Window	completed.		
fixing 95% completed.	• South Side elevation 100%		
• Fourth floor UPVC Window	completed		
fixing 90% completed.	• North Side elevation 100%		
• All floors Staircase fixed	completed. East Side elevation 100%		
windows 90% completed	• East Side elevation 100% completed.		
External Finishing Work.	completed.		
• External Plastering	▲ External Painting		
•West Side elevation 100%	 External Painting 1st Coat 95% completed. 		
completed.			
-			
-			
completed.			
 South Side elevation 100% completed. North Side elevation 100% completed. East Side elevation 100% 			



PHOTOGRAPHS OF WORK PROGRESS AS ON 28th FEBRUARY 2023

Community Hall : External Painting 1st Coat 100% completed





<u>Block A1:</u> Eighth Floor level slab Concrete casting 100% completed. Eighth floor columns 50% completed.





<u>Block A2</u>: Eighth Floor level slab -1^{st} Half Concrete casting 100% completed. Eighth floor columns concrete 50% completed.





Block B1: External Plastering South side elevation 100%, East side 80%, West Side 80% & North Side 90% completed.





Block B2 : Third Floor Level slab concrete casting 100% completed. Shuttering works for 1st half of Fourth floor level slab 15% completed.





Block C1: Terrace Floor level slab concrete 100% completed. External Plastering in North Side elevation 100% completed, West Side elevation 90% completed, East Side elevation 90% completed & West Side elevation 95% completed.





Block C2: Terrace floor level slab 100% completed. External plastering in North side elevation 100% completed, East side elevation 50% completed, West side elevation 50% completed & South side elevation 30% completed on progress






Block C3: Terrace Floor level slab Concrete casting 100% completed. Terrace floor columns concrete 15% completed & balance works on progress.






Block D1: Terrace Floor level slab Concrete casting 100% completed. External plastering in West side elevation on progress.





Block D2: Over Head Water Tank 100% completed.. External Plastering work in West side elevation 100% completed, North side elevation 95% completed, South side elevation 95% & East side elevation 95% completed.





Block D3: Terrace Floor level slab Concrete casting 100% completed. External Plastering in South side elevation 95%, East Side 95% & North side 95% & West Side 55% completed.





QUALITY CONTROL

<u>DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS CONDUCTED</u> <u>AT SITE:</u>

Sl.No.	Materials	Source from	Test Done	Result	
1	M-Sand	Arcot (T.K), Ranipet (Dist) Walajabad(T.K), Kanchipuran (Dt)	Each Truck	Sieve Analysis & Silt content	
2.	P- Sand	Uthiramerur, Kanchipuram (DT) Walajabad(T.K), Kanchipuran (Dt)	Each Truck	Sieve Analysis & Silt content	
2	Coarse Aggregate (20mm)	Sriperambathur, Kanchipuran (Dt), Vellore Dt & Chitoor Dt.	Each Truck	Sieve Analysis	
3	Coarse Aggregate (12mm)	Sriperambathur, Kanchipuran (Dt) Vellore Dt & Chitoor Dt.	Each Truck	Sieve Analysis	
4	Cement	Third party testing is being done.			
5	Steel	Third party testing is being done.			
6	Pile Integrity	Third party testing is being done.			
7	Soil Compaction	Third party testing is being done.			
8	RCC cubes are being tested and Register is being maintained.				
9	Slump test conducted at site to insure workability of concrete.				



PHOTOGRAPH OF QUALITY CONTROL AT SITE

Concrete Cube Compressive Strength Testing





20mm & 12mm Aggregate Sieve Analysis Testing





Fine Aggregate Sieve Analysis Testing



