CGEWHO – CHENNAI PHASE-III PROJECT



MONTHLY PROGRESS REPORT

STATUS AS ON: 30.06.2023

30.06.2023

	30.06.2	
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th JUNE-2023
BLOCK A1 BLOCK	 Structure Work. Completed Upto Tenth floor level slab R.C.C 100% completed. Tenth floor Columns Concrete 100% completed. Terrace floor level slab 1st half 100% completed. On Progress Terrace floor level slab – 2nd half Shuttering & barbending works 75% completed. Internal Finishing Work. Block Work Upto Seventh floor 95% completed. Ninth floor 45% completed. Ninth floor 50% completed. Upto Seventh floor 95% completed. Ninth floor 40% completed. Wall Plastering Upto Seventh floor 95% completed. Eighth floor 40% completed. Eighth floor 40% completed. 	
A1 BLOCK	 Stilt floor 50% completed. Upto Seventh floor 95% completed. Eighth floor 70% completed. Ninth floor 40% completed. Wall Plastering Upto Seventh floor 95% completed. 	 Ninth floor 50% completed. Tenth floor 40% completed. Wall Plastering Upto Eighth floor 95% completed. Ninth floor 45% completed. Tenth floor 40% completed Wall Putty work – 1st Coat Upto Fifth floor 85% completed.
	completed. ◆ Internal Plumbing Lines • Water supply pipe Lines (CPVC) - 50% completed. • Sanitary Lines (PVC) - 25% completed • Model Flat Finishing works 90% completed.	50% completed. ■ Sanitary Lines (PVC) – 25% completed. ◆ External Plastering ■ In West side 90% completed. ■ In North side 10% completed. ■ Model Flat Finishing works 90% completed.



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30 th JUNE-2023		
A2 BLOCK	 Structure Work. Completed Tenth floor level slab 1st Half R.C.C 100% completed. Tenth floor Columns Concrete 50% completed. Terrace floor level slab − 1st Half R.C.C 100% completed. On Progress 10th floor level slab − 2nd half shuttering & barbending works 90% completed. Internal Finishing Work. Block Work Upto Seventh floor 95% completed. Ninth floor 55% completed. Ninth floor 55% completed. Ceiling Plastering Stilt floor 65% completed. Sixth floor 70% completed. Seventh floor 50% completed. Wall Plastering Upto Fifth floor 95% completed. Sixth floor 70% completed. Seventh floor 50% completed. Fixing of Balcony Rails Balcony railing work 60% completed. Internal Plumbing Lines Water supply pipe Lines (CPVC) - 50% completed. Sanitary Lines (PVC) - 20% completed. 	 Structure Work. Completed Upto Tenth floor level slab R.C.C 100% completed. Tenth floor Columns Concrete 100% completed. Terrace floor level slab − 1st Half R.C.C 100% completed. Terrace Parapet columns 40% completed On Progress Terrace floor level slab - 2nd half shuttering & barbending works 60% completed. Internal Finishing Work. Block Work Upto Eighth floor 95% completed. Ninth floor 50% completed. Tenth floor 40% completed. Ceiling Plastering Stilt floor 65% completed. Upto Seventh floor 95% completed. Ninth floor 50% completed. Ninth floor 50% completed. Tenth floor 40% completed. Tenth floor 40% completed. Tenth floor 50% completed. Tenth floor 75% completed. Ninth floor 50% completed. Fixing of Balcony Rails Balcony railing work 60% completed. Internal Plumbing Lines Water supply pipe Lines (CPVC) - 50% completed. Sanitary Lines (PVC) - 20% completed. 		



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th JUNE-2023	
	 Structure Work. Completed Upto Terrace floor level slab- R.C.C 100% completed. 	 Structure Work. Completed Upto Terrace floor level slab R.C.C 100% completed. 	
	■ Terrace floor Parapet Columns Concrete 100% completed.	■ Terrace floor Parapet Column Concrete 100% completed.	
	Lift Head room (3 out of 3) - Slab Concrete 100% completed	Lift Head room (3 out of 3) - Sla Concrete 100% completed	
	 Over Head Water Tank (a) Base Slab Concrete (3 out of 3) 100% completed. (b) Wall Concrete (3 out of 3) - 100% completed. (c) Top Cover slab (3 out of 3) - 100% completed. 	 Over Head Water Tank (a) Base Slab Concrete (3 out of 3 - 100% completed. (b) Wall Concrete (3 out of 3) 100% completed. (c) Top Cover slab (3 out of 3) 100% completed. 	
	• Internal Finishing Work.	• Internal Finishing Work.	
	♦ Block Work	♦ Block Work	
31 BLOCK	Upto Tenth floor 95% completed.Terrace floor Parapet wall 100% completed.	Upto Tenth floor 95% completed.Terrace floor Parapet wall 100% completed.	
of BLOCK	♦ Ceiling Plastering	♦ Ceiling Plastering	
	■ Stilt floor 80% completed.	Stilt floor 80% completed.	
	• First floor to Tenth floor 95% completed.	First floor to Tenth floor 959 completed.	
	◆ Wall Plastering ■ First floor to Tenth floor 95% completed.	◆ Wall Plastering ■ First floor to Tenth floor 959 completed.	
	♦ Wall Putty work - 1st Coat	♦ Wall Putty work - 1st Coat	
	■ Upto Tenth floor 95% completed.	■ Upto Tenth floor 95% completed.	
	♦ Fixing of Balcony Rails	♦ Fixing of Balcony Rails	
	Balcony railing work 95% completed.	Balcony railing work 959 completed.	
	 Fixing of Staircase Hand Rails Staircase 1 -Upto Tenth floor 90% completed. Staircase 2 -Upto Tenth floor 90% completed. Staircase 3 - Upto Fifth floor 60% completed. 	 Fixing of Staircase Hand Rails Staircase 1 -Upto Tenth floor 909 completed. Staircase 2 -Upto Tenth floor 909 completed. Staircase 3 - Upto Fifth floor 809 completed. 	



♦ Internal Plumbing Lines

- Water supply pipe Lines (CPVC) 95% completed.
- Sanitary Lines (PVC) 95% completed

♦ Vertical Plumbing Lines

- Water supply pipe Lines (G.I) 85% completed.
- Sanitary Lines (PVC) 80% completed.

♦ Fixing of Bathroom Wall Tiles

■ Tenth floor to Second floor 90% completed.

♦ Laying Of Floor Tiles

- Ceramic Tiles in Bathroom 80% completed.
- Vitrified Tiles in Halls & Bedrooms 85% completed.

♦ Fixing of UPVC Windows

- Upto Eight floor 75% completed.
- Ninth floor 25% completed.

♦ Erection of LIFTS

- Materials for 3 Nos of Lifts arrived
- Lift 1 Installation works 40% completed.
- Lift 2 Installation works 10% completed.
- Lift 3 Installation works 15% completed.

• External Finishing Works

♦ External Plastering

- In South Side Elevation 100% completed.
- In East Side Elevation 95% completed.
- In West Side Elevation 95% completed.
- In North Side Elevation 95% completed.
- **Model Flat** Finishing works 90% completed.

▶ Internal Plumbing Lines

- Water supply pipe Lines (CPVC) 95% completed.
- Sanitary Lines (PVC) 95% completed

♦ Vertical Plumbing Lines

- Water supply pipe Lines (G.I) 90% completed.
- Sanitary Lines (PVC) 90% completed.

♦ Fixing of Bathroom Wall Tiles

■ Tenth floor to First floor 95% completed.

♦ Laying Of Floor Tiles

- Ceramic Tiles in Bathroom 90% completed.
- Vitrified Tiles in Halls & Bedrooms 85% completed.

♦ Fixing of UPVC Windows

- Upto Eight floor 75% completed.
- Ninth floor 50% completed.
- Tenth floor 40% completed.

♦ Erection of LIFTS

- Materials for 3 Nos of Lifts arrived
- Lift 1 Installation works 70% completed.
- Lift 2 Installation works 50% completed.
- Lift 3 Installation works 25% completed.

External Finishing Works

◆ External Plastering - Overall 95% Completed.

♦ Primer

1st Coat 95% completed. 2nd Coat 95% completed.

• **Model Flat** Finishing works 90% completed.



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th JUNE-2023
B2 BLOCK	 Structure Work. Completed Upto Fourth floor level slab – R.C.C 100% completed. Fourth floor Columns Concrete 100% completed. Fifth floor level slab – 1st half Concrete 100% completed. Fifth floor Columns Concrete 35% completed. On Progress Shuttering works for 2nd half of Fifth floor level slab 90% completed and balance works on progress. Internal Finishing Work. Block Work First floor 90% completed. Second floor 80% completed. Third floor 50% completed. 	 Structure Work. Completed Upto Fifth floor level slab – R.C.C 100% completed. Fifth floor Columns Concrete 50% completed. On Progress Shuttering works for 1st half of Sixth floor level slab 70% completed and balance works on progress. Internal Finishing Work. Block Work First floor 90% completed. Second floor 85% completed. Third floor 80% completed. Ceiling Plastering First floor 50% completed. Second floor 40% completed. Second floor 40% completed. Second floor 40% completed. Second floor 40% completed.



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th JUNE-2023	
	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. 	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. 	
	■ Terrace floor Parapet Columns Concrete 100% completed.	■ Terrace floor Parapet Column Concrete 100% completed.	
	Lift Head room (4 out of 4) - Slab Concrete 100% completed.	■ Lift Head room (4 out of 4) - Slab Concrete 100% completed.	
	 Over Head Water Tank (a) Base Slab Concrete (3 out of 3) - 100% completed. (b) Wall Concrete (3 out of 3) - 100% completed. (c) Top Cover slab Concrete (3 out of 3 100% completed. 	 Over Head Water Tank (a) Base Slab Concrete (3 out of 3) - 100% completed. (b) Wall Concrete (3 out of 3) - 100% completed. (c) Top Cover slab Concrete (3 out of 3 100% completed. 	
	• Internal Finishing Work.	Internal Finishing Work.	
C1 BLOCK	 Block Work Upto Tenth floor 95% completed. Terrace Parapet Wall 95% completed. 	 Block Work Upto Tenth floor 95% completed. Terrace Parapet Wall 95% completed. 	
	◆ Ceiling Plastering ■ Stilt floor 90% completed. ■ First floor to Tenth floor 95% completed.	 Ceiling Plastering Stilt floor 90% completed. First floor to Tenth floor 95% completed. 	
	◆ Wall Plastering ■ First floor to Tenth floor 95% completed.	◆ Wall Plastering • First floor to Tenth floor 95% completed.	
	◆ Wall Putty work – 1 st Coat • First floor to Tenth floor 95% completed.	 ♦ Wall Putty work – 1st Coat • First floor to Tenth floor 95% completed. 	
	◆ Fixing of Balcony Rails ■ Balcony railing work 90% completed.	◆ Fixing of Balcony Rails ■ Balcony railing work 90% completed.	
	 Fixing of Staircase Hand Rails Staircase 1 - Upto Tenth floor 90% completed. Staircase 2 - Upto Fifth floor 90% completed. Staircase 3 - Upto Fifth floor 60% completed. 	 Fixing of Staircase Hand Rails Staircase 1 - Upto Tenth floor 90% completed. Staircase 2 - Upto Fifth floor 90% completed. Staircase 3 - Upto Fifth floor 75% completed. 	



♦ Internal Plumbing Lines

- Water supply pipe Lines (CPVC) 95% completed.
- Sanitary Lines (PVC) 95% completed

♦ Vertical Plumbing Lines

- Water supply pipe Lines (G.I) 90% completed.
- Sanitary Lines (PVC) 90% completed.

♦ Fixing of Bathroom Wall Tiles

- Tenth floor to Sixth floor 100% completed.
- Fifth floor 90% completed
- Fourth floor 90% completed.
- Third floor 50% completed.

♦ Erection of LIFTS

Materials for 4 Nos of Lifts arrived

♦ Terrace Water Proofing

■ Weathering course works 65% completed.

External Finishing Works

♦ External Plastering

- In North Side Elevation 100% completed.
- In West Side Elevation 95% completed.
- In East Side Elevation 95% completed.
- In South Side Elevation 95% completed.
- **Model Flat** Finishing works 90% completed.

♦ Internal Plumbing Lines

- Water supply pipe Lines (CPVC) 95% completed.
- Sanitary Lines (PVC) 95% completed

♦ Vertical Plumbing Lines

- Water supply pipe Lines (G.I) 90% completed.
- Sanitary Lines (PVC) 90% completed.

♦ Fixing of Bathroom Wall Tiles

■ Tenth floor to Second floor floor 100% completed.

♦ Laying Of Floor Tiles

- Ceramic Tiles in Bathroom 50% completed.
- Vitrified Tiles in Halls & Bedrooms 80% completed.

♦ Fixing of UPVC Windows

- Upto Seventh floor 75% completed.
- Eighth floor 5% completed.

♦ Erection of LIFTS

Materials for 4 Nos of Lifts arrived

♦ Terrace Water Proofing

■ Weathering course works 70% completed.

External Finishing Works

◆ External Plastering - Overall 95% Completed.

♦ Primer

1st Coat 95% completed. 2nd Coat 95% completed.

• **Model Flat** Finishing works 90% completed.



		CITATELIC AC ON 20th WINE 2022		
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th JUNE-2023		
	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (3 out of 4) - Slab Concrete 100% completed. 	 Structure Work. Completed Upto Terrace floor level slab - R.C.C 100% completed. Terrace floor Parapet Columns Concrete 100% completed. Lift Head room (3 out of 4) - Slab Concrete 100% completed. 		
	■ Over Head Water Tank (a) Base slab Concrete (2 out of 3) – 100% completed.	■ Over Head Water Tank (a) Base slab Concrete (2 out of 3) – 100% completed.		
	(b) Wall Concrete (2 out of 3) – 100% completed.	(b) Wall Concrete (2 out of 3) – 100% completed.		
	(c) Top slab Concrete (1 out of 3) – 100% completed.	(c) Top slab Concrete (1 out of 3) – 100% completed.		
	◆ On Progress Shuttering works for 2 nd Over Head Water Tank Top slab on progress.	◆ On Progress Shuttering works for 2 nd Over Head Water Tank Top slab on progress.		
C2 BLOCK	Internal Finishing Work.	Internal Finishing Work.		
	 Block Work Upto Tenth floor 95% completed. Parapet Wall 95% competed. 	 Block Work Upto Tenth floor 95% completed. Parapet Wall 95% competed. 		
◆ Ceiling Plastering ■ Stilt floor 90% completed. ■ First floor to Tenth floor 95% completed.		 ◆ Ceiling Plastering ■ Stilt floor 90% completed. ■ First floor to Tenth floor 95% completed. 		
	◆ Wall Plastering ■ Upto Tenth floor 95% completed	◆ Wall Plastering • Upto Tenth floor 95% completed		
	◆ Wall Putty work-1 st Coat ■ Upto Tenth floor 95% completed.	◆ Wall Putty work-1 st Coat ■ Upto Tenth floor 95% completed.		
	◆ Fixing of Balcony Rails ■ Balcony railing work 90% completed.	◆ Fixing of Balcony Rails ■ Balcony railing work 90% completed.		
	◆ Internal Plumbing Lines • Water supply pipe Lines (CPVC) - 90% completed.	◆ Internal Plumbing Lines • Water supply pipe Lines (CPVC) - 90% completed.		
	Sanitary Lines (PVC) – 90% completed.	Sanitary Lines (PVC) – 90% completed.		



♦ Vertical Plumbing Lines

- Water supply pipe Lines (G.I) 85% completed.
- Sanitary Lines (PVC) 85% completed.

♦ Erection of LIFTS

Materials for 3 Nos of Lifts arrived

• External Finishing Works

♦ External Plastering

- In North Side Elevation 100% completed.
- In East Side Elevation 95% completed
- In West Side Elevation 95% completed.
- In South Side Elevation 95% completed.

♦ Vertical Plumbing Lines

- Water supply pipe Lines (G.I) 85% completed.
- Sanitary Lines (PVC) 85% completed.

♦ Fixing of Bathroom Wall Tiles

- Tenth floor 100% completed.
- Ninth floor 50% completed.

♦ Laying Of Floor Tiles

■ Ceramic Tiles in Bathroom – 10% completed.

♦ Fixing of UPVC Windows

- Upto Fourth floor 90% completed.
- Fifth floor 50% completed.

♦ Erection of LIFTS

Materials for 3 Nos of Lifts arrived

• External Finishing Works

- ◆ External Plastering Overall 95% Completed.
- **♦** Primer

1st Coat 95% completed.



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30 th JUNE-2023
C3 BLOCK	 Structure Work. Completed Upto Terrace Floor level slab – R.C.C 100% completed. Terrace floor columns concrete 100% completed. Lift Head room (4 out of 4) - Slab Concrete 100% completed. On Progress Over Head Water Tank Base slab shuttering works on progress. Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Ceiling Plastering Stilt floor 90% completed. First floor to Tenth floor 95% completed. Wall Plastering Upto Ninth floor 95% completed. Fixing of Balcony Rails Balcony railing work 90% completed. Fixing of Balcony Rails Balcony railing work 90% completed. External Plumbing Lines Water supply pipe Lines (CPVC) - 80% completed. External Finishing Works External Plastering In West Side Elevation – 85% completed. In North Side Elevation – 95% completed. In North Side Elevation – 95% completed. In East Side Elevation – 90% completed. In North Side Elevation – 95% completed. In North Side Elevation – 95% completed. 	 Structure Work. Completed Upto Terrace Floor level slab R.C.C 100% completed. Terrace floor columns concre 100% completed. Lift Head room (4 out of 4) - Sla Concrete 100% completed. On Progress Over Head Water Tank Base slasshuttering works on progress. Internal Finishing Work. Block Work Upto Tenth floor 95% completed. Ceiling Plastering Stilt floor 90% completed. First floor to Tenth floor 95% completed. Wall Plastering Upto Ninth floor 95% completed. Wall Putty work − 1st Coat Upto Ninth floor 90% completed. Fixing of Balcony Rails Balcony railing work 90% completed. Fixing of Balcony Rails Balcony railing work 90% completed. Fixing of Balcony Rails Balcony railing work 90% completed. Fixing of Balcony Rails Balcony railing work 90% completed. Fixing of Balcony Rails Balcony railing work 90% completed. Fixing of Balcony Rails Balcony railing work 90% completed. Fixing of Balcony Rails Balcony completed. Fixing of Balcony Rails Balcony completed. Fixing of Balcony Rails Bal



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th JUNE-2023	
BLOCK	 Structure Work. Completed Upto Terrace floor level slab R.C.C 100% completed. Terrace Parapet Columns Concrete 100% completed. Lift Head room (4 out of 4) - Slab Concrete 100% completed. Over Head Water Tank (a) Base slab Concrete (3 out of 3) 	 Structure Work. Completed Upto Terrace floor level slab R.C.C 100% completed. Terrace Parapet Columns Concrete 100% completed. Lift Head room (4 out of 4) - Slab Concrete 100% completed. Over Head Water Tank (a) Base slab Concrete (3 out of 3) 	
) – 100% completed. (b) Wall Concrete (3 out of 3) – 100% completed. (c) Top Cover slab (3 out of 3) – 100%) – 100% completed. (b) Wall Concrete (3 out of 3) – 100% completed. (c) Top Cover slab (3 out of 3) –	
	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. 	 100% completed. Internal Finishing Work. Block Work Upto Tenth floor 95% completed. 	
D1 BLOCK	 Ceiling Plastering Upto Tenth floor 95% completed. Wall Plastering 	 Ceiling Plastering Upto Tenth floor 95% completed. Wall Plastering 	
	 ■ Upto Tenth floor 95% completed. ♦ Wall Putty work – 1st Coat ■ Upto Eighth floor 90% completed. ■ Ninth floor 85% completed. 	 Upto Tenth floor 95% completed. ♦ Wall Putty work – 1st Coat Upto Ninth floor 90% completed. Tenth floor 75% completed 	
	 ■ Tenth floor 70% completed. ♦ Fixing of Balcony Rails ■ Balcony railing work 80% 	◆ Fixing of Balcony Rails ■ Balcony railing work 85% completed.	
	 External Finishing Works External Plastering In West Side Elevation - 95% completed. In North Side Elevation - 85% completed. In South Side Elevation - 90% 	 ◆ Internal Plumbing Lines ■ Water supply pipe Lines (CPVC) - 85% completed. ■ Sanitary Lines (PVC) - 30% completed. ● External Finishing Works ◆ External Plastering - Overall 95% Completed. 	
	completed. In East Side Elevation - 90%	◆ Primer 1 st Coat 95% completed.	



completed.

BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30 th JUNE-2023		
	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed. 	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed. 		
	Terrace floor Parapet Columns Concrete 100% completed.	■ Terrace floor Parapet Column Concrete 100% completed.		
	Lift Head room (4 out of 4)- Slab Concrete 100% completed.	Lift Head room (4 out of 4)- Slab Concrete 100% completed.		
(a) Base Slab Concrete (3 out of 3) - 100% completed. (b) Tank wall Concrete (3 out of 3) - 100% completed. (c) Top Cover slab (3 out of 3) - (a) Base Slab Co - 100% complete (b) Tank wall Co - 100% comp (c) Top Cover slab (c) Top Cover slab		 Over Head Water Tank (a) Base Slab Concrete (3 out of 3) 100% completed. (b) Tank wall Concrete (3 out of 3) 100% completed. (c) Top Cover slab (3 out of 3) - 100% completed. 		
	• Internal Finishing Work.	Internal Finishing Work.		
D2 BLOCK	 ◆ Block Work • Upto Tenth floor 95% completed. • Terrace floor Parapet wall 95% completed. 	 ◆ Block Work ■ Upto Tenth floor 95% completed. ■ Terrace floor Parapet wall 95% completed. 		
	 ◆ Ceiling Plastering ■ Stilt floor 80% completed. ■ First floor to Tenth floor 95% completed. 	◆ Ceiling Plastering ■ Stilt floor 80% completed. ■ First floor to Tenth floor 95% completed.		
	◆ Wall Plastering • First floor to Tenth floor 95% completed.	◆ Wall Plastering ■ First floor to Tenth floor 95% completed.		
	◆ Wall Putty work ■1 st Coat- 95% completed ■2 nd Coat- 85% completed	◆ Wall Putty work ■ 1 st Coat- 95% completed ■ 2 nd Coat- 90% completed		
	◆ Fixing of Balcony Rails ■ Balcony railing work 95% completed.	 Fixing of Balcony Rails ■ Balcony railing work 95% completed. 		
	 Fixing of Staircase Hand Rails Staircae 1 - Upto Tenth floor 90% completed. Staircase 2 - Upto Fifth floor 90% completed. 	 Fixing of Staircase Hand Rails Staircae 1 - Upto Tenth floor 90% completed. Staircase 2 - Upto Fifth floor 90% completed. 		



♦ Internal Plumbing Lines

- Water supply pipe Lines (CPVC) 95% completed.
- Sanitary Lines (PVC) 95% completed

♦ Vertical Plumbing Lines

- Water supply pipe Lines (G.I) 90% completed.
- Sanitary Lines (PVC) 90% completed.

♦ Fixing of Bathroom Wall Tiles

■ Tenth floor to Second floor 70% completed.

♦ Laying Of Floor Tiles

- Ceramic Tiles in Bathroom 60% completed.
- Vitrified Tiles in Halls & Bedrooms 70% completed.

♦ Fixing of UPVC Windows

■ Upto Tenth floor 75% completed.

♦ Terrace Water Proofing

• Weathering course works 50% completed.

♦ Erection of LIFTS

- Materials for 4 Nos of Lifts arrived
- Lift 1- Installation 80% completed.
- Lift 2- Installation 50% completed.
- Lift 3- Installation 10% completed.

• External Finishing Works

♦ External Plastering

- In West Side Elevation 100% completed.
- In North Side Elevation 95% completed.
- In South Side Elevation 95% completed.
- In East Side Elevation 95% completed.
- **Model Flat** Finishing works 90% completed.

♦ Internal Plumbing Lines

- Water supply pipe Lines (CPVC) 95% completed.
- Sanitary Lines (PVC) 95% completed

♦ Vertical Plumbing Lines

- Water supply pipe Lines (G.I) 95% completed.
- Sanitary Lines (PVC) 90% completed.

♦ Fixing of Bathroom Wall Tiles

- Tenth floor to Second floor 100% completed.
- First floor 10% completed.

♦ Laying Of Floor Tiles

- Ceramic Tiles in Bathroom 87% completed.
- Vitrified Tiles in Halls & Bedrooms 92% completed.

♦ Fixing of UPVC Windows

- Upto Eighth floor 90% completed.
- Ninth floor 45% completed.

♦ Fixing of UPVC French Door

- Upto Third floor 100% completed.
- Fourth floor 10% completed.

♦ Terrace Water Proofing

Weathering course works 50% completed.

Erection of LIFTS

- Materials for 4 Nos of Lifts arrived
- Lift 1- Installation 80% completed.
- Lift 2- Installation 50% completed.
- Lift 3- Installation 10% completed.

• External Finishing Works

◆ External Plastering - Overall 95% Completed.

♦ Primer

1st Coat 95% completed. 2nd Coat 50% completed.



BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30 th JUNE-2023		
	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed 	 Structure Work. Completed Upto Terrace floor level slab – R.C.C 100% completed 		
	■ Terrace floor Parapet Columns Concrete 100% completed.	■ Terrace floor Parapet Columns Concrete 100% completed.		
	Lift Head room (4 out of 4)- Slab Concrete 100% completed.	Lift Head room (4 out of 4)- Slab Concrete 100% completed.		
	Over Head Water Tank (a) Base Slab Concrete (3 out of 3) - 100% completed.	Over Head Water Tank (a) Base Slab Concrete (3 out of 3) - 100% completed.		
	(b) Tank Wall Concrete (3 out of 3) – 100% completed.	(b) Tank Wall Concrete (3 out of 3) – 100% completed.		
	(c) Cover slab Concrete (3 out of 3) – 100% completed.	(c) Cover slab Concrete (3 out of 3 – 100% completed.		
D3 BLOCK	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. 	 Internal Finishing Work. Block Work Upto Tenth floor 95% completed. 		
	 Ceiling Plastering Stilt floor 85% completed. First floor to Tenth floor 95% completed. 	 Ceiling Plastering Stilt floor 85% completed. First floor to Tenth floor 95% completed. 		
	◆ Wall Plastering ■ First floor to Tenth floor 95% completed.	◆ Wall Plastering ■ First floor to Tenth floor 95% completed.		
	◆ Wall Putty work – 1 st Coat • Upto Tenth floor 90% completed.	◆ Wall Putty work – 1 st Coat ■ Upto Tenth floor 90% completed.		
	◆ Fixing of Balcony Rails ■ Balcony railing work 90% completed.	 Fixing of Balcony Rails ■Balcony railing work 90% completed. 		
	 ◆ Internal Plumbing Lines • Water supply pipe Lines (CPVC) - 95% completed. • Sanitary Lines (PVC) - 75% completed. 	 ◆ Internal Plumbing Lines ■ Water supply pipe Lines (CPVC) - 95% completed. ■ Sanitary Lines (PVC) - 90% completed. 		
	♦ Vertical Plumbing Lines ■ Water supply pipe Lines (G.I) - 35% completed. ■ Sanitary Lines (PVC) - 35% • Vertical Plumbing Lines ■ Water supply pipe Lines of 75% completed. • Sanitary Lines (PVC) - 35%			



	completed.	completed.	
	External Finishing Works	External Finishing Works	
	♦ External Plastering	◆ External Plastering - Overall 95%	
	■In East Side Elevation 95%	Completed.	
	completed.	♦ Primer	
	■ In North Side Elevation 95%	1 st Coat 95% completed.	
	completed.	1	
	In South Side Elevation 95%		
	completed. In West Side Elevation 95%		
	completed.		
BLOCK	STATUS UPTO PREVIOUS MONTH	STATUS AS ON 30th JUNE-2023	
BLOCK	STATUS OF TO FREVIOUS MONTH	STATUS AS ON 30 JUNE-2023	
	Structure Work.	Structure Work.	
	♦ Completed	♦ Completed	
	■Upto Terrace floor level slab –	■Upto Terrace floor level slab –	
	R.C.C 100% completed.	R.C.C 100% completed.	
	■ Terrace floor Parapet Columns Concrete 100% completed.	■ Terrace floor Parapet Columns Concrete 100% completed.	
	■ Lift Head room (2 out of 2) – slab	■ Lift Head room (2 out of 2) – slab	
	Concrete 100% completed.	Concrete 100% completed.	
	Over Head Water Tank(a) Base slab concrete completed.	Over Head Water Tank(a) Base slab concrete completed.	
	(b) Tank Wall concrete completed.	(b) Tank Wall concrete completed.	
	(c) Top Cover slab concrete	(c) Top Cover slab concrete	
	completed	completed	
	Internal Finishing Work.	• Internal Finishing Work.	
COMMUNITY	♦ Block Work	♦ Block Work	
HALL	■ Upto Fourth 100% completed.	■ Upto Fourth 100% completed.	
	♦ Ceiling Plastering	♦ Ceiling Plastering	
	■ Stilt floor 90% completed.	■ Stilt floor 90% completed.	
	■ Upto Fourth floor 100% completed	■ Upto Fourth floor 100% completed	
	♦ Wall Plastering	♦ Wall Plastering	
	■ Upto Fourth floor 100% completed	■ Upto Fourth floor 100% completed	
	◆ Ceiling Putty work ■ Upto Fourth floor 100% completed	◆ Ceiling Putty work ■ Upto Fourth floor 100% completed	
	♦ Wall Putty work	♦ Wall Putty work	
	■ Upto Fourth floor 100% completed	■ Upto Fourth floor 100% completed	
	♦ Wall Painting work	♦ Wall Painting work	
	• Upto Fourth floor - 1st Coat	• Upto Fourth floor - 1st Coat	
	painting 95% completed.	painting 95% completed.	



♦ Staircase Hand Railing work

■ Upto Fourth floor 90% completed.

♦ Flooring Work

- Stilt floor Granolithic flooring 95% completed.
- Vitrified Floor Tiles in Hall & rooms - Upto Fourth floor 100% completed.
- Ceramic Floor Tiles in Bathrooms
 Upto Fourth floor 100% completed.
- Laying of Kotta Stone in Staircase 70% completed.

♦ Wall Tiles & Cladding Work

Ceramic Wall Tiles in Bathrooms –
 Upto Fourth floor 100% completed.

♦ Fixing of UPVC Windows

- Upto. Fourth floor UPVC Window fixing 100% completed.
- All floors Staircase fixed windows 100 completed.

♦ Fixing of Wooden Flush Door Shutters.

- Upto Third floor 100% completed.
- Fourth floor 90% completed.

♦ Erection of LIFTS

- Materials for 2 Nos of Lifts arrived
- Lift 1- Installation 90% completed.
- Lift 2- Installation 75% completed.

• External Finishing Work.

♦ External Plastering

- West Side elevation 100% completed.
- South Side elevation 100% completed
- North Side elevation 100% completed.
- East Side elevation 100% completed.

♦ External Painting

1st Coat 100% completed.

♦ Staircase Hand Railing work

■ Upto Fourth floor 90% completed.

♦ Flooring Work

- Stilt floor Granolithic flooring 95% completed.
- Vitrified Floor Tiles in Hall & rooms - Upto Fourth floor 100% completed.
- Ceramic Floor Tiles in Bathrooms
 Upto Fourth floor 100% completed.
- Laying of Kotta Stone in Staircase 80% completed.

♦ Wall Tiles & Cladding Work

Ceramic Wall Tiles in Bathrooms –
 Upto Fourth floor 100% completed.

♦ Fixing of UPVC Windows

- Upto. Fourth floor UPVC Window fixing 100% completed.
- All floors Staircase fixed windows 100 completed.

♦ Fixing of Wooden Flush Door Shutters.

- Upto Third floor 100% completed.
- Fourth floor 95% completed.

♦ Erection of LIFTS

- Materials for 2 Nos of Lifts arrived
- Lift 1- Installation 90% completed.
- Lift 2- Installation 75% completed.

♦ Internal Electrification

• Electrical cable pulling work 10% completed.

♦ Fire Fighting Works

- Fixing of Pipeline in Ceiling 1st Floor 50% completed
- External Finishing Work.
 - ◆ External Plastering Overall 95% Completed.

♦ Primer

2 Coats 100% completed.


♦ External Painting

■ 1st Coat 100% completed.



PHOTOGRAPHS OF WORK PROGRESS AS ON 30th JUNE 2023

Community Hall: Lift Erection works on progress. Staircase Kotta stone laying 80% completed. Fire fighting works on progress



<u>Block A1:</u> Terrace Floor level slab Concrete casting 100% completed. Parapet columns 55% completed .External plastering works on progress.



<u>Block A2</u>: Terrace Floor level slab -1^{st} Half Concrete casting 100% completed. Parapet columns 40% completed. External Plastering on progress





Block B1: Lift Installation works on progress. Fixing of UPVC Windows on progress. External Painting works on progress.




Block B2: Fifth Floor Level slab concrete casting 100% completed. Shuttering works for 1st half of Sixth floor level slab on progress. Fifth floor Columns concrete 50% completed





\


Block C1: External Plastering overall 95% completed. 2nd Coat of Primer 95% completed. Lift Installation works on Progress. Terrace weathering course work 70% completed.



Block C2: External plastering overall 95% completed. 1st Coat Primer 95% completed. Lift Erection works on Progress.



Block C3: External Plastering 90% completed. 1st Coat Primer 95% completed.




View of C1, C2 & C3 Block




Block D1: External plastering overall 95% completed. 1st Coat Primer 95% completed.



Block D2: Over Head Water Tank 100% completed. Lift installation works on progress. Terrace weathering course on progress. External Painting works on progress



Block D3: External Plastering work overall 95% completed. 1st Coat of Primer 95% completed. Tiling works on progress.



QUALITY CONTROL

DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS CONDUCTED AT SITE:

Sl.No.	Materials	Source from	Test Done	Result
1	M-Sand	Arcot (T.K), Ranipet (Dist) Walajabad(T.K), Kanchipuran (Dt)	Each Truck	Sieve Analysis & Silt content
2.	P- Sand	Uthiramerur, Kanchipuram (DT) Walajabad(T.K), Kanchipuran (Dt)	Each Truck	Sieve Analysis & Silt content
2	Coarse Aggregate (20mm)	Sriperambathur, Kanchipuran (Dt), Vellore Dt & Chitoor Dt.	Each Truck	Sieve Analysis
3	Coarse Aggregate (12mm)	Sriperambathur, Kanchipuran (Dt) Vellore Dt & Chitoor Dt.	Each Truck	Sieve Analysis
4	Cement	Third party testing is being done.		
5	Steel	Third party testing is being done.		
6	Pile Integrity	Third party testing is being done.		
7	Soil Compaction	Third party testing is being done.		
8	RCC cubes are being tested and Register is being maintained.			
9	Slump test conducted at site to insure workability of concrete.			



PHOTOGRAPH OF QUALITY CONTROL AT SITE

Concrete Cube Compressive Strength Testing



20mm & 12mm Aggregate Sieve Analysis Testing



Fine Aggregate Sieve Analysis Testing

