30th - SEPTEMBER-2017

PACKAGE-II	STATUS AS ON 30/09/2017
Up to Last Month	DILLED IN OLI UUI VIII VII
Current Month Activity	 100% 4th & 5th floor Roof slab casting done. 100% columns casted at 6th floor level. Two flats Shuttering and Reinforcement binding of 6th floor Roof in progress. 80% Brick work in Stilt floor completed. 100% Brick work in 1st floor completed. 90% Brick work in 2nd floor level completed. 75% Brick work in 3rd floor level completed. 10% Brick work in 4th floor level completed. 10% Brick work in 4th floor level completed. 100% 6th & 7th floor Roof slab casting done. 100% columns casted at 8th floor level. Two flats Shuttering and Reinforcement binding of 8th
	 floor Roof in progress. 20% Brick work in Stilt floor completed. Balance 10% Brick work in 2nd floor completed. Balance 15% Brick work in 3rd floor and 90% in 4th & 5th floor level completed. Brick work in 6th floor level in progress. Plaster work in Two flats at 1st floor lvl completed. 50% Plaster work done in Stilt floor lvl. Door frames 100% fixed in 1st flr lvl. 100% cpvc piping work in 1st & 2nd floor lvl completed.
Up to Last Month Block D04	 Balance 50 % Stilt Roof Slab casted.(100% stilt roof casted) Balance 48 columns casted up to soffit of 1st floor Roof beams.(100% columns casted) 100% 1st floor Roof slab casted. 100% 2nd floor columns casted 75% 2nd floor Roof slab casted.
Current Month Activity	 Balance 25% 2nd floor Roof slab casted. 100% 3rd & 4th floor Roof slabs casted. Total 24 columns casted up to soffit of 5th floor Roof beams.
Up to Last Month Block D05	 Balance 75% basement Roof slab casted. (100% basement casted). 100% columns casted up to Soffit of Stilt Roof beam bottom. 50% Stilt Roof slab casted. Shuttering and Reinforcement binding for two flats is in progress.





Current Month Activity Up to Last Month	 Balance 50% Stilt Roof slab casted. (100% Stilt slab casted). 100% 1st floor Roof slab casted. 100% columns up to soffit of 2nd floor Roof beams casted. Shuttering and Reinforcement binding for two flats is in progress. 25% Basement Roof slab casted. 			
Block D06 Current Month Activity	 Balance 75% Basement Roof slab casted.(Total 100% casted). Total 50 columns up to soffit of Stilt Roof beams casted. One flat Stilt Roof slab shuttering in progress. 			
Up to Last Month Block D07	Balance 21 Columns casted in 2nd lift. (100% columns casted up to basement roof soffit).			
Current Month Activity	Basement Roof slab one flat down portion casted.			
Up to Last Month Block D08	 Balance 19 columns casted in 1st lift and 30 columns casted in 2nd lift in Basement floor. (100% columns casted up to basement roof soffit) 			
Current Month Activity				
Up to Last Month Non Tower	 Total 593 nos. of piles casted out of 593 nos. 30% P.C.C. for foundation work completed. 14% of Stitch slab casted. 39 Pile caps casted. Total 30 Columns casted up to soffit of Basement Roof beam bottom. Total 270 Sqm Basement Roof slab casting done. 			
Current Month Activity	 7.5% of stitch slab casted.(Total 21.5% casted.) 400 Sqm Basement Roof slab shuttering competed and Reinforcement binding in progress. 			
Up to Last Month Retaining Wall	 Total 72 nos. of piles casted out of 72 nos. Retaining wall footing of length 40 mtrs. Retaining wall of length 56 mtrs casted in 1st lift. Retaining wall of length 40 mtrs casted in 2nd lift. 			
Current Month Activity	• Kota stone cladding (water proofing) on outer side wall is in Progress.			





2

Sample Flat	 Internal Electrical conduiting & G.I. boxes completed.
	 Internal water supply piping work completed.

- Internal soil & waste piping work Completed.
- Internal Wooden door frames fixed.
- R.C.C. for balcony walls casted.
- 100% Plaster work completed.
- POP cornice work completed.
- Wall Tiling in all Toilets completed.
- Flooring in All bedrooms & Toilets completed.
- SS Railing fixing work in Balcony completed.

PHOTOGRAPHS OF PACKAGE-II on 30TH SEPT-2017

IN BLOCK D-04 5th FLOOR ROOF SLAB SHUTTERING IN PROGRESS.







IN BLOCK D-03 8th FLOOR ROOF SLAB SHUTTERING IN PROGRESS.







IN BLOCK D-05 2ND FLOOR ROOF SLAB REINFORCEMENT BINDING IN PROGRESS.







IN BLOCK D-06 STILT ROOF SLAB SHUTTERING IN PROGRESS

AND IN BLOCK D-07 BASEMENT ROOF SLAB SHUTTERING IN PROGRESS.







Up to Last Month Block C06	• 53 nos. of piles completed out of 195 no's.			
Current Month Activity	• 147 nos. of piles completed out of 195 no's.			
Up to Last Month Block C07	• 72 nos. of piles completed out of 195 no's.			
Current Month Activity	• 144 nos. of piles completed out of 195 no's.			
Up to Last Month Block C08	 Layout of piles completed. 115 nos. of piles completed out of 195 no's. 			
Current Month Activity	 Layout of piles completed. 191 nos. of piles completed out of 195 no's. 			
Up to Last Month Block C01	Initial testing of pile completed successfully.			
Current Month Activity	06 nos. of piles completed out of 195 no's.			
Up to Last Month Block C02	Excavation work 100% done.			
Current Month Activity	• Layout of piles completed.			

Progress Report No. 17 (1st Sept- 17 – 30th Sept- 17)





PHOTOGRAPHS OF PACKAGE-III on 30TH SEPT-2017

KENTLEDGE PLATFORM FOR ROUTINE TEST IN BLOCKS C06, C07, C08 COMPLETED.







PILING WORK IN PROGRESS IN BLOCKS C06, C07, C08







PACKAGE-IV	STATUS AS ON 30/09/2017				
Block A01	• 100% Basement floor slab casting completed.				
UpTo Last Month					
Current Month	• 100% First floor slab casting work completed.				
Activity	• 100% First to second floor columns casting completed.				
	 Second floor slab 50% shuttering work in progress. 				
Block B04	• Fourth floor slab casting 50% (4 flats) completed.				
UpTo Last Month	 Second floor brick work 50% (4 flats) completed. 				
Current Month	• Remaining Fourth floor slab casting 50% (4 flats) completed.				
Activity	• Remaining Second floor brick work 50% (4 flats) completed.				
	Stilt floor plaster work in progress.				
Block B05	• Fifth floor slab casting 50% (4 flats) completed.				
UpTo Last Month	• Third floor brick work 50% (4 flats) completed.				
Current Month	• Remaining Fifth floor slab casting 50% (4 flats) completed.				
Activity	• Sixth floor slab casting 100% (8 flats) completed.				
	• Remaining Third floor brick work 50% (4 flats) completed.				
	• Fourth floor brick work 25% (2 flats) completed.				
DI 1 C12	First floor internal electrical work in progress.				
Block C13	• Fifth floor slab casting 100% (4 flats) completed.				
UpTo Last Month	• Third floor brick work 100% (4 flats) completed.				
Current Month Activity	• Sixth floor slab casting 100% (4 flats) completed.				
Activity	Sixth to seventh floor columns binding & casting work in				
	progress.Fourth floor brick work in progress.				
Block C14	 Sixth floor slab casting 100% (4 flats) completed. 				
UpTo Last Month	 Third floor brick work 100% (4 flats) completed. 				
Current Month	• Seventh floor slab casting 100% (4 flats) completed.				
Activity	 Fourth floor brick work 100% (4 flats) completed. 				
	• Fifth floor brick work in progress.				
Block C03	• Pile caps casted 22 no's out of 44 no's.				
UpTo Last Month	The cups custom 22 has a custom in the st				
Current Month	• Pile caps casted 25 no's out of 44 no's.				
Activity	 70%Stitch slab casting work completed. 				
Block C04	Total 140 nos. of piles casted out of 194.				
UpTo Last Month					
Current Month	 Piling work in progress (185 completed out of 194) 				
Activity					
Block C05	• Total 195 nos. of piles casted out of 195.				
UpTo Last Month	500/ D.C.C. 1 1/1				
Current Month	• 50% P.C.C work completed.				
Activity	• 20% stitch slab work completed.				
Non Tower	• Total 630 nos. of piles casted out of 825.				
UpTo Last Month	• 1500 Sqm slab casting of extended basement completed.				
Current Month	• 72 piles casting completed (702/825).				
Activity	• 750 Sqm stitch slab casting completed.				
	• 625 Sqm slab casting completed.				





Sample Flat Type	Paint work of walls & Ceiling completed.
B Status	 Tile fixing work completed.
	Electrical work completed.
	 Water supply work completed.
	 Drainage and Sewage work completed.
Sample flat Type	 Paint work of walls & Ceiling completed.
C Status	 Tile fixing work completed.
	 Electrical work completed.
	 Water supply work completed.
	 Drainage and Sewage work completed.

PHOTOGRAPHS OF PACKAGE-IV on 30TH SEPT-2017

BLOCK A01: SECOND FLOOR 50% SLAB STEEL BINDING IN PROGRESS.
BLOCK C13: SIXTH TO SEVENTH FLOOR COLUMNS CASTING & SEVENTH
FLOOR SALB SHUTTERING WORK IN PROGRESS.







BLOCK B04: FIFTH FLOOR 50% SLAB WORK IN PROGRESS.







BLOCK B05: SIXTH FLOOR SLAB CASTING COMPLETED. BLOCK A01: SECOND FLOOR SLAB SHUTTERING WORK IN PROGRESS.







TOP VEIW OF BLOCK A01,B04,B05,C14 & NON TOWER AREA. BLOCK: C14 EIGHT FLOOR SLAB CASTING COMPLETED.







PACKAGE-V	STATUS AS ON 30/09/2017			
Up to Last Month	• 75% columns casted at 7 th floor lvl.			
	• 25% casting of 7 th Floor Roof slab done.			
Block B01	• 5% Brickwork done in Stilt Floor.			
	• 15% Brickwork done in 1 st floor.			
	• 95% Brick work done in 2 nd floor lvl.			
	• 25% Brickwork done in 3 rd floor lvl.			
	• 30% ceiling plaster done in Stilt floor.			
	• 50% Ceiling plaster done in 1 st floor.			
	 Except Aluminum doors & windows sample flat work completed. 			
Current Month	 Balance 25% of columns casted up to soffit of 7th floor Roof 			
Activity	beams.			
	 Balance 75% of 7th floor Roof slab casted. 			
	 100% 8th floor Roof slabs casted. 			
	 9th floor Roof slab Reinforcement binding for Two flats in 			
	progress.			
	• 65% Brick work done in 3 rd floor lvl.			
	• 40% Brick work done in 4 th flr lvl.			
	• 15% Brick work done in 5 th flr lvl.			
	• 60% Plaster done in 1 st flr lvl.			
	• 85% Plaster done in 2 nd flr lvl.			
	• 25% Plaster done in 3 rd flr lyl.			
	• 95% Door frames fixed in 1 st ,2 nd & 3 rd flr lvl.			
	• 100% cpvc Piping work In 1 st & 2 nd floor completed.			
	• 80% cpvc piping in 3 rd floor lvl completed.			
Up to Last Month	Balance 75% casting of 3 rd floor Roof slab completed.			
Block B02	• 100% casting of 4 th floor Roof slab done.			
Diock Doz	 100% casting of 4 Hoof Roof stab dolle. 100% casting of columns done at 5th floor lvl. 			
	 75% casting of 5th floor Roof slab completed. 			
	 75% casting of 5 Thoof Roof stab completed. 70% Brick work completed in 1st floor lvl. 			
	• 25% Brickwork done in 2 nd floor lvl.			
	 90% ceiling plaster done in stilt floor lvl. 			
Current Month	Balance 25% casting of 5 th floor Roof slab completed.			
Activity	• 100% 6 th floor Roof slab casted.			
	• 100% columns casted up to soffit of 7 th flr Roof beams.			
	• 25% casting of 7 th flr Roof slab completed.			
	 20% Brick work completed in 1st floor lvl. 			
	• 65% Brickwork done in 2 nd floor lvl.			
	• 95% Door frames fixed in 1 st & 2 nd flr lvl.			
	• 100% cpvc piping completed in 1 st floor lvl.			
	• 100 /0 cp /c piping completed in 1 moor ivi.			
Up to Last Month	• 100% casting of Basement Roof slab done.			
-	• 100% columns casted at Stilt floor lvl.			
Block B03				





C Mandle			
Current Month Activity	100% columns casted at Stilt flr lvl.		
Up to Last Month Block C15	Balance 75% casting of 2 nd floor Roof completed. 1000%		
Block C15	• 100% casting of 3 rd floor columns completed.		
	• 25 % casting of 3r ^d floor Roof slab casting completed.		
	• 15% Brickwork completed in stilt floor.		
	• 50% Brickwork completed in 1 st floor.		
	• 70% Brick work completed in 2 nd floor level.		
Current Month			
Activity	• Balance 75% casting of 3 rd floor Roof slab done.		
	• 50% casting of 4 th floor Roof slab done.		
	• 15% columns casted at 5 th flr lvl.		
	• 45 % Brick work done in 1 st flr lvl.		
	• 25% Brick work done in 2 nd flr lvl.		
	• 95% Door frames fixed in 1 st & 2 nd flr lvl.		
	• 25% Plaster done in 1 st flr lvl.		
	• 90% Plaster done in stilt flr lvl.		
	• 95% cpvc piping in 1 st floor lvl completed.		
Up to Last Month	Balance 75% casting of columns at 1 st floor lvl completed.		
Block C16	• 100% casting of 1 st floor Roof slab completed.		
	• 80% Columns casted at 2 nd floor level.		
Current Month	Balance 20% columns casted up to soffit of 2 nd floor Roof		
Activity	beams.		
	• 100% 2 nd flr Roof slab casted.		
	 100% columns casted up to soffit of 3rd floor Roof beams. 		
	• 75% casting of 3 rd floor Roof slab done.		
	• 80% Brick work done in 1 st flr lvl.		
	• 80% Plaster done in Stilt flr lvl.		
Up to Last Month	Piling work is completed.		
Non Tower	 98% stitch slab casting completed. 		
	• 75 % columns casting completed.		
Current Month Activity	• 750 Sqm Basement Roof slab casted.		
Up to Last Month	Piling work is completed.		
Retaining Wall	 Casting of retaining wall upto a length of 155 mtr completed. 		
Current Month	• Water proofing(Kota stone) on outer side of Retaining wall in		
Activity	progress.		
Sample Flat	 Internal water supply and drainage work completed. 		
Type-C	Water proofing work completed.		
	• 100% Plaster work completed.		
	Wall & Floor Tiling work completed.		
	Wall putty work completed.		
	Chinaware fixing in progress.		





PHOTOGRAPHS OF PACKAGE-V on 30st SEPT-2017

IN BLOCK B-02 6^{TH} FLOOR ROOF SLAB SHUTTERING IN PROGRESS.







IN BLOCK B-02 6TH FLOOR ROOF SLAB SHUTTERING IN PROGRESS.

IN BLOCK C-16 3RD FLOOR ROOF SLAB SHUTTERING IN PROGRESS.

IN BLOCKB-01 9TH FLOOR ROOF SLAB REINFORCEMENT BINDING WORK IN PROGRESS.







IN BLOCK C-15 5TH FLOOR ROOF SLAB SHUTTERING WORK IN PROGRESS.







IN NON TOWER NEAR BLOCK B-02 BASEMENT ROOF SLAB SHUTTERING IN PROGRESS.







OVERALL VIEW OF PACKAGE







QUALITY CONTROL

<u>DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS</u> <u>CONDUCTED AT SITE:</u>

S. No	Materials	Source From	Test Date	Tests done	Result
1	Coarse Sand	Bajpur		Each truck	Sieve/ Silt
2	Coarse Aggregate	Nagal		Each truck	Sieve Analysis
3	Fine Sand				
4	Cement	Third party testing is being done			
5	Steel	Third party testing is being done			
6	RCC Cubes are being tested and Register is being maintained.				
7	Slump test conducted at site to insure workability if concrete.				

PHOTOGRAPH OF QUALITY CONTROL AT SITE

Slump Testing







Brick Compressive Strength Testing







20mm & 10mm Aggregate Testing







Cube Testing Of Concrete







Fine Aggregate Testing









