30th -NOV-2021


PACKAGE-II	STATUS AS ON 30/11/2021
BLOCK D-01	 All works completed except following which will be done during handing over of flats: - Fixing of Fly mesh shutters. Internal door locks. Internal & External final painting. CP fittings







PACKAGE-II	STATUS AS ON 30/11/2021
BLOCK D-02	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	Internal & External final painting.
	• CP fittings.







PACKAGE-II	STATUS AS ON 30/11/2021
BLOCK D-03	All works completed except following which will be done during handing over
	of flats: -
	Fixing of Fly mesh shutters.Internal door locks.
	Internal & External final painting.
	• CP fittings.







PACKAGE-II	STATUS AS ON 30/11/2021
BLOCK D-04	All works completed except following which will be done during handing over
	of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.







PACKAGE-II	STATUS AS ON 30/11/2021
BLOCK D-05	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.







PACKAGE-II	STATUS AS ON 30/11/2021
BLOCK D-06	BALANCE WORKS
	Internal Tiles flooring
	Aluminum door & windows
	Internal & External final painting
	• Lifts
	• CP fittings
	Door shutters
	• Wiring, switch & sockets
	• Solar water heating system etc.
	Surrounding Development







PACKAGE-II	STATUS AS ON 30/11/2021
EXTERNAL DEVELOPMENT	BALANCE WORKS
	Road works -10%.Horticulture works-20%.
	• Hornculture works-20%.








PACKAGE-III	STATUS AS ON 30/11/2021
Block C01	
Balance work	 A. All works completed except following which will be done during handing over of flats: - Internal door locks. CP fitting. Internal & External final coat paint. Aluminium fly mesh door.
	 B. Following works are in progress. Terrace Booster pump. Solar water heating system. Lift testing in progress.












	<u>CGEWHO – GREATER NOIDA PROJECT</u>
Balance work	 A. All works completed except following which will be done during handing over of flats: - Internal door locks. CP fitting. Internal & External final coat paint. Aluminium fly mesh door. B. Following works are in progress. Terrace Booster pump. Solar water heating system. Lift testing in progress.
Block C07	
Balance work	 A. All works completed except following which will be done during handing over of flats: - Internal door locks. CP fitting. Internal & External final coat paint. Aluminium fly mesh door. B. Following works are in progress. Terrace Booster pump. Solar water heating system. Lift testing in progress.











Block C09	
	A. All works completed except following which will be done during
	handing over of flats: -
Balance work	Internal door locks.
	CP & chinaware fitting.
	 Internal & External final coat paint.
	Aluminium fly mesh door.
	B. Following works are in progress.
	 Is a ronowing works are in progress. 12 flat Internal floor tiles.
	 16 flat internal wall tiles.
	 Terrace Booster pump.
	 Lift installation in progress.
	Aluminum door & window fixing.
	Electrical wiring, switch, socket.
	Entrance door locks.
	• Meter board.
	Solar water heating system.
	• False ceiling.
	Rising main & Metre board.












Block C11	
Balance work	 A. All works completed except following which will be done during handing over of flats: - Internal door locks. CP fitting. Internal & External final coat paint. Aluminium fly mesh door. B. Following works are in progress. Terrace Booster pump. Solar water heating system. Lift testing in progress.


















PACKAGE-IV	STATUS AS ON 30/11/2021
BLOCK B-04	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.







PACKAGE-IV	STATUS AS ON 30/11/2021
BLOCK B-05	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.







PACKAGE-IV	STATUS AS ON 30/11/2021
BLOCK A-01	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.







PACKAGE-IV	STATUS AS ON 30/11/2021
BLOCK C-02	All works completed except following which will be done during handing over of flats: -
	Fixing of Fly mesh shutters.Internal door locks.
	 Internal & External final painting.
	• CP fittings







PACKAGE-IV	STATUS AS ON 30/11/2021
BLOCK C-03	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.







PACKAGE-IV	STATUS AS ON 30/11/2021
BLOCK C-04	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.







PACKAGE-IV	STATUS AS ON 30/11/2021
BLOCK C-16	All works completed except following
	which will be done during handing over
	of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.







PACKAGE-IV	STATUS AS ON 30/11/2021
BLOCK C-17	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.








PACKAGE-IV	STATUS AS ON 30/11/2021
EXTERNALDEVELOPMENT	BALANCE WORKS
	• Horticulture work-10%.








PACKAGE-V	STATUS AS ON 30/11/2021
BLOCK B-01	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.







PACKAGE-V	STATUS AS ON 30/11/2021
BLOCK B-02	 All works completed except following which will be done during handing over of flats: - Fixing of Fly mesh shutters. Internal door locks.
	 Internal & External final painting.
	• CP fittings.







PACKAGE-V	STATUS AS ON 30/11/2021
BLOCK B-03	All works completed except following which will be done during handing over of flats: - • Fixing of Fly mesh shutters.
	Internal door locks.
	Internal & External final painting.CP fittings.







PACKAGE-V	STATUS AS ON 30/11/2021
BLOCK C-14	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings







PACKAGE-V	STATUS AS ON 30/11/2021
BLOCK C-15	All works completed except following which will be done during handing over of flats: -
	• Fixing of Fly mesh shutters.
	Internal door locks.
	• Internal & External final painting.
	• CP fittings.







PACKAGE-V	STATUS AS ON 30/11/2021
EXTERNAL DEVELOPMENT	BALANCE WORKS
	• Horticulture works- 10%.



(





PACKAGE-VI	STATUS AS ON 30/11/2021
SHOPPING COMPLEX	BALANCE WORKS
	Aluminum Door & Windows
	Internal & External final painting
	• CP fittings
	• switch & socket, meter panel
	Chinaware
	Shaft louvers
	Toilets false ceiling







PACKAGE-VI	STATUS AS ON 30/11/2021
NURSING HOME	BALANCE WORKS
	Aluminum Door & Windows
	Internal & External final painting
	• CP fittings
	• Electrical wiring, switch & socket, meter
	panel
	Chinaware
	Shaft louvers
	Toilets false ceiling







PACKAGE-VI	STATUS AS ON 30/11/2021
SCHOOL	BALANCE WORKS
	• External plaster 50%.
	Internal flooring.
	Aluminum Door & Windows.
	Shaft louvers.
	Toilets false ceiling.
	Internal & External final painting
	• CP fittings.
	• Meter Panel, Wiring & Switch sockets.







PACKAGE-VI	STATUS AS ON 30/11/2021
COMMUNITY CENTER	BALANCE WORKS
	• External plaster 50%.
	• Internal flooring 75%.
	Aluminum Door & Windows.
	• Internal & External painting.
	• CP fittings.
	• HVAC ducting work-25%.
	• AC Machines fixing work-50%.
	• Internal wiring-50%.
	Panel & Switch sockets.







PACKAGE-VI	STATUS AS ON 30/11/2021
EXTERNAL DEVELOPMENT	BALANCE WORKS
	 Basement final painting External development works-40%. Horticulture works-60%.







QUALITY CONTROL

DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS CONDUCTED AT SITE:

S. No.	Materials	Source From	Test Date	Tests done	Result
1	Coarse Sand	Bajpur		Each truck	Sieve Analysis & Silt content
2	Coarse Aggregate	Nangal		Each truck	Sieve Analysis & Impact Value
3	Fine Sand	Yamuna Nagar		Each truck	Sieve Analysis & Silt content
4	Bricks	Greater Noida		Each truck	Dimension, Water Absorption & Compressive strength
5	Cement	Third party testing is being done			
6	Steel	Third party testing is being done			
7	Piles Integrity	Third party testing is being done			
8	Soil Compaction	Third party testing is being done			
9	STP water		Third party te	sting is being done	
10	Wood	Third party testing is being done			
11	Wires	Third party testing is being done			
12	Tiles	Third party testing is being done			
13	VDF	Third party testing is being done (Flexural Strength done.).			
14	RCC Cubes are bei	ng tested and Register	r is being maintained	•	
15	15 Slump test conducted at site to insure workability of concrete.				





CUBE COMPRESSIVE STRENGTH TESTING



BRICK COMPRESSIVE STRENGTH TESTING







COARSE SAND SIEVE ANALASYS TESTING.







20MM COARSE AGGREGATE TESTING







PACKAGE-E(a)	STATUS AS ON 30/11/2021
External works	BALANCE WORKS
	• Final testing with Main supply is balance.

SOLAR INSTALLATION WORK COMPLETED







PACKAGE-E(b)	STATUS AS ON 30/11/2021
External works	BALANCE WORKS
	• Final testing with main supply is balance.

CABLES TERMINATION WORK COMPLETED.





